



CALIPER CATALOGUE 2016



Independent Aftermarket Company

FOR EUROPEAN COMMERCIAL VEHICLES

CALIPER

Article Groups


SUITABLE FOR KNORR	01 - 22
SUITABLE FOR WABCO	25 - 31
SUITABLE FOR HALDEX	35 - 41
SUITABLE FOR ROR-MERITOR	45 - 76
SUITABLE FOR BERGISCHE ACHSEN	79 - 81
OTHER TYPE CALIPERS	85
SENSOR	89 - 95



Independent Aftermarket Company

FOR EUROPEAN COMMERCIAL VEHICLES

iamauger.com



BEST QUALITY PRODUCT RANGE

We would like to provide you the best quality spare parts for each brand across the world in the Independent Aftermarket. Therefore, we have shaped the operations within the company according to this basis prudentially. Several different kinds of modern control and audit systems have been testing all of our products. As well as the quality of material, we also pay special attention on mounting reliability. In this sense, you can get from Auger many parts of which you may not even find any alternatives in the aftermarket. We have been improving the quality of our products constantly by the help of Technical Inspections Organization (TUV).



mauger

GERMANY

**Suitable for
KNORR**



Auger No. **57175** Description
Adjusting Mechanism Shaft Kit
Type : SB5 - SN5
Replaces : -



Auger No. **56138** Description
Adjusting Mechanism Shaft Kit
Type : SB5 - SN5
Replaces : -



Auger No. **57163** Description
Adjusting Mechanism Shaft
Type : SB6 - SB7 - SN6 - SN7 - SK7 - SL7 - SM7
Replaces : -



Auger No. **57162** Description
Pinion Shaft
Type : SB6 - SB7 - SN6 - SN7 - SK7
Replaces : -



Auger No. **76974** Description
Pinion Shaft
Type : SB6 - SB7 - SN6 - SN7 - SK7 - SL7 - SM7
Replaces : -



Auger No. **76973** Description
Pinion Shaft
Type : SN6 - SN7 - SK7 - SL7 - SM7
Replaces : -



Auger No. **57176** Description
Pinion Shaft
Type : SN5
Replaces : -



Auger No. **57177** Description
Caliper Mechanism Gear
Type : SB5 - SN5 - SB6 - SB7 - SN6 - SN7 - SK7 - SL7 - SM7
Replaces : -



Auger No.

56007

Type : SB5
Replaces : -

Description

Caliper Mechanizm Chain
12 Links



Auger No.

57182

Type : SB6 - SB7 - SN6 - SN7 - SK7 - SL7 - SM7
Replaces : -

Description

Caliper Mechanizm Chain
29 Links



Auger No.

57179

Type : SB6 - SB7
Replaces : -

Description

Caliper Lever (0° - 114 mm)




Auger No.

77434

Type : SB6 - SB7
Replaces : -

Description

Caliper Lever (0° - 127 mm)



Auger No.

77433

Type : SB6 - SB7
Replaces : -

Description

Caliper Lever (12° - 123 mm)



Auger No.

57181

Type : SB6 - SB7
Replaces : -

Description

Caliper Lever (12° - 126 mm)



Auger No.

57178

Type : SN6 - SN7 - SK7
Replaces : -

Description

Caliper Lever (0° - 113 mm)



Auger No.

76975

Type : SN6 - SN7 - SK7
Replaces : -

Description

Caliper Lever (0° - 113 mm)
57178's With Roller



Auger No. **57180** Description
Caliper Lever (0° - 125 mm)
Type : SN6 - SN7
Replaces : -



Auger No. **79277** Description
Caliper Lever (0° - 125 mm)
57180's With Roller
Type : SN6 - SN7 - SK7
Replaces : -



Auger No. **77435** Description
Caliper Lever (12° - 123 mm)
Type : SN6 - SN7
Replaces : -



Auger No. **79276** Description
Caliper Lever (12° - 123 mm)
77435's With Roller
Type : SN7 - SK7
Replaces : -



Auger No. **79386** Description
Caliper Lever
Type : SL7 - SM7
Replaces : -



Auger No. **79387** Description
Caliper Lever
Type : SB7 RADIAL
Replaces : -



Auger No. **72856** Description
Roller Bearing
One Side Claw
Type : SB5 - SB6 - SB7
Replaces : -



Auger No. **72857** Description
Roller Bearing
Both Sides of the Claw
Type : SB6 - SB7 - SN6 - SN7 - SK7
Replaces : -



Auger No. **80733** Description
Roller Bearing
Type : SL7 - SM7
Replaces : -



Auger No.
57166

Type : SB6 - SB7 - SB7 RADIAL
Replaces : -

Description
Caliper Bridge



Auger No.
56155

Type : SB6 - SB7 - SB7 RADIAL
Replaces : -

Description
Caliper Bridge Assembly



Auger No.
56156

Type : SB6 - SB7 - SB7 RADIAL
Replaces : -

Description
Caliper Bridge Assembly



Auger No.
57601

Type : SB6 - SB7 - SB7 RADIAL
Replaces : -

Description
Caliper Bridge Assembly



Auger No.
57165

Type : SN6 - SN7 - SK7
Replaces : -

Description
Caliper Bridge



Auger No.
56153

Type : SN6 - SN7 - SK7
Replaces : -

Description
Caliper Bridge Assembly



Auger No.
56154

Type : SN6 - SN7 - SK7
Replaces : -

Description
Caliper Bridge Assembly



Auger No.
57580

Type : SN6 - SN7 - SK7
Replaces : -

Description
Caliper Bridge Assembly



Auger No.
57164

Description
Caliper Bridge

Type : SN6 - SN7 - SK7 - SL7 - SM7
Replaces : -



Auger No.
56151

Description
Caliper Bridge Assembly

Type : SN6 - SN7 - SK7 - SL7 - SM7
Replaces : -



Auger No.
56152

Description
Caliper Bridge Assembly

Type : SN6 - SN7 - SK7 - SL7 - SM7
Replaces : -



Auger No.
57579

Description
Caliper Bridge Assembly

Type : SN6 - SN7 - SK7 - SL7 - SM7
Replaces : -



Auger No.
79279

Description
Caliper Bridge Assembly

Type : SL7 - SM7
Replaces : -



Auger No.
57183

Description
Caliper Sensor Cover (3 Cable)
(Suitable for Mercedes)

Type : SB6 - SB7 - SN6 - SN7 - SK7 - SL7 - SM7
Replaces : -



Auger No.
79149

Description
Caliper Sensor Cover (2 Cable)

Type : SB6 - SB7 - SN6 - SN7 - SK7 - SL7 - SM7
Replaces : -



Auger No.
79175

Description
Caliper Sensor Cover (Without Sensor)

Type : SB6 - SB7 - SN6 - SN7 - SK7 - SL7 - SM7
Replaces : -



Auger No.
56130

Description
Caliper Cover Kit

Type : SN6 - SN7 - SK7
Replaces : -



Auger No.
76978

Description
Caliper Cover Kit

Type : SN6 - SN7 - SK7 - SL7 - SM7
Replaces : -



Auger No.
79039

Description
Tappet Kit


Type : SN6 - SN7 - SK7
Replaces : -



Auger No.
76385

Description
Tappet Kit

Type : SN6 - SN7 - SK7
Replaces : -




Auger No.
53881

Description
Tappet Kit, Old Type Dust Cover

Type : SN6 - SN7 - SK7
Replaces : K001300

Suitable for	Replaces	Suitable for
Man	81.50822.6020	TGA / TGS / TGM / TGX
Iveco	42541413	EuroTrakker / EuroCargo EuroTech / EuroStar / Stralis




Auger No.
54167

Description
Tappet Kit, New Type Dust Cover

Type : SN6 - SN7 - SK7
Replaces : K010603 - K000366

Suitable for	Replaces	Suitable for
Mercedes	000 420 49 82 000 420 40 82 000 420 23 82	Actros 2/3
Man	81.50822.6031	TGA / TGS / TGM / TGX
Daf	1689313 1622785	XF105/95 / CF65/75/85
Bergische Achsen	09.801.06.32.0	SH..LL Series (SB 4309 / SB 4345) SKH Series (SB 3745)



54523
ø69

72998
ø16/ø18/10

Auger No.
54523

Description
Tappet Kit

Type : SN5
Replaces : K001929

Suitable for	Replaces	Suitable for
Man	81.50822.6027	TGL



79280
ø69

72998
ø16/ø18/10

Auger No.
79280

Description
Tappet Kit, Old Type Dust Cover

Type : SN5
Replaces : -

Suitable for	Replaces	Suitable for
Man	-	TGL



77447
ø69

80569
ø15/ø17/7

Auger No.
77447

Description
Tappet Kit, New Type

Type : SL7 - SM7
Replaces : K046523K50

Suitable for	Replaces	Suitable for
Mercedes	000 423 03 16	Actros / Axor / Axor 2 Antos / Aros



56023
ø74

72998
ø16/ø18/10

Auger No.
56023

Description
Tappet Kit

Type : SB5 - SB6 - SB7
Replaces : I1370760065

Suitable for	Replaces	Suitable for
Mercedes	000 420 13 82	Atego / Atego2 / Accelo

Auger No. 53878

Description
Tappet Kit

Type : SB5 - SB6 - SB7

Replaces : II304130065 - II179320065

Suitable for	Replaces	Suitable for
Man	81.50822.6007	M2000

Auger No. 79379

Description
Tappet Kit, Old Type Dust Cover

Type : SB5 - SB6 - SB7

Replaces : -

Auger No. 54178

Description
Tappet Kit, Old Type Dust Cover

Type : SB6 - SB7

Replaces : K000944

Auger No. 54168

Description
Tappet Kit, New Type Dust Cover

Type : SB6 - SB7

Replaces : K010604

Suitable for	Replaces	Suitable for
Mercedes	000 420 48 82 000 420 39 82 000 420 06 82	Citaro
Man	81.50822.6022 81.50822.6032	TGA / M2000
Scania	1759811 1746824 1390429	4 Series Truck PGRT Series Truck
Sauer Achsen	3 434 3804 00	SBK 1937-11 S SBK 2243-11 S
Bergische Achsen	09.801.02.63.0	SH.LL Series (SB 4309 / SB 4345) SKH Series (SB 3745)

Auger No. 56055

Description
Tappet Kit, New Type Dust Cover

Type : SB6 - SB7

Replaces : K010606

Auger No. 57167

Description
Caliper Cap

Type : SB5 - SN5 - SB6 - SB7 - SN6 - SN7 - SK7 - SL7 - SM7

Replaces : -

Auger No. Description
54072 Caliper Pin Cap Set



Type : SB5 - SB6 - SB7 - SB7 RADIAL
Replaces : K001301
Suitable for Replaces Suitable for
Man 81.50822.6025 TGA / LION'S CITY / M2000

Auger No. Description
73597 Caliper Pin Cap Set




Type : SB5 - SB6 - SB7 - SB7 RADIAL
Replaces : I1350470063
Suitable for Replaces Suitable for
Bergische 09.801.02.58.0 SKH Series (SB 3745)
Achsen SKH..LL Series (SB 3745)
SH Series (SB 4345)
Sauer Achsen 3 434 3803 00 -

Auger No. Description
53879 Caliper Pin Cap Set



Type : SB5 - SB6 - SB7 - SB7 RADIAL - SN7
Replaces : I139769F0063
Suitable for Replaces Suitable for
Sauer Achsen 3 434 3806 00 SBK 1937-11 S
SBK 2243-11 S

Auger No. Description
56066 Caliper Pin Boot & Cap Set



Type : SB5 - SB6 - SB7
Replaces : -
Suitable for Replaces Suitable for
Bergische 09.801.06.11.0 SH..LL Series (SB 4309 / SB 4345)
Achsen SKH Series (SB 3745)

55331
ø30/ø51/36

Auger No. **79234**

Description
Caliper Pin Boot Set

Type : SB5 - SN5 - SB6 - SB7 - SN6 - SN7 - SK7 - SL7 - SM7

Replaces : -

Suitable for Bergische Achsen	Replaces	Suitable for SH..LL Series (SB 4309 / SB 4345) SKH Series (SB 3745)
---	-----------------	--

60485
ø40/15

55331
ø30/ø51/36

Auger No. **56065**

Description
Caliper Pin Boot & Cap Set

Type : SB5 - SN5 - SB6 - SB7 - SN6 - SN7 - SK7 - SL7 - SM7

Replaces : -

Suitable for Bergische Achsen	Replaces 09.801.06.34.0	Suitable for SH..LL Series (SB 4309 / SB 4345) SKH Series (SB 3745)
---	-----------------------------------	--

55344
ø35/ø40/48

ø34/80

Auger No. **79235**

Description
Caliper Short Bush Repair Kit

Type : SB5 - SB6 - SB7

Replaces : -

Suitable for Daf	Replaces -	Suitable for 95XF / CF65/75/85
Sauer Achsen	Replaces -	Suitable for SBK 1937-11 S SBK 2243-11 S

55344
ø35/ø40/48

ø34/80

Auger No. **53875**

Description
Caliper Short Bush Repair Kit

Type : SB5 - SB6 - SB7

Replaces : II368470064

Suitable for Daf	Replaces 1448910	Suitable for 95XF / CF65/75/85
Sauer Achsen	Replaces 3 434 3801 00	Suitable for SBK 1937-11 S SBK 2243-11 S



Auger No. **56022** Description
Caliper Long Bush Repair Kit

Type : SB7
Replaces : I1339830064




Auger No. **76380** Description
Caliper Pin Rubber Bush (Short) $\varnothing 39$

Type : SB6 - SB7 - SN6 - SN7 - SL7 - SM7
Replaces : -




Auger No. **76379** Description
Caliper Pin Rubber Bush (Short) $\varnothing 39$

Type : SB6 - SB7 - SN6 - SN7 - SL7 - SM7
Replaces : -



Auger No. **76378** Description
Caliper Pin Rubber Bush (Short) $\varnothing 39$

Type : SB6 - SB7 - SN6 - SN7 - SL7 - SM7
Replaces : -



Auger No. **76383** Description
Caliper Pin Rubber Bush (Long) $\varnothing 39$

Type : SB5 - SB6 - SB7 - SN6 - SN7 - SK7 - SL7 - SM7
Replaces : -

Suitable for	Replaces	Suitable for
Bergische Achsen	02.1410.21.00	SH...LL Series (SB 4309 / SB 4345) SKH Series (SB 3745)



Auger No. **76381** Description
Caliper Pin Rubber Bush (Long) $\varnothing 39$

Type : SB5 - SB6 - SB7 - SN6 - SN7 - SK7 - SL7 - SM7
Replaces : -



Auger No. **70833** Description
Caliper Pin Rubber Bush (Long) $\varnothing 39$

Type : SB5 - SB6 - SB7
Replaces : K000697

Auger No.
76384

Description
Caliper Pin Rubber Bush (Long) ø35

Type : SB5 - SB6 - SB7

Replaces : -

Suitable for : Bergische Achsen

Replaces : 02.1410.22.00

Suitable for : SH..LL Series (SB 4309 / SB 4345) SKH Series (SB 3745)

Auger No.
76382

Description
Caliper Pin Rubber Bush (Long) ø35

Type : SB5 - SB6 - SB7

Replaces : -

Auger No.
70835

Description
Caliper Pin Rubber Bush (Long) ø35

Type : SB5 - SB6 - SB7

Replaces : -

Auger No.
56057

Description
Caliper Pin Rubber Bush (Long) ø35

Type : SB5 - SB6 - SB7

Replaces : K000421

Suitable for : Scania 1472919

Suitable for : 4 Series Truck PGR Series Truck

Auger No.
56113

Description
Caliper Pin Rubber Bush (Long)

Type : SB5 - SN5 - SB6 - SB7 - SN6 - SN7

Replaces : -

Auger No.
54685

Description
Caliper Pin Repair Kit

Type : SB5 - SB6 - SB7

Replaces : K000935




Auger No. **53876** Description
Caliper Pin Repair Kit

Type : SB6 - SB7
Replaces : K000696 - K004218 - I1310370066

Suitable for	Replaces	Suitable for
Mercedes	002 420 03 83	Actros / Atego / Axor 2
Scania	1527631 1477675	4 Series Truck PGRT Series Truck
Sauer Achsen	3 434 3805 00	SBK 1937-11 S SBK 2243-11 S

Components: $\varnothing 36/114$, 55331 $\varnothing 30/\varnothing 51/36$, 60533 $\varnothing 36/\varnothing 40/82$, 60485 $\varnothing 40/15$



Auger No. **56054** Description
Caliper Pin Repair Kit

Type : SB7 - SB7 RADIAL
Replaces : K010813

Suitable for	Replaces	Suitable for
Man	81.50822.6033	LION'S CITY / Centroliner

Components: 55331 $\varnothing 30/\varnothing 51/36$, 60533 $\varnothing 36/\varnothing 40/82$, $\varnothing 36/64$, $\varnothing 36/114$, 73004 $\varnothing 36/\varnothing 40/20$



Auger No. **54526** Description
Caliper Pin Repair Kit

Type : SN7 - SK7
Replaces : K004100

Suitable for	Replaces	Suitable for
Sauer Achsen	3 434 3815 00	SK RB 9022 / B9-22K01 BA9-22K01 / B19-22K01 S19-22K01 / S111-22K01 Z19-22K01 / Z111-22K01 BL9-22K01 / BIL9-22K01 SIL9-22K01 / SIL11-22K01

Components: 55331 $\varnothing 30/\varnothing 51/36$, 60533 $\varnothing 36/\varnothing 40/82$, $\varnothing 36/64$, $\varnothing 36/114$, 73004 $\varnothing 36/\varnothing 40/20$, 73186 $\varnothing 35$, 60485 $\varnothing 40/15$



Auger No. **56021** Description
Caliper Pin Repair Kit

Type : SN7 - SK7
Replaces : K010766

Suitable for	Replaces	Suitable for
Mercedes	000 420 56 82 000 420 50 82	Actros 2/3 Steermaster Airmaster
Sauer Achsen	-	SK RB 9022 / B9-22K01 BA9-22K01 / B19-22K01 S19-22K01 / S111-22K01 Z19-22K01 / Z111-22K01 BL9-22K01 / BIL9-22K01 SIL9-22K01 / SIL11-22K01

Components: 60485 $\varnothing 40/15$, 55331 $\varnothing 30/\varnothing 51/36$, $\varnothing 36/64$, 60533 $\varnothing 36/\varnothing 40/82$, $\varnothing 36/114$, 73004 $\varnothing 36/\varnothing 40/20$

Auger No.
54524

Description
 Caliper Pin Repair Kit

Type : SN5
Replaces : K001928

Suitable for Man
Replaces 81.50822.6026
Suitable for TGL

Auger No.
53882

Description
 Caliper Pin Repair Kit

Type : SB7
Replaces : II358510062

Suitable for Mercedes
Replaces 000 420 11 82
Suitable for -

Scania 1415149
 1415154
Suitable for 4 Series Truck
 FKN Series Bus

Auger No.
53885

Description
 Caliper Pin Repair Kit

Type : SB7
Replaces : II179320062

Auger No.
53884

Description
 Caliper Pin Repair Kit

Type : SB6 - SB7
Replaces : II197140062

Auger No.
54522

Description
 Caliper Pin Repair Kit

Type : SB6 - SB7
Replaces : II39769F0062

Suitable for Iveco
Replaces 42537451
Suitable for EuroCargo / EuroTech
 EuroStar



Auger No. **53886** Description
Caliper Pin Repair Kit

Type : SB6 - SB7
Replaces : II197330062 - II304130062

Suitable for	Replaces	Suitable for
Scania	1390426	4 Series Bus



Auger No. **53890** Description
Caliper Pin Repair Kit

Type : SB5 - SB6 - SB7 - SB7 RADIAL
Replaces : II339680062 - II328090062 - II369100062 - II328090061

Suitable for	Replaces	Suitable for
Mercedes	000 420 12 82 000 420 22 82 000 420 07 82 001 420 52 83	Atego / Atego2
Man	81.50822.6009	M2000
Scania	1390427	4 Series Bus



Auger No. **54686** Description
Caliper Pin Repair Kit

Type : SB6 - SB7
Replaces : K000132 - II350470062

Suitable for	Replaces	Suitable for
Mercedes	000 420 21 82	Atego / Atego2
Scania	1798063	4 Series Truck 4 Series Bus



Auger No. **54070** Description
Caliper Pin Repair Kit

Type : SB5
Replaces : K001925



Auger No. **70834** Description
Caliper Pin Repair Kit

Type : SN6
Replaces : K028451

Auger No.
54684
Description
 Caliper Pin Repair Kit
Type : SN6 - SN7 - SL7 - SM7
Replaces : K001915

Auger No.
71448
Description
 Caliper Pin Repair Kit
Type : SB6 - SB7
Replaces : K048396K50

Auger No.
71447
Description
 Caliper Pin Repair Kit
Type : SN6 - SN7 - SL7 - SM7
Replaces : K048389K50
Suitable for Man
Replaces 81.50822.6037
Suitable for TGA / TGS / TGM / TGX

Auger No.
78333
Description
 Caliper Pin Repair Kit
Type : SB6 - SB7
Replaces : K048371K50
Suitable for Man
Replaces 81.50822.6036
Suitable for TGA

Auger No.
68164
Description
 Caliper Pin Repair Kit
Type : SB7 - SN7
Replaces : K011117 - K031844K50 - K031844K55
Suitable for Scania
Replaces 1906779
 1756390
Suitable for 4 Series Truck
 PGRT Series Truck



Auger No. **70359**

Description: Caliper Pin Repair Kit

Type : SB5 - SB6 - SB7

Replaces : K000698 - K048434K55

Suitable for Scania Replaces 2021750, 1906776, 1477678 Suitable for 4 Series Truck, PGR Series Truck

Components: 60533 (ø36/ø40/82), 55345 (ø40/46), 55331 (ø30/ø51/36), ø32/80, ø36/114, ø39, ø35, 60485 (ø40/15)



Auger No. **53877**

Description: Caliper Pin Repair Kit

Type : SB7

Replaces : K000687

Suitable for Daf Replaces 1603326 Suitable for XF105/95, CF65/75/85

Components: ø32/80, ø36/145, 55378 (ø50/40), 60533, 55345 (ø40/46), ø39, 55331 (ø30/ø51/36)



Auger No. **53887**

Description: Caliper Pin Repair Kit

Type : SB5

Replaces : K001274

Components: ø36/102, ø36/ø40/70, 55376 (ø40/61), 55331 (ø30/ø51/36), ø32/80, ø39



Auger No. **56056**

Description: Caliper Pin Repair Kit

Type : SN6 - SN7 - SK7

Replaces : K002716

Components: 55331 (ø30/ø51/36), ø36/ø40/75, 55376 (ø40/61), ø36/102, ø32/80, ø39



Auger No. **54069**

Description: Caliper Pin Repair Kit

Type : SN6 - SN7 - SK7

Replaces : K000472

Suitable for Man Replaces 81.50822.6019 Suitable for TGA / TGS / TGM / TGX

Daf Replaces 1639100, 1622786 Suitable for CF65/75/85 / LF55

Bergische Achsen Replaces 09.801.06.33.0 Suitable for SKH Series (SB 3745), SH Series (SB 4345), SKH..LL Series (SB 3745), SH..LL Series (SB 4309 / SB 4345)

Sauer Achsen Replaces 3 434 3812 00 Suitable for SBK 1937-11 S, SBK 2243-11 S


Components: 60533 (ø36/ø40/82), 60485 (ø40/15), 55331 (ø30/ø51/36), 55376 (ø40/61), ø36/114, ø32/80, ø39

Auger No.	53889		Description
			Caliper Pin Repair Kit
Type	: SN6 - SN7 - SK7		
Replaces	: -		
Suitable for	Replaces	Suitable for	
Iveco	42541412	Tector / EuroFire / Eurostar EuroTech / Stralls	

Auger No.	53888		Description
			Caliper Pin Repair Kit
Type	: SB6 - SB7 - SN6 - SN7		
Replaces	: K000375		
Suitable for	Replaces	Suitable for	
Man	81.50822.6023	TGA	

Auger No.	56063		Description
			Caliper Pin Repair Kit
Type	: SB6 - SB7		
Replaces	: -		
Suitable for	Replaces	Suitable for	
Bergische Achsen	09.801.06.24.0	SKH Series (SB 3745) SKH..LL Series (SB 3745)	


Auger No.	56064		Description
			Caliper Pin Repair Kit
Type	: SB5 - SB6 - SB7		
Replaces	: -		
Suitable for	Replaces	Suitable for	
Bergische Achsen	09.801.06.31.0	SKH Series (SB 3745) SH Series (SB 4345) SKH..LL Series (SB 3745) SH..LL Series (SB 4309 / SB 4345)	



Auger No. **54071** Description Caliper Pin Repair Kit

Type : SB5 - SB6 - SB7
Replaces : K001532

Components: 55331 (ø30/ø51/36), 55376 (ø40/61), 60533 (ø36/ø40/82), ø35, ø36/114, ø32/80



Auger No. **76298** Description Caliper Pin Repair Kit

Type : SB6 - SB7 - SN6 - SN7
Replaces : K067417K50

Components: 55376 (ø40/61), ø36/114, ø32/80, 60533 (ø36/ø40/82), 55331 (ø30/ø51/36), ø35, ø39, 60485 (ø40/15)




Auger No. **77262** Description Caliper Pin Repair Kit

Type : SB5 - SB6 - SB7
Replaces : K001470

Suitable for Mercedes Replaces Suitable for
000 421 61 74 Atego 2 / Touro
000 420 46 82 Multtego / Turismo
000 420 34 82

Components: ø34/80, ø32/88, ø36/114, 60533 (ø36/ø40/82), 55344 (ø35/ø40/48), 55376 (ø40/61), 55331 (ø30/ø51/36), ø39, 60485 (ø40/15)



Auger No. **80235** Description Complete Caliper Kit New Type

Type : SN6 - SN7 - SK7
Replaces : -

Suitable for Mercedes Replaces Suitable for
- Actros
Bergische Achsen - SKH Series (SB 3745)
SH Series (SB 4345)
SKH..LL Series (SB 3745)
SH..LL Series (SB 4309 / SB 4345)

Components: 55348 (ø69), ø32/80, 57163, 57165, ø36/114, 55376 (ø40/61), 57162, 56008 (ø13,5), 73062, 55331 (ø30/ø51/36), 57182, ø39, 60533 (ø36/ø40/82), 72998 (ø16/ø18/10), 60485 (ø40/15)



Auger No. **80236** Description Complete Caliper Kit Old Type

Type : SN6 - SN7 - SK7
Replaces : -

Suitable for Mercedes Replaces Suitable for
- Actros
Bergische Achsen - SKH Series (SB 3745)
SH Series (SB 4345)
SKH..LL Series (SB 3745)
SH..LL Series (SB 4309 / SB 4345)

Components: 55348 (ø69), ø32/80, 57163, 57164, ø36/114, 56008 (ø13,5), 55376 (ø40/61), 57162, 55331 (ø30/ø51/36), 57182, ø35, 60533 (ø36/ø40/82), 72998 (ø16/ø18/10)

M14x2/55

M8x1.25/45

M10x1.5/60

Auger No.
56135

Description
Caliper Screw Set

Type : SB5 - SB6 - SB7 - SB7 RADIAL

Replaces : -

73184
ø38

73062

Auger No.
56112

Description
Brake Pad Retainer Kit

Type : SB5 - SN5 - SB6 - SB7 - SN6 - SN7 - SK7 - SL7 - SM7

Replaces : -

73186
ø35

73062

Auger No.
54525

Description
Adjusting Mechanism Cap Set

Type : SN6 - SN7 - SK7

Replaces : K003902

Suitable for	Replaces	Suitable for
Schmitz	1008543	-

73184
ø38

73062

Auger No.
54068

Description
Adjusting Mechanism Cap Set

Type : SN5 - SB6 - SB7 - SN6 - SN7 - SL7 - SM7

Replaces : K000029

Suitable for	Replaces	Suitable for
Man	81.50822.6021	TGA / TGS / TGM / TGX

73184
ø38

73062

Auger No.
53880

Description
Adjusting Mechanism Cap Set

Type : SB5 - SN5 - SB6 - SB7 - SN6 - SN7

Replaces : K000945

Suitable for	Replaces	Suitable for
Man	81.50822.6024	TGA / TGS / TGL / TGM / TGX
Scania	1390430	4 Series Bus
Daf	1439493	XF105/95 / CF65/75/85

Auger No. **70829** Description
Brake Pad Retainer Kit
Pad 25 mm

Type : SN5 - SB6 - SN6 - SK7 - SL7 - SM7
Replaces : K000133

Suitable for	Replaces	Suitable for
Mercedes	000 420 25 82	Atego / Atego 2 / Axor 2 Accelo / Actros 2/3



Auger No. **56144** Description
Brake Pad Retainer Kit

Type : Bendix ADB 3700 / 4300
Replaces : 381.419

Suitable for	Replaces	Suitable for
Iveco	93161560	EuroCargo / EuroTech EuroStar / EuroPolis



Auger No. **56145** Description
Brake Pad Retainer Kit

Type : Bendix ADB 3700 / 4300
Replaces : 381.422

Suitable for	Replaces	Suitable for
Iveco	93161559	EuroCargo / EuroFire



Auger No. **56085** Description
Pad Retention Pins and Clips Kit

Type : Bendix ADB 3700 / 4300
Replaces : I133692

Suitable for	Replaces	Suitable for
Iveco	-	EuroCargo / EuroTech EuroStar / EuroPolis EuroFire



Auger No.

56058

Description

Caliper Pin Repair Kit

Type : Bendix ADB 3700 / 4300

Replaces : 381.391

Suitable for
Iveco

Replaces
93161189

Suitable for
EuroCargo / EuroTech
EuroStar / EuroPolis
EuroFire



Auger No.

53883

Description

Caliper Pin Boot Set

Type : Bendix ADB 3700 / 4300

Replaces : 381.413

Suitable for
Iveco

Replaces
93161192

Suitable for
EuroCargo / EuroTech
EuroStar / EuroPolis
EuroFire



Auger No.

56069

Description

Wedge Assembly

Type : Bendix ADB 3700 / 4300

Replaces : 381.427

Suitable for
Iveco

Replaces
93192575

Suitable for
EuroCargo / EuroTech
EuroStar / EuroPolis



Auger No.

56106

Description

Wedge Assembly

Type : Bendix ADB 3700 / 4300

Replaces : 381.426

Suitable for
Iveco

Replaces
93192555

Suitable for
EuroCargo / EuroFire



mauger

GERMANY

**Suitable for
WABCO**



Auger No.

77415

Type : 19.5" - 22.5"

Replaces : -

Description

Caliper Adjusting Mechanism, Long
With Pin, 115 mm



Auger No.

75961

Type : 19.5" - 22.5"

Replaces : -

Description

Caliper Calibration Bolt, Long
With Pin, 80.4 mm



Auger No.

79285

Type : 17.5"

Replaces : -

Description

Caliper Adjusting Mechanism, Short
With Pin, 110 mm



Auger No.

77413

Type : 17.5"

Replaces : -

Description

Caliper Calibration Bolt, Short
With Pin, 76 mm



Auger No.

79284

Type : 17.5"

Replaces : -

Description

Caliper Adjusting Mechanism, Short
With Groove, 110 mm



Auger No.

75960

Type : 17.5"

Replaces : -

Description

Caliper Calibration Bolt, Short
With Groove, 76 mm



Auger No.

77414

Type : 19.5" - 22.5"

Replaces : -

Description

Caliper Bridge



Auger No.


79286

Type : 17.5"

Replaces : -

Description

Caliper Bridge



Auger No.
77311

Type : 17.5" - 19.5" - 22.5"
Replaces : -

Description
Caliper Lever



Auger No.
57600

Type : 17.5" - 19.5" - 22.5"
Replaces : -

Description
Roller Bearing



Auger No.
79236

Type : 17.5"
Replaces : -

Description
Caliper Gasket Kit



Auger No.
79232

Type : 17.5"
Replaces : -

Description
Caliper Gasket Kit



Auger No.
54528

Type : 1000VG
Replaces : 12 999 729VT

Suitable for	Replaces	Suitable for
Man	81.50800.6023	L2000
Daf	1517354	-
Neoplan	0821.392.00 1101 5566	-

Description
Caliper Pin & Durt Rubber Repair Kit




Auger No.
54559

Type : 19.5" - 22.5"
Replaces : 12999738VT

Suitable for	Replaces	Suitable for
Daf	1505890	-
Sauer Achsen	3 434 3827 01	9019/11019 W Brake SBW 1937 - PAN 19-1 9022/11222 W Brake SBW 2243 - PAN 22

Description
Caliper Pin Repair Kit

Auger No. **54561** Description
Caliper Pin Repair Kit



Type : 17.5"
Replaces : 12 999 704VT

Suitable for	Replaces	Suitable for
Daf	1519363	
R.V.I.	5001 852 880	Midlum

Auger No. **54565** Description
Caliper Pin Repair Kit



Type : 17.5"
Replaces : 12 999 580VT

Suitable for	Replaces	Suitable for
Man	81.50822.6003	L2000 / M2000
Daf	1517407	

Auger No. **54566** Description
Caliper Pin Repair Kit



Type : 17.5"
Replaces : 12 999 699VT - 12 999 702

Suitable for	Replaces	Suitable for
Daf	1436853	LF45 / LF55
Iveco	42536957	EuroCargo / EuroPolis

Auger No. **56026** Description
Dust Cover Kit



Type : 17.5" - 19.5" - 22.5"
Replaces : 640 175 920 2

Suitable for	Replaces	Suitable for
Sauer Achsen	3 434 3829 00	SK RB 9019 W SK RB 9022 W BI9-19W BI9-22W

Auger No. **56118**

Description: Dust Cover & Bush Kit

Type : 17.5"

Replaces : -

Labels in image: 55335 $\phi 23/\phi 30/25$, 72888 $\phi 34/16$, 55354 $\phi 31/\phi 73/11$

Auger No. **56120**

Description: Dust Cover & Bush Kit

Type : 19.5"

Replaces : -

Label in image: 55354 $\phi 31/\phi 73/11$

Auger No. **70838**

Description: Caliper Pin Repair Kit

Type : 19.5" - 22.5"

Replaces : 12 999 776

Suitable for

Daf	1628065	Suitable for LF45 / LF55
R.V.I.	5001 866 626	Midlum
Sauer Achsen	3 434 3828 00	-

Labels in image: 55337 $\phi 35/\phi 38/33$, 55354 $\phi 31/\phi 73/11$, 72884 $\phi 42/17$, 72886 $\phi 42/29$

Auger No. **70838**

Description: Caliper Pin Repair Kit

Type : 19.5" - 22.5"

Replaces : 12 999 776

Suitable for

Daf	1628065	Suitable for LF45 / LF55
R.V.I.	5001 866 626	Midlum
Sauer Achsen	3 434 3828 00	-

Auger No. **56119**

Description: Caliper Pin Repair Kit

Type : 17.5"

Replaces : -

Auger No. **56121**

Description: Caliper Pin Repair Kit

Type : 19.5"

Replaces : -

Auger No. **54569**

Description: Caliper Pin Repair Kit

Type : 22.5" Double Piston

Replaces : 12 999 678VT

Suitable for

Daf	0865966	-
R.V.I.	5021 170 488	-

Labels in image: 55334 $\phi 35/\phi 51/33$, 72884 $\phi 42/17$

Auger No. **54569**


Description: Caliper Pin Repair Kit

Type : 22.5" Double Piston

Replaces : 12 999 678VT

Suitable for

Daf	0865966	-
R.V.I.	5021 170 488	-



72886 $\varnothing 42/29$

55350 $\varnothing 18/\varnothing 70$

72884 $\varnothing 42/17$


55334 $\varnothing 35/\varnothing 51/33$

Auger No. 54562

Description
Caliper Pin Repair Kit

Type : 19.5" Double Piston
Replaces : 12 999 746VT

Suitable for	Replaces	Suitable for
Daf	1440505	LF55
R.V.I.	5001 858 722	Midlum



55350 $\varnothing 18/\varnothing 70$

55334 $\varnothing 35/\varnothing 51/33$


72884 $\varnothing 42/17$

Auger No. 54558

Description
Caliper Pin Repair Kit

Type : 22.5" Double Piston
Replaces : 12 999 677VT

Suitable for	Replaces	Suitable for
Daf	0865965	-
R.V.I.	5021 170 487	-



Auger No. 54568

Description
Caliper Pin Repair Kit

Type : AIR DISC BRAKE 1600 V-G
Replaces : 12 999 551VT

Suitable for	Replaces	Suitable for
Mercedes	000 420 09 82	O 405
Daf	AMPA137	-
Neoplan	1101 5717	-



Auger No. 54560

Description
Dust Cover Kit

Type : AIR DISC BRAKE 1600 V-G
Replaces : 12 999 552VT

Suitable for	Replaces	Suitable for
Mercedes	000 421 08 80	O 405
Daf	AMPA141	-



Auger No. 56024 **Description**
Caliper Pin Repair Kit

Type : AIR DISC BRAKE 1300 V-G
Replaces : 12 999 734VT

Suitable for Mercedes	Replaces 405 420 00 76	Suitable for Unimog
------------------------------	----------------------------------	-------------------------------


72884
ø42/17



Auger No. 56025 **Description**
Dust Cover Kit

Type : AIR DISC BRAKE 1300 V-G
Replaces : 12 999 733VT


Suitable for Mercedes	Replaces 405 420 00 83	Suitable for Unimog
------------------------------	----------------------------------	-------------------------------



Auger No. 54567 **Description**
Dust Cover Kit

Type : CALIPER DISC BRAKE 244 V-Ö
Replaces : 12 999 543VT


Suitable for Mercedes	Replaces 000 420 04 82	Suitable for Sprinter / Vario
Daf	1517794	-



Auger No. 55814 **Description**
Dust Cover Kit

Type : CALIPER DISC BRAKE 244 V-Ö
Replaces : -

Suitable for Mercedes	Replaces 001 420 23 83	Suitable for Sprinter / Vito
------------------------------	----------------------------------	--



Auger No. 54563 **Description**
Dust Cover Kit

Type : CALIPER DISC BRAKE 485 F-Ö
Replaces : 12 999 076VT

Suitable for Daf	Replaces 1518458	Suitable for -
Iveco	8124438	TurboCity


Auger No. Description
54527 Dust Cover Kit



Type : CALIPER DISC BRAKE 450 F-Ö
Replaces : 12 999 199VT

Suitable for	Replaces	Suitable for
Iveco	93161181	Daily II

Auger No. Description
54570 Dust Cover Kit



Type : CALIPER DISC BRAKE 456 F-Ö
Replaces : 12 999 141VT

Suitable for	Replaces	Suitable for
Daf	FBU1298	F600-800-1000 ROADRUNNER

Auger No. Description
56027 Dust Cover Kit



Type : CALIPER DISC BRAKE 456 F-Ö
Replaces : 12 999 116VT

Suitable for	Replaces	Suitable for
Daf	FBU1076	F45 F600-800-1000 ROADRUNNER

Auger No. Description
54564 Dust Cover Kit



Type : CALIPER DISC BRAKE 444 F-Ö
Replaces : 12999197VT

Suitable for	Replaces	Suitable for
Mercedes	000 420 68 83	L Series
Daf	1505880	-
Iveco	8124729	Daily I/II

mauger

GERMANY

**Suitable for
HALDEX**



Auger No.

79759

Description

Caliper Adjusting Mechanism

Type : Suitable for MODUL T

Replaces : -

Suitable for
Sauer Achsen

Replaces
-

Suitable for
BI9-22S (SBS 2220 Series)



Auger No.

79760

Description

Caliper Bridge

Type : Suitable for MODUL T

Replaces : -

Suitable for
Sauer Achsen

Replaces
-

Suitable for
BI9-22S (SBS 2220 Series)



Auger No.

79761

Description

Caliper Lever

Type : Suitable for MODUL T

Replaces : -

Suitable for
Sauer Achsen

Replaces
-

Suitable for
BI9-22S (SBS 2220 Series)



Auger No.

79762

Description

Caliper Lever Housing

Type : Suitable for MODUL T

Replaces : -

Suitable for
Sauer Achsen

Replaces
-

Suitable for
BI9-22S (SBS 2220 Series)


Auger No. Description
79763 Caliper Calibration Bolt



Type : Suitable for MODUL T
 Replaces : -

Suitable for	Replaces	Suitable for
Sauer Achsen	-	BI9-22S (SBS 2220 Series)

Auger No. Description
79751 Roller Bearing Kit



Type : Suitable for MODUL T
 Replaces : -

Suitable for	Replaces	Suitable for
Sauer Achsen	-	BI9-22S (SBS 2220 Series)

Auger No. Description
79753 Roller Bearing Kit



Type : Suitable for MODUL T
 Replaces : -

Suitable for	Replaces	Suitable for
Sauer Achsen	-	BI9-22S (SBS 2220 Series)

Auger No. Description
79752 Roller Bearing Kit



Type : Suitable for MODUL T
 Replaces : -

Suitable for	Replaces	Suitable for
Sauer Achsen	-	BI9-22S (SBS 2220 Series)

Auger No. **79764** Description
Caliper Mechanizm Gear



Type : Suitable for MODUL T

Replaces : -

Suitable for	Replaces	Suitable for
Sauer Achsen	-	BI9-22S (SBS 2220 Series)

Auger No. **79754** Description
Caliper Reset Shaft Kit



Type : -

Replaces : 95398 - 95055

Suitable for	Replaces	Suitable for
Sauer Achsen	3 434 3862 00	BI9-22S (SBS 2220 Series)

Auger No. **79755** Description
Caliper Repair Kit



Type : Suitable for MODUL T

Replaces : -

Suitable for	Replaces	Suitable for
Sauer Achsen	-	BI9-22S (SBS 2220 Series)

Auger No. **79756** Description
Adjusting Mechanism Repair Kit



Type : Suitable for MODUL T

Replaces : -

Suitable for	Replaces	Suitable for
Sauer Achsen	-	BI9-22S (SBS 2220 Series)

Auger No.

79758

Description

Caliper Pin Repair Kit



Type : Suitable for MODUL T

Replaces : -

Suitable for
Sauer Achsen

Replaces
-

Suitable for
BI9-22S (SBS 2220 Series)

Auger No.

79785

Description

Dust Cover Kit



Type : Suitable for MODUL T

Replaces : -

Suitable for
Sauer Achsen

Replaces
-

Suitable for
BI9-22S (SBS 2220 Series)

Auger No.

79780

Description

Dust Cover Kit



Type : Suitable for MODUL T

Replaces : -

Suitable for
Sauer Achsen

Replaces
-

Suitable for
BI9-22S (SBS 2220 Series)



Auger No.
57599

Description
Roller Bearing

Type : MARK IV - Suitable for MODUL X GEN 1
Replaces : -



Auger No.
56093

Description
Caliper Plug Set

Type : MARK III - Suitable for MODUL X GEN 1 - MODUL X GEN 2
Replaces : 89925



Auger No.
56099

Description
Brake Tappet Plate

Type : MARK IV - Suitable for MODUL X GEN 1
Replaces : 91236



Auger No.
56092

Description
Caliper Plug Set

Type : MARK IV - Suitable for MODUL X GEN 1 - MODUL X GEN 2
Replaces : 90693



Auger No.
56098

Description
Spring & Brake Tappet Plate

Type : MARK IV - Suitable for MODUL X - GEN 1
Replaces : 92731



Auger No.
56094

Description
Spring & Boot Set

Type : MARK IV - Suitable for MODUL X GEN 1 - MODUL X GEN 2
Replaces : 89794



Auger No.
70839

Description
Caliper Tappet Plate & Boot Set

Type : MARK IV - Suitable for MODUL X GEN 1
Replaces : 94664 - 93285

57651
ø36xø67x50


<p>Auger No. 56091</p> <p>Type : MARK IV - Suitable for MODUL X GEN 1</p> <p>Replaces : 94662</p> <p>Suitable for Sauer Achsen</p>	<table border="0"> <tr> <td>Replaces</td> <td>3 434 3852 02</td> </tr> </table> <p>Suitable for</p> <p>SK RB 9022 H (MK IV) SK RB 9022 H (MODUL X) 9022/11222H(MODUL X) Brake SBH 2243-11 S (MODUL X)</p>	Replaces	3 434 3852 02	<p>Description Caliper Boot & Plug Set</p>
Replaces	3 434 3852 02			

57650
ø41xø78x52

<p>Auger No. 56090</p> <p>Type : MARK II - MARK III</p> <p>Replaces : 94663 - 87405</p> <p>Suitable for Sauer Achsen</p>	<table border="0"> <tr> <td>Replaces</td> <td>3 434 3852 00</td> </tr> </table> <p>Suitable for</p> <p>SK RB 9022 H (MK II/III) 9022/11222 H (MK II) Brake SBH 2243-11 S (MK II) 9022/11222 H (MK III) Brake SBH 2243-11 S (MK III)</p>	Replaces	3 434 3852 00	<p>Description Caliper Boot & Plug Set</p>
Replaces	3 434 3852 00			

<p>Auger No. 56095</p> <p>Type : MARK II - MARK III - MARK IV</p> <p>Replaces : 94661</p> <p>Suitable for Sauer Achsen</p>	<table border="0"> <tr> <td>Replaces</td> <td>3 434 3858 00 3 434 3854 01</td> </tr> </table> <p>Suitable for</p> <p>SK RB 9022 H (MK II/III) SK RB 9022 H (MK IV) 9022/11222 H (MK II) Brake SBH 2243-11 S (MK II) 9022/11222 H (MK III) Brake SBH 2243-11 S (MK III) 9022/11222 H (MK IV) Brake SBH 2243-11 S (MK IV)</p>	Replaces	3 434 3858 00 3 434 3854 01	<p>Description Caliper Pin Bolt Repair Kit</p>
Replaces	3 434 3858 00 3 434 3854 01			

<p>Auger No. 56096</p> <p>Type : Suitable for MODUL X GEN 1 - MODUL X GEN 2</p> <p>Replaces : 94660</p> <p>Suitable for Sauer Achsen</p>	<table border="0"> <tr> <td>Replaces</td> <td>-</td> </tr> </table> <p>Suitable for</p> <p>SK RB 9022 H (MODUL X) 9022/11222H(MODUL X) Brake SBH 2243-11 S (MODUL X)</p>	Replaces	-	<p>Description Caliper Pin Bolt Repair Kit</p>
Replaces	-			



Auger No.

56097

Description

Caliper Pin Repair Kit

Type : MARK II - MARK III - MARK IV

Replaces : 89541



Auger No.

56100

Description

Caliper Pin Repair Kit

Type : MARK II - MARK III - MARK IV

Replaces : 87406



Auger No.

56101

Description

Caliper Pin Repair Kit

Type : Suitable for MODUL X GEN 1

Replaces : 91012



Auger No.

71446

Description

Caliper Pin Repair Kit

Type : Suitable for MODUL X GEN 2

Replaces : 93299

AUGER

GERMANY

Suitable for ROR-MERITOR



Auger No. **77377** Description
Caliper Bridge Assembly, Left
Type : DX195
Replaces : -



Auger No. **77378** Description
Caliper Bridge Assembly, Right
Type : DX195
Replaces : -



Auger No. **56031** Description
Caliper Bridge Assembly, Left
Type : DX195
Replaces : MCK1292



Auger No. **56032** Description
Caliper Bridge Assembly, Right
Type : DX195
Replaces : MCK1293




Auger No. **56111** Description
Caliper Piston Kit, Left
Type : DX195
Replaces : -



Auger No. **56110** Description
Caliper Piston Kit, Right
Type : DX195
Replaces : -



Auger No. **56109** Description
Caliper Plate Kit, Left
Type : DX195
Replaces : -



Auger No. **56108** Description
Caliper Plate Kit, Right
Type : DX195
Replaces : -



Auger No. **56043** Description
 Adjusting Mechanism Repair Kit, Left

Type : DX195
 Replaces : MCK1290



Auger No. **56073** Description
 Adjusting Mechanism Repair Kit, Right

Type : DX195
 Replaces : MCK1291



Auger No. **77383** Description
 Adjusting Mechanism Repair Kit, Left

Type : DX195
 Replaces : DSL5L



Auger No. **77384** Description
 Adjusting Mechanism Repair Kit, Right

Type : DX195
 Replaces : DSL5R



Auger No. **56117** Description
 Caliper Adjusting Gear Set

Type : DX195 - DX225
 Replaces : -



Auger No. **70701** Description
 Eccentric Shaft

Type : DX195
 Replaces : -



Auger No. **77382** Description
 Caliper Bearing Kit

Type : DX195 - DX225
 Replaces : MCK1344



Auger No. **56006** Description
 Roller Bearing

Type : DX195 - DX225
 Replaces : -



Auger No. **56041** Description
 Eccentric Shaft Repair Kit

Type : DX195
 Replaces : MCK1294 - MCK1168 - MCK1169



Auger No. **53866** Description
 Caliper Pin Repair Kit

Type : DX195
 Replaces : MCK1171/N



55374
ø19/ø34/ø58/22

55375
ø21/ø42/21

Auger No.
53872

Description
Caliper Pin Repair Kit

Type : DX195
Replaces : MCK1171



55374
ø19/ø34/ø58/22

55375
ø21/ø42/21

Auger No.
53873

Description
Caliper Boot & Cap Set

Type : DX195
Replaces : MCK1192



55375
ø21/ø42/21

Auger No.
56020

Description
Caliper Pin Repair Kit

Type : DX195
Replaces : DSB1



55374
ø19/ø34/ø58/22

Auger No.
56035

Description
Caliper Pin Repair Kit

Type : DX225
Replaces : MCK1172



Auger No.
56036

Description
Caliper Pin Repair Kit

Type : DX175
Replaces : MCK1191



55374
ø19/ø34/ø58/22

Auger No.
56044

Description
Caliper Boot & Cap Set

Type : DX225
Replaces : MCK1193




55374
ø19/ø34/ø58/22

55375
ø21/ø42/21

Auger No.
70687

Description
Caliper Pin Repair Kit

Type : DX225
Replaces : MCK1173



Auger No.
56042

Description
Brake Pad Retainer Kit

Type : DX195
Replaces : MCK1154



Auger No. **56122** Description
Spline Shaft, Left (48 Teeth), Front
Type : D3
Replaces : -



Auger No. **56123** Description
Spline Shaft, Right (48 Teeth), Front
Type : D3
Replaces : -



Auger No. **56124** Description
Spline Shaft, Left (26 Teeth), Front
Type : D3
Replaces : -



Auger No. **56125** Description
Spline Shaft, Right (26 Teeth), Front
Type : D3
Replaces : -



Auger No. **56131** Description
Shaft Base, Left
Type : D3
Replaces : -



Auger No. **56132** Description
Shaft Base, Right
Type : D3
Replaces : -



Auger No. **71855** Description
Ball Bearing Set
Type : D3
Replaces : -



Auger No. **56004** Description
Roller Bearing
Type : D3
Replaces : -



Auger No. **56126** Description Clutch System Kit, Left
Type : D3
Replaces : -




Auger No. **56127** Description Clutch System Kit, Right
Type : D3
Replaces : -



Auger No. **73416** Description Caliper Adjusting Gear Set, Left
Type : D3
Replaces : -



Auger No. **57591** Description Caliper Adjusting Gear Set, Right
Type : D3
Replaces : -



Auger No. **55176** Description Spline Shaft Cover Set
Type : D3
Replaces : -
Suitable for R.V.I. Replaces 5001 831 176 Suitable for Premium / Magnum



Auger No. **56019** Description Spline Shaft Cover Set
Type : D3
Replaces : SJ1212
Suitable for Mercedes Replaces - Suitable for O350 / O403 / O404
Man 81.50802.6007 F90 / F2000 / M2000 E Series
Kassbohrer 8.285.388.441 -

Auger No. **70697** Description
Dust Cover



Type : D3
Replaces : 68320507PK10

Suitable for	Replaces	Suitable for
-	-	-

Auger No. **54175** Description
Caliper Pin Repair Kit



Type : D3
Replaces : SJ4001

Suitable for	Replaces	Suitable for
R.V.I.	5001 822 994	Premium / Magnum

Auger No. **54546** Description
Caliper Pin Repair Kit



Type : D3
Replaces : SJ1213

Suitable for	Replaces	Suitable for
Mercedes	000 420 01 76	Tourismo


Auger No. **54549** Description
Caliper Pin Repair Kit



Type : D3
Replaces : SJ4011 - MCK1213 - SJ1228

Suitable for	Replaces	Suitable for
Mercedes	000 420 02 76	Tourismo
Man	81.50802.6009 81.50802.6008	F90 / F2000 / M2000 E Series

Auger No. Description
56059 Caliper Adjusting Mechanism, Left



Type : C LISA
Replaces : MCK1075
Suitable for R.V.I. Replaces 5001 854 954 Suitable for Premium / Magnum Midliner

Auger No. Description
56060 Caliper Adjusting Mechanism, Right



Type : C LISA
Replaces : MCK1076
Suitable for R.V.I. Replaces 5001 854 955 Suitable for Premium / Magnum Midliner

Auger No. Description
56014 Caliper Adjusting Mechanism, Left



Type : C LISA - D LISA
Replaces : -
Suitable for R.V.I. Replaces 5001 856 319 Suitable for Premium / Magnum Midliner

Auger No. Description
56015 Caliper Adjusting Mechanism, Right



Type : C LISA - D LISA
Replaces : -
Suitable for R.V.I. Replaces 5001 856 320 Suitable for Premium / Magnum Midliner



<p>Auger No. 56040</p> <p>Type : C LISA - D LISA Replaces : SJ4113 - MCK4113</p> <table border="0"> <tr> <td>Suitable for</td> <td>Replaces</td> <td>Suitable for</td> </tr> <tr> <td>Volvo</td> <td>-</td> <td>B10</td> </tr> <tr> <td>R.V.I.</td> <td>-</td> <td>Premium / Magnum Midliner</td> </tr> </table>	Suitable for	Replaces	Suitable for	Volvo	-	B10	R.V.I.	-	Premium / Magnum Midliner	<p style="text-align: right;">Description</p> <p>Caliper Adjusting Mechanism, Left</p>
Suitable for	Replaces	Suitable for								
Volvo	-	B10								
R.V.I.	-	Premium / Magnum Midliner								



<p>Auger No. 56018</p> <p>Type : C LISA - D LISA Replaces : SJ4114</p> <table border="0"> <tr> <td>Suitable for</td> <td>Replaces</td> <td>Suitable for</td> </tr> <tr> <td>Volvo</td> <td>-</td> <td>B10</td> </tr> <tr> <td>R.V.I.</td> <td>-</td> <td>Premium / Magnum Midliner</td> </tr> </table>	Suitable for	Replaces	Suitable for	Volvo	-	B10	R.V.I.	-	Premium / Magnum Midliner	<p style="text-align: right;">Description</p> <p>Caliper Adjusting Mechanism, Right</p>
Suitable for	Replaces	Suitable for								
Volvo	-	B10								
R.V.I.	-	Premium / Magnum Midliner								



<p>Auger No. 56033</p> <p>Type : C LISA - D LISA Replaces : SJ4074</p> <table border="0"> <tr> <td>Suitable for</td> <td>Replaces</td> <td>Suitable for</td> </tr> <tr> <td>Volvo</td> <td>3098110</td> <td>B10</td> </tr> <tr> <td>R.V.I.</td> <td>-</td> <td>Premium / Magnum Midliner</td> </tr> </table>	Suitable for	Replaces	Suitable for	Volvo	3098110	B10	R.V.I.	-	Premium / Magnum Midliner	<p style="text-align: right;">Description</p> <p>Caliper Adjusting Gear Set, Left</p>
Suitable for	Replaces	Suitable for								
Volvo	3098110	B10								
R.V.I.	-	Premium / Magnum Midliner								



<p>Auger No. 56034</p> <p>Type : C LISA - D LISA Replaces : SJ4074</p> <table border="0"> <tr> <td>Suitable for</td> <td>Replaces</td> <td>Suitable for</td> </tr> <tr> <td>Volvo</td> <td>3098111</td> <td>B10</td> </tr> <tr> <td>R.V.I.</td> <td>-</td> <td>Premium / Magnum Midliner</td> </tr> </table>	Suitable for	Replaces	Suitable for	Volvo	3098111	B10	R.V.I.	-	Premium / Magnum Midliner	<p style="text-align: right;">Description</p> <p>Caliper Adjusting Gear Set, Right</p>
Suitable for	Replaces	Suitable for								
Volvo	3098111	B10								
R.V.I.	-	Premium / Magnum Midliner								

Auger No.

56029

Description

Operating Shaft Kit, Left



Type : C LISA - D LISA

Replaces : MCK1151 - MCK1021

Suitable for

Volvo

Replaces

-

Suitable for

B10

R.V.I.

-

Premium / Magnum
Midliner

Auger No.

56030

Description

Operating Shaft Kit, Right



Type : C LISA - D LISA

Replaces : MCK1152 - MCK1022

Suitable for

Volvo

Replaces

-

Suitable for

B10

R.V.I.

-

Premium / Magnum
Midliner

Auger No.

57586

Description

Operating Shaft, Left



Type : C LISA - D LISA

Replaces : -

Suitable for

Volvo

Replaces

-

Suitable for

B10

R.V.I.

-

Premium / Magnum
Midliner

Auger No.

57587

Description

Operating Shaft, Right



Type : C LISA - D LISA

Replaces : -

Suitable for

Volvo

Replaces

-

Suitable for

B10

R.V.I.

-

Premium / Magnum
Midliner

Auger No. Description
56114 Shaft Base, Left



Type : C LISA - D LISA

Replaces : -

Suitable for	Replaces	Suitable for
Volvo	-	B10
R.V.I.	-	Premium / Magnum Midliner

Auger No. Description
56115 Shaft Base, Right



Type : C LISA - D LISA

Replaces : -

Suitable for	Replaces	Suitable for
Volvo	-	B10
R.V.I.	-	Premium / Magnum Midliner

Auger No. Description
56116 Ball Bearing Set



Type : C LISA - D LISA

Replaces : -

Suitable for	Replaces	Suitable for
Volvo	-	B10
R.V.I.	-	Premium / Magnum Midliner

Auger No. Description
56028 Caliper Bearing Kit



Type : C LISA - D LISA

Replaces : SJ4031

Suitable for	Replaces	Suitable for
Volvo	-	B10
R.V.I.	-	Premium / Magnum Midliner

Auger No.
54532

Description

Caliper Pin Repair Kit

Type : C LISA
Replaces : SJ4052

Suitable for R.V.I. Replaces -

Suitable for Midliner



Auger No.
54548

Description

Caliper Pin Repair Kit

Type : D LISA
Replaces : SJ4076 - MCK1104

Suitable for Volvo R.V.I. Replaces 3098108 -

Suitable for B7/10 Premium / Magnum



Auger No.
53874

Description

Caliper Pin Repair Kit

Type : D LISA
Replaces : -

Suitable for R.V.I. Replaces 5001 837 006

Suitable for Premium / Magnum



Auger No.
56088

Description

Seal Kit

Type : D LISA
Replaces : -

Suitable for R.V.I. Replaces 5001 854 951

Suitable for Premium / Magnum



Auger No.

54552

Description

Screw & Cap Kit



Type : D LISA

Replaces : SJ4021

Suitable for Replaces
Volvo 8550881

Suitable for
B10

R.V.I. -

Premium / Magnum

Auger No.

54547

Description

Dust Cover & Gasket Kit



Type : D LISA

Replaces : SJ4078

Suitable for Replaces
Volvo 3098113

Suitable for
B7/10/12

R.V.I. -


Premium / Magnum

Auger No.

56017

Description

Dust Cover & Gasket Kit



Type : C LISA

Replaces : SJ4032

Suitable for Replaces
R.V.I. -

Suitable for
Premium

Auger No.

56045

Description

Dust Cover & Gasket Kit



Type : C LISA

Replaces : SJ4061

Suitable for Replaces
R.V.I. -

Suitable for
Midliner

Auger No.

54531

Description

Dust Cover Kit

Type : D LISA

Replaces : SJ4077

Suitable for Replaces

Volvo -

Suitable for

B10

R.V.I. -

Premium / Magnum



Auger No.

54555

Description

Dust Cover Kit

Type : C LISA

Replaces : SJ4053

Suitable for Replaces

R.V.I. -

Suitable for

Midliner



Auger No.

56086

Description

Brake Pad Retainer Kit

Type : C LISA


Replaces : SJ4051

Suitable for Replaces

R.V.I. -

Suitable for

Midliner



Auger No.

56087

Description

Brake Pad Retainer Kit

Type : D LISA

Replaces : SJ4022

Suitable for Replaces

Volvo -

Suitable for

B10

R.V.I. 5001836607

Premium / Magnum



73105
M24x1,5 LHT

Auger No. **79282**

Description
Caliper Adjusting Gear Set
Left (Ø35 mm)

Type : Suitable for ELSA 1
Replaces : -

73104
M24x1,5 RHT

Auger No. **79281**

Description
Caliper Adjusting Gear Set
Right (Ø35 mm)

Type : Suitable for ELSA 1
Replaces : -

73105
M24x1,5 LHT

Auger No. **57590**

Description
Caliper Adjusting Gear Set
Left (Ø37,5 mm)

Type : Suitable for ELSA 1
Replaces : -

73104
M24x1,5 RHT

Auger No. **57589**

Description
Caliper Adjusting Gear Set
Right (Ø37,5 mm)

Type : Suitable for ELSA 1
Replaces : -

73173

Auger No. **57597**

Description
Adjusting Mechanism Repair Kit, Left

Type : Suitable for ELSA 1
Replaces : -

73174

Auger No. **57598**

Description
Adjusting Mechanism Repair Kit, Right

Type : Suitable for ELSA 1
Replaces : -

Auger No. **56139**

Description
Clutch System Kit, Left

Type : Suitable for ELSA 1
Replaces : -

Auger No. **56140**

Description
Clutch System Kit, Right

Type : Suitable for ELSA 1
Replaces : -

Auger No.

56005

Description
Locking Shim


Type : Suitable for ELSA 1

Replaces : 68321678PK10 - 68321678

Suitable for
Man

Replaces
81.50822.0006

Suitable for
TGA / TGS / TGX
Lion's Series



Auger No.

70699

Description

Caliper Adjusting Mechanism (Bearing)

Type : Suitable for ELSA2 SERIES - ELSA195 - ELSA225 - EX225

Replaces : -



Auger No.

56141

Description

Adjusting Mechanism Repair Kit
For 70699

Type : Suitable for ELSA2 SERIES - ELSA195 - ELSA225 - EX225

Replaces : -



Auger No.

56136

Description

Caliper Adjusting Gear Set

Type : Suitable for ELSA2 SERIES - ELSA195 - ELSA225 - EX225

Replaces : -



Auger No.

70694

Description

Caliper Adjusting Gear Set

Type : Suitable for ELSA2 AXIAL - ELSA195 - ELSA225

Replaces : -



Auger No.

79746

Description

Small Gear Mechanism, Right

Type : C DUCO - Le DUCO - D DUCO SERIES - Suitable for ELSA 1

Replaces : 68322563PK4



Auger No.

73417

Description

Small Gear Mechanism, Left

Type : C DUCO - Le DUCO - D DUCO SERIES - Suitable for ELSA 1

Replaces : 68322562PK4





Auger No.
70695

Description
Caliper Cover Kit


Type : Suitable for ELSA2 AXIAL
Replaces : -



Auger No.
76246

Description
Caliper Adjusting Gear Set

Type : Suitable for ELSA195 - ELSA225 - EX225
Replaces : -



Auger No.
70688

Description
Caliper Adjusting Gear Set, Left

Type : Suitable for ELSA2 SERIES
Replaces : -



Auger No.
70689

Description
Caliper Adjusting Gear Set, Right

Type : Suitable for ELSA2 SERIES
Replaces : -



Auger No.
55820

Description
Intermediate Gear & Spring Set

Type : D DUCO SERIES
Replaces : MCK1067

Suitable for	Replaces	Suitable for
Volvo	3095626	FH12/16 FM7/9/10/12 B7/12



Auger No.
57161

Description
Lock Plate

Type : D DUCO SERIES
Replaces : 68322900PK10



Auger No.
70698

Description
Lock Plate

Type : C DUCO - Le DUCO
Replaces : 68322485PK10

Auger No.

57345

Description

Caliper Lever Set



Type : B DUCO

Replaces : MCK1048

Suitable for
Volvo

Replaces
-

Suitable for
FL6

Auger No.

57343

Description

Caliper Lever Set, Left



Type : C DUCO - Le DUCO

Replaces : MCK1127

Suitable for
Volvo

Replaces
-

Suitable for
FM9

Auger No.

57344

Description

Caliper Lever Set, Right



Type : C DUCO - Le DUCO

Replaces : MCK1128

Suitable for
Volvo

Replaces
-

Suitable for
FM9

Auger No.

56053

Description

Caliper Lever Set



Type : D DUCO RADIAL

Replaces : SJ4108

Suitable for
Volvo

Replaces
21109755
85109977
3092260

Suitable for
FH12/16
FM7/9/12

Auger No. Description
56071 Caliper Lever Set, Left



Type : D DUCO AXIAL
 Replaces : SJ4096

Suitable for	Replaces	Suitable for
Volvo	21109753	FH12/16
	85109975	FM7/9/10/12
	3092258	

Auger No. Description
56072 Caliper Lever Set, Right



Type : D DUCO AXIAL
 Replaces : SJ4097

Suitable for	Replaces	Suitable for
Volvo	21109754	FH12/16
	85109976	FM7/9/10/12
	3092259	

Auger No. Description
55819 Roller Bearing Kit



Type : B DUCO - C DUCO - Le DUCO - D DUCO AXIAL
 Replaces : SJ4112

Suitable for	Replaces	Suitable for
Volvo	3092329	FH12/16
		FM7/9/10/12


Auger No. Description
57581 Roller Bearing Kit



Type : D DUCO RADIAL - Suitable for ELSA2 RADIAL
 Replaces : SJ4098

Suitable for	Replaces	Suitable for
Volvo	3092261	FH12/16
		FM7/9/10/12


Auger No. **55720** Description
Adjusting Mechanism Shaft Kit
Rear Left



Type : C DUCO - Le DUCO - D DUCO SERIES
Replaces : MCK1111

Suitable for	Replaces	Suitable for
Volvo	85102095	FH12/16 FM7/9/10/12

Auger No. **56047** Description
Adjusting Mechanism Shaft Kit
Rear Left, 55720' s Old Type



Type : C DUCO - Le DUCO - D DUCO SERIES
Replaces : SJ4102

Suitable for	Replaces	Suitable for
Volvo	3092265	FH12/16 FM7/9/10/12


Auger No. **55721** Description
Adjusting Mechanism Shaft Kit
Rear Right



Type : C DUCO - Le DUCO - D DUCO SERIES
Replaces : MCK1112

Suitable for	Replaces	Suitable for
Volvo	85102096	FH12/16 FM7/9/10/12

Auger No. **56048** Description
Adjusting Mechanism Shaft Kit
Rear Right, 55721' s Old Type



Type : C DUCO - Le DUCO - D DUCO SERIES
Replaces : SJ4103

Suitable for	Replaces	Suitable for
Volvo	3092266	FH12/16 FM7/9/10/12

Auger No. **55719** Description
Adjusting Mechanism Shaft Kit
Front Left-Right

Type : C DUCO - Le DUCO - D DUCO SERIES
Replaces : MCK1113

Suitable for	Replaces	Suitable for
Volvo	85102093	FH12/16 FM7/9/10/12



Auger No. **55823** Description
Dust Cover & Gasket Kit

Type : D DUCO AXIAL
Replaces : SJ4105

Suitable for	Replaces	Suitable for
Volvo	3092269	FH12/16 FM7/9/10/12



Auger No. **55822** Description
Dust Cover & Gasket Kit

Type : D DUCO RADIAL
Replaces : SJ4109

Suitable for	Replaces	Suitable for
Volvo	3092270	FH12/16 FM7/9/10/12



Auger No. **55821** Description
Dust Cover & Gasket Kit

Type : C DUCO - Le DUCO
Replaces : MCK1041

Suitable for	Replaces	Suitable for
Volvo	3095669	FH12 FM9/12



Auger No.

55857

Description

Dust Cover Kit

Type : Suitable for ELSA 1

Replaces : ST1156

Suitable for
Man

Replaces
81.50802.6016

Suitable for
TGA / TGS / TGX
Lion's Series



Auger No.

53870

Description

Dust Cover Kit

Type : B DUCO - C DUCO - Le DUCO - D DUCO SERIES

Replaces : MCK1139

Suitable for
Man

Replaces
81.50802.6024

Suitable for
TGA / TGL/
Lion's City

Volvo

85107913

FH12/16
FM7/9/10/12



Auger No.

53871

Description

Tappet Kit

Type : B DUCO - C DUCO - Le DUCO - D DUCO SERIES

Replaces : MCK1238

Suitable for
Volvo

Replaces
3092264

Suitable for
FH12/16
FM7/9/10/12



Auger No.

54174

Description

Tappet Kit

Type : Suitable for ELSA2 SERIES - ELSA195 - ELSA225

Replaces : MCK1309

Suitable for
R.V.I.

Replaces
5001 866 398

Suitable for
Premium / Magnum
Midlum



Auger No.	Description	
54173	Caliper Boot & Cap Set	
Type	: Suitable for ELSA2 SERIES - ELSA195 - ELSA225	
Replaces	: MCK1244	
Suitable for	Replaces	Suitable for
R.V.I.	5001 858 718 5001 860 792	Premium / Magnum

Auger No.	Description	
54172	Caliper Boot & Cap Set	
Type	: Suitable for ELSA225	
Replaces	: MCK1310	
Suitable for	Replaces	Suitable for
Volvo	85109892	FH13/12/16 FM9/11/12/13
R.V.I.	5001 866 400	Premium / Magnum Midlum

Auger No.	Description	
53868	Caliper Boot & Cap Set	
Type	: Suitable for ELSA195	
Replaces	: MCK1253	

Auger No.	Description	
53869	Caliper Pin Repair Kit	
Type	: Suitable for ELSA2 SERIES - ELSA195	
Replaces	: MCK1254	

Auger No.	Description	
54169	Caliper Pin Repair Kit	
Type	: Suitable for ELSA195 - EX225	
Replaces	: MCK1298	
Suitable for	Replaces	Suitable for
Volvo	85109890	FH13/12/16 FM9/11/12/13
R.V.I.	5001 866 989	Premium / Magnum Midlum

Auger No.

54170

Description

Caliper Pin Repair Kit

Type : Suitable for ELSA2 SERIES

Replaces : MCK1086

Suitable for
Man

Replaces
-

Suitable for
F2000

R.V.I.

5001 858 717

Premium / Magnum



Auger No.

54171

Description

Caliper Pin Repair Kit

Type : Suitable for ELSA2 SERIES

Replaces : MCK1243 - MCK1140

Suitable for
Man

Replaces
81.50802.6025

Suitable for
TGA / TGL/ Lion's City

Volvo

85107912

FH12/16 - FM7/9/10/12

R.V.I.

5001 860 791

Premium / Magnum
Midlum



Auger No.

54529

Description

Caliper Pin Repair Kit

Type : Suitable for ELSA 1

Replaces : MCK1103

Suitable for
Man

Replaces
81.50802.6022

Suitable for
TGA / TGS / TGX
Lion's Series



Auger No.

54550

Description

Caliper Pin Repair Kit

Type : Suitable for ELSA 1

Replaces : MCK1102

Suitable for
Man

Replaces
-

Suitable for
TGA / Lion's Series



Auger No.

53867

Description

Caliper Pin Repair Kit


Type : Suitable for ELSA 1

Replaces : MCK1102/N

Suitable for
Man

Replaces
-

Suitable for
TGA / Lion's Series



Auger No.

56009

Description

Caliper Pin Repair Kit

Type : Suitable for ELSA 1

Replaces : ST1157 - ST1192

Suitable for
Man

Replaces
81.50802.6021
81.50802.6020
81.50802.6017

Suitable for
TGA / TGS / TGX
Lion's Series



Auger No.

54530

Description

Caliper Pin Repair Kit

Type : B DUCO - C DUCO - Le DUCO - D DUCO AXIAL

Replaces : MCK1134 - SJ4094

Suitable for
Volvo

Replaces
85103892

Suitable for
FH12/16
FM7/10



Auger No.

54551

Description

Caliper Pin Repair Kit

Type : B DUCO - C DUCO - Le DUCO - D DUCO AXIAL

Replaces : MCK1116

Suitable for
Volvo

Replaces
85102094

Suitable for
FH12/16
FM7/9/10/12



Auger No.

54553

Description

Caliper Pin Repair Kit

Type : D DUCO RADIAL

Replaces : MCK1135

Suitable for
Volvo

Replaces
85103891

Suitable for
FH12/16
FM10/12



Auger No.

54556

Description

Caliper Pin Repair Kit

Type : D DUCO RADIAL

Replaces : MCK1118

Suitable for
Volvo

Replaces
85102092

Suitable for
FH12/16
FM7/9/10/12



Auger No.

54554

Description

Caliper Pin Repair Kit

Type : B DUCO - C DUCO - Le DUCO - D DUCO SERIES

Replaces : MCK1299 - MCK1066

Suitable for
Volvo

Replaces
85107718
3095628
3096769

Suitable for
FH12/16
FM7/9/10/12



Auger No.

56016

Description

Caliper Boot & Cap Set

Type : Suitable for ELSA2 SERIES - ELSA195 - ELSA225

Replaces : MCK1088

Suitable for
Man

Replaces
-

Suitable for
F2000



72996
31xø42/30

55369
ø29/24

Auger No.	Description	
56010	Caliper Pin Repair Kit	
Type	: Suitable for ELSA 225 RADIAL - EX225	
Replaces	: MCK1317	
Suitable for	Replaces	Suitable for
Volvo	85109889	FH12/16 FM7/9/10/12

Auger No.	Description	
56049	Caliper Visual Indicator	
Type	: B DUCO - C DUCO - Le DUCO - D DUCO SERIES	
Replaces	: SJ4111	
Suitable for	Replaces	Suitable for
Volvo	3092283	B6/7/9/12 - FL6

Auger No.	Description	
56011	Caliper Visual Indicator	
Type	: Suitable for ELSA225	
Replaces	: MCK1296	
Suitable for	Replaces	Suitable for
Volvo	85109893	FH12/16 FM7/9/10/12
R.V.I.	7485 109 893	Premium / Midlum

Auger No.	Description	
56050	Caliper Visual Indicator	
Type	: Suitable for ELSA2 SERIES	
Replaces	: MCK1240	
Suitable for	Replaces	Suitable for
-	-	-

Auger No.

56082

Description


Brake Pad Retainer Kit

Type : B DUCO

Replaces : MCK1263

Suitable for Volvo Replaces -

Suitable for FL6



Auger No.

56083

Description

Brake Pad Retainer Kit

Type : C DUCO - Le DUCO - D DUCO SERIES

Replaces : MCK1264

Suitable for Volvo Replaces -

Suitable for FH12/16 FM7/9/10/12 FL6



Auger No.

56081

Description

Brake Pad Retainer Kit

Type : Suitable for ELSA 1

Replaces : MCK1262

Suitable for Man Replaces -

Suitable for TGA / Lion's Series



Auger No.

56107

Description


Brake Pad Retainer Kit

Type : Suitable for ELSA2 SERIES - ELSA195 - ELSA225

Replaces : MCK1174

Suitable for Man Replaces -

Suitable for TGA / F2000



Auger No.

54557

Description

Caliper Pin Repair Kit

Type : D2

Replaces : SP8999

Suitable for
R.V.I.

Replaces
5000 821 966

Suitable for
Magnum / Major



Auger No.

55180

Description

Dust Cover & Gasket Kit

Type : D2

Replaces : SJ1018

Suitable for
R.V.I.

Replaces
-

Suitable for
Magnum / Major



Auger No.

57594

Description

Eccentric Shaft Repair Kit

Type : 58 FRONT - 68 FRONT - 58 REAR - 68 REAR

Replaces : SP8570

Suitable for
Volvo

Replaces
-

Suitable for
FL4/6

Iveco

-

EuroCargo



Auger No.

57595

Description

Eccentric Shaft Repair Kit

Type : 60 FRONT - 68 FRONT - 60 REAR - 68 REAR

Replaces : SJ1032

Suitable for
Iveco

Replaces
-

Suitable for
EuroCargo





55342
ø17/ø20/31

Auger No. 54538

Description
Caliper Pin Repair Kit

Type : 60 REAR
Replaces : SJ1034

Suitable for	Replaces	Suitable for
Iveco	93161037 93161473	EuroCargo / EuroFire




55342
ø17/ø20/31

Auger No. 54540

Description
Caliper Pin Repair Kit

Type : 58 FRONT - 68 FRONT - 58 REAR - 68 REAR
Replaces : SP8565

Suitable for	Replaces	Suitable for
Volvo	3090851	FL4/6
Iveco	8124737	EuroCargo
R.V.I.	-	Midliner




55342
ø17/ø20/31

Auger No. 54543

Description
Caliper Pin Repair Kit

Type : 60 FRONT
Replaces : SJ1035 - ST1153

Suitable for	Replaces	Suitable for
Mercedes	000 420 04 76	Sprinter/Vario
Iveco	93161029 93161472	EuroCargo



55342
ø17/ø20/31

Auger No. 54544

Description
Caliper Pin Repair Kit

Type : 60 FRONT
Replaces : SP8902

Suitable for	Replaces	Suitable for
Mercedes	000 421 14 63	Vario
R.V.I.	-	Midliner

55342
ø17/ø20/31

Auger No.
54541

Description
Caliper Pin Repair Kit

Type : 68 REAR
Replaces : SJ1022

Suitable for Iveco	Replaces -	Suitable for EuroCargo
------------------------------	----------------------	----------------------------------

55342
ø17/ø20/31

55360
ø57/ø67/15

Auger No.
54534

Description
Caliper Repair Kit

Type : 68 REAR
Replaces : SP9670

Suitable for Volvo	Replaces 3090940	Suitable for FL6
Iveco	-	EuroCargo

55359
ø47/ø57/15

55342
ø17/ø20/31

Auger No.
54536

Description
Caliper Repair Kit

Type : 58 REAR
Replaces : SP9669

Suitable for Volvo	Replaces 3090939 3090356 271163	Suitable for FL6
------------------------------	---	----------------------------

55362
ø49/ø60/13


55342
ø17/ø20/31

Auger No.
54539

Description
Caliper Repair Kit

Type : 60 REAR
Replaces : SJ1030

Suitable for Iveco	Replaces 93161036	Suitable for EuroCargo / EuroFire
------------------------------	-----------------------------	---



55360
ø57/ø67/15

55342
ø17/ø20/31

Auger No. 55179

Description
Caliper Repair Kit

Type : 68 REAR
Replaces : SJ1033

Suitable for Iveco	Replaces 93161034 93161471	Suitable for EuroCargo
--------------------	-------------------------------	------------------------



55342
ø17/ø20/31


55360
ø57/ø67/15

Auger No. 54537

Description
Caliper Repair Kit

Type : 68 FRONT
Replaces : SP8564 - SP8564 - SP8564

Suitable for Volvo	Replaces 3090937 270527	Suitable for FL6
Iveco	93161552	EuroCargo
R.V.I.	5001 829 895 5001 014 701	Midliner



55342
ø17/ø20/31

55359
ø47/ø57/15

Auger No. 54535

Description
Caliper Repair Kit

Type : 58 FRONT
Replaces : SP8567

Suitable for Volvo	Replaces 3090938 270531	Suitable for FL4/6
--------------------	----------------------------	--------------------



55342
ø17/ø20/31

55362
ø49/ø60/13

Auger No. 54545

Description
Caliper Repair Kit

Type : 60 FRONT
Replaces : SJ1037

Suitable for Iveco	Replaces 93161028	Suitable for EuroCargo / EuroFire
--------------------	-------------------	-----------------------------------



55362
ø49/ø60/13

55342
ø17/ø20/31

Auger No.
54533

Description
Caliper Repair Kit

Type : 60 FRONT
Replaces : SP8597

Suitable for Mercedes	Replaces	Suitable for
-	-	Vario
R.V.I.	5001 014 679 5001 829 892	Midliner



55342
ø17/ø20/31

Auger No.
54542

Description
Caliper Repair Kit

Type : 58 FRONT - 60 FRONT - 68 FRONT - 58 REAR
Replaces : SP8566

Suitable for Mercedes	Replaces	Suitable for
-	-	Vario
Volvo	-	FL4/6
Iveco	-	EuroCargo
R.V.I.	-	Midliner



55342
ø17/ø20/31

Auger No.
55813

Description
Caliper Repair Kit

Type : 58 FRONT - 60 FRONT - 68 FRONT - 58 REAR
Replaces : ST1154

Suitable for Mercedes	Replaces	Suitable for
-	000 421 83 86	Sprinter / Vario

mauger

GERMANY


**Suitable for
BERGISCHE
ACHSEN**




Auger No.	79332		Description
			Caliper Cover Kit, Complete
Type	:-		
Replaces	:-		
Suitable for	Replaces	Suitable for	
Bergische Achsen	-	BPW ECO DISC TSB 3709 BPW ECO DISC TSB 4309 BPW ECO DISC TSB 4312	




Auger No.	79333		Description
			Caliper Cover Kit
Type	:-		
Replaces	:-		
Suitable for	Replaces	Suitable for	
Bergische Achsen	-	BPW ECO DISC TSB 3709 BPW ECO DISC TSB 4309 BPW ECO DISC TSB 4312	



Auger No.	79335		Description
			Caliper Mechanism Bearing House
Type	:-		
Replaces	:-		
Suitable for	Replaces	Suitable for	
Bergische Achsen	-	BPW ECO DISC TSB 3709 BPW ECO DISC TSB 4309 BPW ECO DISC TSB 4312	



Auger No.	79336		Description
			Caliper Calibration Bolt
Type	:-		
Replaces	:-		
Suitable for	Replaces	Suitable for	
Bergische Achsen	-	BPW ECO DISC TSB 3709 BPW ECO DISC TSB 4309 BPW ECO DISC TSB 4312	



Auger No.	79337		Description
			Caliper Mechanism House
Type	:-		
Replaces	:-		
Suitable for	Replaces	Suitable for	
Bergische Achsen	-	BPW ECO DISC TSB 3709 BPW ECO DISC TSB 4309 BPW ECO DISC TSB 4312	

Auger No. **79338** Description
Caliper lever



Type : -
Replaces : -

Suitable for Bergische Achsen Replaces -

Suitable for
BPW ECO DISC TSB 3709
BPW ECO DISC TSB 4309
BPW ECO DISC TSB 4312

Auger No. **80160** Description
Caliper Cap




Type : -
Replaces : -

Suitable for Bergische Achsen Replaces -

Suitable for
BPW ECO DISC TSB 3709
BPW ECO DISC TSB 4309
BPW ECO DISC TSB 4312

Auger No. **79340** Description
Roller Bearing Kit




Type : -
Replaces : -

Suitable for Bergische Achsen Replaces -

Suitable for
BPW ECO DISC TSB 3709
BPW ECO DISC TSB 4309
BPW ECO DISC TSB 4312

Auger No. **79341** Description
Roller Bearing Kit



Type : -
Replaces : -

Suitable for Bergische Achsen Replaces -

Suitable for
BPW ECO DISC TSB 3709
BPW ECO DISC TSB 4309
BPW ECO DISC TSB 4312

Auger No.

80743

Description

Roller Bearing

Type : -

Replaces : -


Suitable for
Bergische
Achsen

Replaces

-

Suitable for

BPW ECO DISC TSB 3709
BPW ECO DISC TSB 4309
BPW ECO DISC TSB 4312



Auger No.

80731

Description

Roller Bearing

Type : -

Replaces : -

Suitable for
Bergische
Achsen

Replaces

-

Suitable for

BPW ECO DISC TSB 3709
BPW ECO DISC TSB 4309
BPW ECO DISC TSB 4312



Auger No.

70656

Description

Caliper Pin Boot & Cap Set

Type : -

Replaces : 09.801.07.62.0


Suitable for
Bergische
Achsen

Replaces

09.801.07.62.0

Suitable for

BPW ECO DISC TSB 3709
BPW ECO DISC TSB 4309
BPW ECO DISC TSB 4312



Auger No.

70657

Description

Caliper Pin Repair Kit

Type : -

Replaces : 09.801.07.61.0

Suitable for
Bergische
Achsen

Replaces

09.801.07.61.0

Suitable for

BPW ECO DISC TSB 3709
BPW ECO DISC TSB 4309
BPW ECO DISC TSB 4312



mauger

GERMANY

OTHER TYPE CALIPERS

Auger No. Description
55810 Caliper Repair Kit



Type : -
Replaces : 001 420 25 83
Suitable for Mercedes Replaces 001 420 25 83 Suitable for Sprinter

Auger No. Description
55815 Caliper Repair Kit



Type : -
Replaces : 001 420 24 83
Suitable for Mercedes Replaces 001 420 24 83 Suitable for Sprinter

Auger No. Description
72137 Caliper Repair Kit



Type : -
Replaces : 42555883
Suitable for Iveco Replaces 42555883 Suitable for Daily IV/V

Auger No. Description
55809 Caliper Repair Kit



Type : -
Replaces : 0025865342
Suitable for Mercedes Replaces 002 586 53 42 Suitable for L Series

Auger No. Description
56089 Caliper Repair Kit



Type : -
Replaces : 0004201444
Suitable for Mercedes Replaces 000 420 14 44 Suitable for L Series

AUGER

GERMANY

SENSOR

Auger No.

70704

Description

Pad Wear Indicator,
Front Left and Right



Type : -

Replaces : -

Suitable for
Man

Replaces
81.25937.6039
81.25937.6015

Suitable for
TGA

Ror-Meritor -

Elsa2 Series
Elsa195
Elsa225

Auger No.

70705

Description

Pad Wear Indicator
Rear Left



Type : -

Replaces : 81.25937.6041 - 81.25937.6017 - 81.25937.6010

Suitable for
Man

Replaces
81.25937.6041
81.25937.6017
81.25937.6010

Suitable for
TGA

Ror-Meritor -

Elsa2 Series
Elsa195
Elsa225

Auger No.

70706

Description

Pad Wear Indicator
Rear Right



Type : -

Replaces : -

Suitable for
Man

Replaces
81.25937.6044
81.25937.6022
81.25937.6018

Suitable for
TGA

Ror-Meritor -

Elsa2 Series
Elsa195
Elsa225

Auger No.

76946

Description

Pad Wear Indicator



Type : -

Replaces : -

Suitable for
Man

Replaces
81.25937.6038
81.25937.6013

Suitable for
Lion's City / Centroliner

Auger No. Description
76947 Pad Wear Indicator



Type : -
Replaces : -
Suitable for Man Replaces 81.25937.6046
81.25937.6028 Suitable for Lion's City Centroliner

Auger No. Description
76948 Pad Wear Indicator



Type : -
Replaces : -
Suitable for Man Replaces 81.25937.6040
81.25937.6019
81.25937.6009 Suitable for TGA / Lion's City Centroliner

Auger No. Description
70707 Pad Wear Indicator, Front



Type : -
Replaces : -
Suitable for Volvo Replaces 20928533
20442608
20392985
3986607 Suitable for FH12/16
FM7/9/10/12
Ror-Meritor - Elsa2 Series
Elsa195
Elsa225

Auger No. Description
70708 Pad Wear Indicator, Rear



Type : -
Replaces : 20928532 - 20442607
Suitable for Volvo Replaces 20928532
20442607 Suitable for FH12/16
FM9/12
Ror-Meritor - Elsa2 Series
Elsa195
Elsa225

Auger No. Description
74450 Pad Wear Indicator



Type : -
Replaces : -

Suitable for	Replaces	Suitable for
Volvo	20928541 20526767	FH12/16 - FM9/12

Ror-Meritor - -

Auger No. Description
74455 Pad Wear Indicator, Left




Type : -
Replaces : -

Suitable for	Replaces	Suitable for
Volvo	21390373 20928537	FH12/16 FM7/9/10/12

Ror-Meritor - -

Auger No. Description
74454 Pad Wear Indicator, Right



Type : -
Replaces : -

Suitable for	Replaces	Suitable for
Volvo	21390372 20928536	FH12/16 FM7/9/10/12

Ror-Meritor - -

Auger No. Description
74453 Pad Wear Indicator, Left



Type : -
Replaces : -

Suitable for	Replaces	Suitable for
Volvo	21390376 20928545 20534389	FH12/16 FM7/9/10/12

Ror-Meritor - -



Auger No.
74451

Description
Pad Wear Indicator, Right

Type : -
Replaces : -

Suitable for Volvo	Replaces 21390374 20928539	Suitable for FH12/16 FM7/9/10/12
Ror-Meritor	-	-




Auger No.
74452

Description
Pad Wear Indicator, Right

Type : -
Replaces : -

Suitable for Volvo	Replaces 21390375 20928544	Suitable for FH12/16 FM7/9/10/12
Ror-Meritor	-	-



Auger No.
74457

Description
Pad Wear Indicator, Left

Type : -
Replaces : -

Suitable for Volvo	Replaces 20928548 20554517	Suitable for FH12/16 FM7/9/10/12
Ror-Meritor	-	-



Auger No.
74456

Description
Pad Wear Indicator, Right

Type : -
Replaces : 20928547 - 20554506

Suitable for Volvo	Replaces -	Suitable for FH12/16 FM7/9/10/12
Ror-Meritor	-	-

Auger No.

74459

Description

Pad Wear Indicator, Left



Type : -

Replaces : -

Suitable for
Volvo

Replaces
20928564

Suitable for
FH12/16
FM7/9/10/12

Auger No.

74458

Description

Pad Wear Indicator, Right



Type : -

Replaces : -

Suitable for
Volvo

Replaces
20928563

Suitable for
FH12/16
FM7/9/10/12

Auger No.

70711

Description

Pad Wear Indicator, Front Left



Type : -

Replaces : -

Suitable for
R.V.I.

Replaces
5001 856 031

Suitable for
Premium

Ror-Meritor

-

Elsa2 Series
Elsa195
Elsa225

Auger No.

70709

Description

Pad Wear Indicator, Front Right



Type : -

Replaces : -

Suitable for
R.V.I.

Replaces
5001 856 032

Suitable for
Premium

Ror-Meritor

-

Elsa2 Series
Elsa195
Elsa225



Auger No.
70712

Description
Pad Wear Indicator, Rear Left

Type : -
Replaces : -

Suitable for R.V.I.	Replaces 5001 856 033	Suitable for Premium / Magnum
Ror-Meritor	-	Elsa2 Series Elsa195 Elsa225



Auger No.
70710

Description
Pad Wear Indicator, Rear Right

Type : -
Replaces : -

Suitable for R.V.I.	Replaces 5001 856 034	Suitable for Premium / Magnum
Ror-Meritor	-	Elsa2 Series Elsa195 Elsa225




Auger No.
70715

Description
Pad Wear Indicator, Front Left

Type : -
Replaces : -

Suitable for R.V.I.	Replaces 7420 928 559	Suitable for Premium DXI / Premium
Ror-Meritor	-	Elsa2 Series Elsa195 Elsa225



Auger No.
70713

Description
Pad Wear Indicator, Front Right

Type : -
Replaces : -

Suitable for R.V.I.	Replaces 7420 928 560	Suitable for Premium DXI / Premium
Ror-Meritor	-	Elsa2 Series Elsa195 Elsa225

Auger No.

70716

Description

Pad Wear Indicator, Rear Left



Type : -

Replaces : -

Suitable for
R.V.I.

Replaces
7420 928 552

Suitable for
Premium DXI
Premium / Magnum

Ror-Meritor

-

Elsa2 Series
Elsa195
Elsa225

Auger No.

70714

Description

Pad Wear Indicator, Rear Right



Type : -

Replaces : -

Suitable for
R.V.I.

Replaces
7420 928 553

Suitable for
Premium DXI
Premium / Magnum

Ror-Meritor

-

Elsa2 Series
Elsa195
Elsa225