



CALIPER 2018



Independent Aftermarket Company

FOR EUROPEAN COMMERCIAL VEHICLES



NOTE: All previous editions are no longer valid after new published catalogue.

Products sold by AUGER are not original parts but they are interchangeable with them and they are sold under our brand.

All original equipment manufacturers (OEM) numbers, symbols and descriptions are used for identifications purpose only. They will not be used in delivery notes or invoice to our customers.

We cannot accept any responsibility for errors which may occur from the printing etc. This catalogue is not permitted to be reprinted or duplicated even partially without our prior written permission.

We reserve the right to make technical changes and design modifications.

The information provided in this catalogue has been researched and prepared with utmost care. However specifications, descriptions and illustrative material contained herein are subject to possible changes without notice. We do not accept liability for any errors in this issue.

AUGER frequently updates and improves its products. AUGER may discontinue to offer or modify its products at any time. Please consult your AUGER country representative for specific product information.

The brand AUGER® is a registered and protected trademark.
Registration numbers are; CTM 14965834, M 2014 00939, DE 302014055048

Explanation of the used terms in this catalogue;

Replaces: The spare part which shown is a product of AUGER® brand, it can be used instead of the original spare part of the vehicle manufacturer.

Replaces No with "S" letter: The spare part which shown is differs from the original spare part or repair kit but it is still interchangeable with them. Please pay attention product descriptions or ask your country representative for these differences.

Suitable for: The spare part which shown is suitable for the listed vehicles, models, product types etc.

Thank you for choosing AUGER products.

CALIPER

Article Groups


SUITABLE FOR KNORR	1 - 46
SUITABLE FOR ROR-MERITOR	49 - 82
SUITABLE FOR WABCO	85 - 96
SUITABLE FOR HALDEX	99 - 110
SUITABLE FOR BPW	113 - 114
SUITABLE FOR BREMBO	117
OTHER TYPE	121
SENSOR	125 - 131

Independent Aftermarket Company

FOR EUROPEAN COMMERCIAL VEHICLES

iamauger.com





BEST QUALITY PRODUCT RANGE

We would like to provide you the best quality spare parts for each brand across the world in the Independent Aftermarket. Therefore, we have shaped the operations within the company according to this basis prudentially. Several different kinds of modern control and audit systems have been testing all of our products. As well as the quality of material, we also pay special attention on mounting reliability. In this sense, you can get from Auger many parts of which you may not even find any alternatives in the aftermarket. We have been improving the quality of our products constantly by the help of Technical Inspections Organization (TUV).



mauger
GERMANY


Suitable for
KNORR



81467

Adjusting Mechanism Shaft

Type : SB5
Replaces : -



57175

Adjusting Mechanism Shaft

Type : SN5
Replaces : -



56138

Adjusting Mechanism Shaft Kit

Type : SB5
Replaces : -



57162

Pinion Shaft

Type : SB6 - SB7 - SB7 RADIAL - SN6 - SN7 - SK7 - ST7
Replaces : -



57163

Adjusting Mechanism Shaft

Type : SB6 - SB7 - SB7 RADIAL - SN6 - SN7 - ST7 - SK7 - SL7 - SM7
Replaces : -



81483

Adjusting Mechanism Shaft Kit

Type : SB6 - SB7 - SB7 RADIAL - SN6 - SN7 - SK7 - ST7
Replaces : -




76974 Pinion Shaft
 Type : SB6 - SB7 - SN6 - SN7 - SK7 - ST7
 Replaces : -



81466 Pinion Shaft
 Type : SB6 - SB7 - SN6 - SN7 - SK7 - ST7
 Replaces : -



76973 Pinion Shaft
 Type : SL7 - SM7
 Replaces : -



70826 Pinion Shaft
 Type : SB5
 Replaces : -



57176 Pinion Shaft
 Type : SN5
 Replaces : -



57177 Caliper Mechanism Gear
 Type : ALL MODELS
 Replaces : -




56007 Calliper Mechanism Chain
 12 Links
 Type : SB5
 Replaces : -



81468 Calliper Mechanism Chain
 14 Links
 Type : SN5
 Replaces : -



57182 Calliper Mechanism Chain
 29 Links
 Type : SB6 - SB7 - SB7 RADIAL - SN6
 SN7 - ST7 - SK7 - SL7 - SM7
 Replaces : -



81463

Caliper Lever

Type : SB5
Replaces : -



81464

Caliper Lever

Type : SN5
Replaces : -



57179

Caliper Lever (0° - 114 mm)


Type : SB6 - SB7
Replaces : C73158



77434

Caliper Lever (0° - 127 mm)

Type : SB6 - SB7
Replaces : -



77433

Caliper Lever (12° - 123 mm)

Type : SB6 - SB7
Replaces : -



57181

Caliper Lever (12° - 126 mm)

Type : SB6 - SB7
Replaces : C73164



57178

Caliper Lever (0° - 113 mm)

Type : SN6 - SN7 - SK7 - ST7
Replaces : -



76975

Caliper Lever (0° - 113 mm),
57178's With Roller

Type : SN6 - SN7 - SK7
Replaces : Z002881



57180

Caliper Lever (0° - 125 mm)

Type : SN6 - SN7
Replaces : -



79277

Caliper Lever (0° - 125 mm),
57180's With Roller

Type : SN6 - SN7 - SK7 - ST7
Replaces : -



77435

Caliper Lever (12° - 123 mm)


Type : SN6 - SN7
Replaces : Z002962



79276

Caliper Lever (12° - 123 mm),
77435's With Roller

Type : SN7 - SK7
Replaces : -



79386

Caliper Lever


Type : SL7 - SM7
Replaces : Z033222



79387

Caliper Lever


Type : SB7 RADIAL
Replaces : -



81465

Caliper Lever


Type : SB7 RADIAL
Replaces : -



56133

Roller Bearing Kit, One Side Claw


Type : SB5 - SB6 - SB7 - SB7 RADIAL
Replaces : -



56134

Roller Bearing Kit, Both Sides of the Claw

Type : SN6 - SN7 - SK7 - ST7
Replaces : -



79388

Roller Bearing Kit

Type : SL7 - SM7
Replaces : -



81484

Roller Bearing Kit

Type : SN5
Replaces : -



81485

Caliper Bridge Assembly

Type : SB5
Replaces : -



81624

Caliper Bridge Assembly

Type : SB5
Replaces : -



81486

Caliper Bridge Assembly

Type : SN5
Replaces : -



81625

Caliper Bridge Assembly

Type : SN5
Replaces : -



57166

Caliper Bridge

Type : SB6 - SB7 - SB7 RADIAL
Replaces : -



56155

Caliper Bridge Assembly

Type : SB6 - SB7 - SB7 RADIAL
Replaces : -



56156

Caliper Bridge Assembly

Type : SB6 - SB7 - SB7 RADIAL
Replaces : -



57601

Caliper Bridge Assembly

Type : SB6 - SB7 - SB7 RADIAL
Replaces : -



57165

Caliper Bridge

Type : SN6 - SN7 - SK7 - ST7
Replaces : -



56153

Caliper Bridge Assembly

Type : SN6 - SN7 - SK7 - ST7
Replaces : -



56154

Caliper Bridge Assembly

Type : SN6 - SN7 - SK7 - ST7
Replaces : -



57580

Caliper Bridge Assembly

Type : SN6 - SN7 - SK7 - ST7
Replaces : -



57164
M36x6 P3/131x63,5

56008
13,5 mm

56152 Caliper Bridge Assembly

Type : SN6 - SN7 - SK7 - ST7
Replaces : -



57164
M36x6 P3/131x63,5

56008
13,5 mm

57579 Caliper Bridge Assembly

Type : SN6 - SN7 - SK7 - ST7
Replaces : -



57164
M36x6 P3/131x63,5

79278
9,5 mm

79279 Caliper Bridge Assembly

Type : SL7 - SM7
Replaces : -



57164
M36x6 P3/131x63,5

56151 Caliper Bridge Assembly

Type : SN6 - SN7 - SK7 - ST7 - SL7 - SM7
Replaces : -



57164 Caliper Bridge

Type : SN6 - SN7 - SK7 - ST7 - SL7 - SM7
Replaces : -



13,5 mm

56008 Caliper Calibration Bolt

Type : SB5 - SN5 - SB6 - SB7 - SB7 RADIAL
SN6 - SN7 - SK7 - ST7
Replaces : -



9,5 mm

79278 Caliper Calibration Bolt

Type : SL7 - SM7
Replaces : -



81667

Caliper Sensor Cover (Without Sensor)

Type : SN5
Replaces : -



81666

Caliper Sensor Cover (2 Cable)

Type : SN5
Replaces : -



81664

Caliper Sensor Cover (3 Cable) (Mercedes)

Type : SN5
Replaces : -



81665

Caliper Sensor Cover (3 Cable) (Man)

Type : SN5
Replaces : -



81614

Caliper Sensor Cover (Without Sensor)

Type : SB5
Replaces : -



81613

Caliper Sensor Cover (2 Cable)

Type : SB5
Replaces : -



81611

Caliper Sensor Cover (3 Cable) (Mercedes)

Type : SB5
Replaces : -



81612

Caliper Sensor Cover (3 Cable) (Man)

Type : SB5
Replaces : -



81618

Caliper Sensor Cover (Without Sensor)

Type : SB7 RADIAL
Replaces : -



81617

Caliper Sensor Cover (2 Cable)

Type : SB7 RADIAL
Replaces : -



81615

Caliper Sensor Cover (3 Cable) (Mercedes)

Type : SB7 RADIAL
Replaces : -



81616

Caliper Sensor Cover (3 Cable) (Man)

Type : SB7 RADIAL
Replaces : -



81622

Caliper Sensor Cover
(Without sensor, W/Clip)

Type : SB7 RADIAL
Replaces : -



81621

Caliper Sensor Cover (2 Cable, W/Clip)

Type : SB7 RADIAL
Replaces : -



81619

Caliper Sensor Cover (3 Cable, W/Clip)
(Mercedes)

Type : SB7 RADIAL
Replaces : -



81620

Caliper Sensor Cover (3 Cable, W/Clip)
(Man)

Type : SB7 RADIAL
Replaces : -



79175 Caliper Sensor Cover (Without Sensor)

Type : SB6 - SB7 - SN6 - SN7 - SK7 - ST7 - SL7 - SM7



79149 Caliper Sensor Cover (2 Cable)

Type : SB6 - SB7 - SN6 - SN7 - SK7 - ST7 - SL7 - SM7



57183 Caliper Sensor Cover (3 Cable) (Mercedes)

Type : SB6 - SB7 - SN6 - SN7 - SK7 - ST7 - SL7 - SM7



81218 Caliper Sensor Cover (3 Cable) (Man)

Type : SB6 - SB7 - SN6 - SN7 - SK7 - ST7 - SL7 - SM7



81610 Caliper Sensor Cover (Without sensor, W/Clip)

Type : SB6 - SB7 - SN6 - SN7 - SK7 - ST7



81609 Caliper Sensor Cover (2 Cable, W/Clip)

Type : SB6 - SB7 - SN6 - SN7 - SK7 - ST7



81219 Caliper Sensor Cover (3 Cable, W/Clip) (Scania)

Type : SB6 - SB7 - SN6 - SN7 - SK7 - ST7



81623 Caliper Cover Kit

Type : SN5



56130 Caliper Cover Kit

Type : SN6 - SN7 - SK7 - ST7



76978 Caliper Cover Kit

Type : SN6 - SN7 - SK7 - ST7 - SL7 - SM7



55348
ø69,3

72998
ø16xø18x10

79039 Tappet Kit

Type : SN6 - SN7 - SK7 - ST7
Replaces : -



55348
ø69,3

72998
ø16xø18x10

76385 Tappet Kit

Type : SN6 - SN7 - SK7 - ST7
Replaces : -



55348
ø69,3

72998
ø16xø18x10

55373

53881 Tappet Kit, Old Type Dust Cover

Type : SN6 - SN7 - SK7 - ST7
Replaces : K001300

Suitable for	Replaces	Suitable for
Man	81.50822.6020	TGA / TGS / TGM / TGX / LION'S
Iveco	42541413	Stralis / EuroRider / EuroStar EuroTech / EuroTrakker / Irisbus



55348
ø69,3

72998
ø16xø18x10

55370

54167 Tappet Kit, New Type Dust Cover

Type : SN6 - SN7 - SK7 - ST7
Replaces : K010603 - K000366

Suitable for	Replaces	Suitable for
Mercedes	000 420 49 82 000 420 40 82 000 420 23 82	Actros 2/3
Man	81.50822.6031	TGA / TGS / TGM / TGX / F 2000 / LION'S
Scania	1756389 1743421	4 Series Truck / PGRT Series Truck / 4 Series Bus / FKN Series Bus
Daf	1689313 1622785	XF105/95 / CF65/75/85 / LF55
Bpw	09.801.06.32.0	SH...LL Series (SB 4309 / SB 4345) SKH Series (SB 3745)
Saf	3 434 3814 00	SKRB 9019 K (SN 6) / SKRB 9022 K 01 (SK 7) SKRS 9019 K (SN 6) / SKRS 9022 K (SN 7) SKRZ 11019 K (SN 6) / SKRZ 9022 K (SN 7) SKRZ 11222 K (SN 7) / B9-19K / B9-22K01 B9-19K / B9-22K01 / S9-19K / S11-22K01 Z9-22K01 / Z11-19K / Z11-22K01
Schmitz	1008451	-

54523

Tappet Kit



Type : SN5

Replaces : K097826K50 - K001929

Suitable for	Replaces	Suitable for
Mercedes	000 420 42 82	Atego / Atego 2/3 / Axor 2 Accelo / Actros 2/3
Man	81.50822.6027	TGL



79280

Tappet Kit, Old Type Dust Cover

Type : SN5
Replaces : -

Suitable for	Replaces	Suitable for
Man	-	TGL



77447

Tappet Kit, New Type

Type : SL7 - SM7
Replaces : K046523K50

Suitable for	Replaces	Suitable for
Mercedes	000 423 03 16	Actros / Axor / Axor 2 / Antos / Aros



56023

Tappet Kit

Type : SB5 - SB6 - SB7 - SB7 RADIAL
Replaces : II370760065

Suitable for	Replaces	Suitable for
Mercedes	000 420 13 82	Atego / Atego2 / Accelo



56055

Tappet Kit, New Type Dust Cover

Type : SB6 - SB7 - SB7 RADIAL
Replaces : K010606

53878

Tappet Kit



Type : SB6 - SB7 - SB7 RADIAL
Replaces : II304130065 - II179320065

Suitable for	Replaces	Suitable for
Man	81.50822.6007	M 2000 / LION'S COACH
Daf	1448913 1623221	XF105/95 / CF65/75/85 / LF45/55

79379 Tappet Kit, Old Type Dust Cover

Type : SB5 - SB6 - SB7 - SB7 RADIAL
Replaces : -

54178 Tappet Kit, Old Type Dust Cover

Type : SB6 - SB7 - SB7 RADIAL
Replaces : K000944

54168 Tappet Kit, New Type Dust Cover

Type : SB6 - SB7 - SB7 RADIAL
Replaces : K010604

Suitable for	Replaces	Suitable for
Mercedes	000 420 48 82 000 420 39 82 000 420 06 82	Citaro
Man	81.50822.6022 81.50822.6032	TGA / M 2000 / LION'S CITY
Scania	1759811 1746824 1390429	4 Series Truck / PGRT Series Truck 4 Series Bus / FKN Series Bus
Daf	1690420	XF105/95 / CF65/75/85 / LF55
Iveco	42553530 42541341 93162050	EuroCargo / EuroMover / EuroStar EuroTech / EuroTrakker / Irisbus
Saf	3 434 3804 00	SBK 1937-11 S / SBK 2243-11 S
Bpw	09.801.02.63.0	SH...LL Series (SB 4309 / SB 4345) SKH Series (SB 3745)



81469

Calliper Cap

Type : SN6 - SN7 - SK7
Replaces : Z003360



81470

Calliper Cap

Type : SN6 - SN7 - SK7
Replaces : -



57167

Calliper Cap

Type : SN5 - SN6 - SN7 - SK7 - ST7 - SL7 - SM7
Replaces : -



73198

Calliper Cap

Type : SB5 - SB6 - SB7 - SB7 RADIAL
Replaces : -



81471

Rubber Bush Cap (Short)


Type : SB5 - SB6 - SB7 - SB7 RADIAL - SN6 - SN7 SK7 - SL7 - SM7
Replaces : -



81472

Rubber Bush Cap (Long)

Type : SB5 - SB6 - SB7 - SB7 RADIAL - SN6 - SN7 SK7 - SL7 - SM7
Replaces : -



54072

Caliper Pin Cap Set


Type : SB5 - SB6 - SB7 - SB7 RADIAL
 Replaces : K001301
 Suitable for Man 81.50822.6025 Daf 1439494
 Replaces TGA / M 2000 / LION'S CITY
 Suitable for -



73597

Caliper Pin Cap Set


Type : SB5 - SB6 - SB7 - SB7 RADIAL
 Replaces : II350470063
 Suitable for Bpw 09.801.02.58.0
 Replaces SH Series (SB 3745)
 Suitable for SKH Series (SB 3745) SH Series (SB 4345)
 Saf 3 434 3803 00 -



53879

Caliper Pin Cap Set

Type : SB5 - SB6 - SB7 - SB7 RADIAL
 Replaces : II39769F0063
 Suitable for Saf 3 434 3806 00
 Replaces SBK 1937-11 S / SBK 2243-11 S
 Suitable for -



56066

Caliper Pin Boot & Cap Set

Type : SB5 - SB6 - SB7 - SB7 RADIAL
 Replaces : -
 Suitable for Bpw 09.801.06.11.0
 Replaces SH..LL Series (SB 4309 / SB 4345)
 Suitable for SKH Series (SB 3745)



79234

Caliper Pin Boot Set

Type : SB5 - SN5 - SB6 - SB7 - SB7 RADIAL - SN6 - SN7 - SK7 - ST7 - SL7 - SM7
 Replaces : -
 Suitable for Bpw -
 Replaces SH..LL Series (SB 4309 / SB 4345)
 Suitable for SKH Series (SB 3745)




56065

Caliper Pin Boot & Cap Set

Type : SB5 - SN5 - SB6 - SB7 - SB7 RADIAL - SN6 - SN7 - SK7 - ST7 - SL7 - SM7
 Replaces : -
 Suitable for Bpw 09.801.06.34.0
 Replaces SH..LL Series (SB 4309 / SB 4345)
 Suitable for SKH Series (SB 3745)

53875

Caliper Short Bush Repair Kit



Type : SB5 - SB6 - SB7 - SB7 RADIAL

Replaces : II368470064

Suitable for	Replaces	Suitable for
Daf	1448910	XF105/95 95XF CF65/75/85 LF45/55
Saf	3 434 3801 00	SBK 1937-11 S SBK 2243-11 S




79235

Caliper Short Bush Repair Kit

Type : SB5 - SB6 - SB7 - SB7 RADIAL

Replaces : -



56022

Caliper Long Bush Repair Kit

Type : SB7 - SB7 RADIAL

Replaces : II339830064



76380

Caliper Pin Rubber Bush (Short)

Type : SB6 - SB7 - SB7 RADIAL - SN6 - SN7 - ST7 - SK7 - SL7 - SM7

Replaces : -

Suitable for	Replaces	Suitable for
Mercedes	-	Atego Atego 2 Atego 3
Man	-	TGA / TGS TGM / TGX F 2000 / LION'S
Scania	-	4 Series Truck PGRT Series Truck 4 Series Bus FKN Series Bus
Daf	-	XF105/95 / CF65/75/85 / LF45/55

76379

Caliper Pin Rubber Bush (Short)




Type : SB6 - SB7 - SB7 RADIAL - SN6 - SN7 - ST7 - SK7 - SL7 - SM7
Replaces : -

Suitable for	Replaces	Suitable for
Mercedes	-	Atego / Atego 2 / Atego 3
Man	-	TGA / TGS / TGM TGX / F 2000 / LION'S
Scania	-	4 Series Truck PGRT Series Truck 4 Series Bus FKN Series Bus
Daf	-	XF105/95 CF65/75/85 LF45/55

76378

Caliper Pin Rubber Bush (Short)



Type : SB6 - SB7 - SB7 RADIAL - SN6 - SN7 - ST7 - SK7 - SL7 - SM7
Replaces : -

Suitable for	Replaces	Suitable for
Mercedes	-	Atego / Atego 2 / Atego 3
Man	-	TGA / TGS TGM / TGX F 2000 / LION'S
Scania	-	4 Series Truck PGRT Series Truck 4 Series Bus FKN Series Bus
Daf	-	XF105/95 CF65/75/85 LF45/55

76383

Caliper Pin Rubber Bush (Long)



Type : SB5 - SB6 - SB7 - SN6 - SN7 - SK7 - SL7 - SM7
Replaces : -

Suitable for	Replaces	Suitable for
Mercedes	-	Actros / Atego 2 / Touro / Multigo Tourismo
Man	-	TGA / TGS / TGM / TGX / F 2000 / LION'S
Scania	-	4 Series Truck / PGRT Series Truck / 4 Series Bus / FKN Series Bus
Daf	-	XF105/95 / CF65/75/85 / LF55
Iveco	-	Stralis / EuroStar / EuroTech / EuroTrakker / Irisbus
Bpw	02.1410.21.00	SKH Series (SB 3745) SH Series (SB 4345) SKH..LL Series (SB 3745) SH..LL Series (SB 4309 / SB 4345)
Saf	-	SKRB 9019 K (SN 6) SKRB 9022 K (SN 7) SKRS 9019 K (SN 6) SKRS 9022 K (SN 7) SKRZ 9019 K (SN 6) SKRZ 11019 K (SN 6)

76381

Caliper Pin Rubber Bush (Long)



Type : SB5 - SB6 - SB7 - SN6 - SN7 - SK7 - SL7 - SM7

Replaces : -

Suitable for	Replaces	Suitable for
Mercedes	-	Actros / Atego 2 / Touro / Multitego Turismo
Man	-	TGA / TGS / TGM / TGX / F 2000 LION'S
Scania	-	4 Series Truck / PGRT Series Truck / 4 Series Bus / FKN Series Bus
Daf	-	XF105/95 / CF65/75/85 / LF55
Iveco	-	Stralis / EuroStar / EuroTech / EuroTrakker / Irisbus
Bpw	-	SKH Series (SB 3745) SH Series (SB 4345) SKH..LL Series (SB 3745) SH..LL Series (SB 4309 / SB 4345)
Saf	-	SKRB 9019 K (SN 6) SKRB 9022 K (SN 7) SKRS 9019 K (SN 6) SKRS 9022 K (SN 7) SKRZ 9019 K (SN 6) SKRZ 11019 K (SN 6)

76384

Caliper Pin Rubber Bush (Long)




Type : SB5 - SB6 - SB7

Replaces : -

Suitable for	Replaces	Suitable for
Mercedes	-	Actros
Scania	-	4 Series Truck / PGRT Series Truck / 4 Series Bus / FKN Series Bus
Bpw	02.1410.22.00	SH..LL Series (SB 4309 / SB 4345) SKH Series (SB 3745)
Saf	-	SKRB 9019 K (SN 6) SKRB 9022 K (SN 7) SKRS 9019 K (SN 6) SKRS 9022 K (SN 7) SKRZ 9019 K (SN 6) SKRZ 11019 K (SN 6) SKRZ 9022 K (SN 7) SKRZ 11222 K (SN 7) B9-19K / B19-19K / S19-19K / Z11-19K

76382

Caliper Pin Rubber Bush (Long)



Type : SB5 - SB6 - SB7

Replaces : -

Suitable for	Replaces	Suitable for
Mercedes	-	Actros
Scania	-	4 Series Truck / PGRT Series Truck / 4 Series Bus / FKN Series Bus
Bpw	-	SKH Series (SB 3745) SH Series (SB 4345) SKH..LL Series (SB 3745) SH..LL Series (SB 4309 / SB 4345)
Saf	-	SKRB 9019 K (SN 6) SKRB 9022 K (SN 7) SKRS 9019 K (SN 6) SKRS 9022 K (SN 7) SKRZ 9019 K (SN 6) SKRZ 11019 K (SN 6) SKRZ 9022 K (SN 7) SKRZ 11222 K (SN 7) B9-19K / B19-19K / S19-19K / Z11-19K

70833

Caliper Pin Rubber Bush (Long)



Type : SB5 - SB6 - SB7
Replaces : K000697

Suitable for Bpw	Replaces 09.801.06.91.0	Suitable for BPW ECO Disc TSB 3709 BPW ECO Disc TSB 3745 BPW ECO Disc TSB 4309 BPW ECO Disc TSB 4345
------------------	-------------------------	--

70835

Caliper Pin Rubber Bush (Long)



Type : SB5 - SB6 - SB7
Replaces : -

Suitable for Bpw	Replaces 09.801.06.90.0	Suitable for BPW ECO Disc TSB 3709 BPW ECO Disc TSB 3745 BPW ECO Disc TSB 4345
------------------	-------------------------	---

56057


Caliper Pin Rubber Bush (Long)



Type : SB5 - SB6 - SB7
Replaces : K000421

53876

Caliper Pin Repair Kit



Type : SB6 - SB7 - SB7 RADIAL
Replaces : K000696 - K004218 - I1310370066

Suitable for Mercedes	Replaces 002 420 03 83	Suitable for Actros / Atego / Axor 2
Scania	1527631	4 Series Truck / PGRT Series Truck
	1477675	4 Series Bus / FKN Series Bus
Saf	3 434 3805 00	SBK 1937-11 S / SBK 2243-11 S

56113 Caliper Pin Rubber Bush (Long)

Type : SB5 - SN5 - SB6 - SB7 - SN6 - SN7 - SK7

Replaces : -

81220 Caliper Pin Repair Kit

Type : SB7 - SB7 RADIAL - SN6 - SN7 - SK7

Replaces : -

54685 Caliper Pin Repair Kit

Type : SB5 - SB6 - SB7 - SB7 RADIAL

Replaces : K000935

Suitable for Saf : Replaces 3 434 3802 00 Suitable for -

56054 Caliper Pin Repair Kit

Type : SB7 - SB7 RADIAL

Replaces : K010813

Suitable for Man : Replaces 81.50822.6033 Suitable for LION'S CITY / CENTROLINER

54526 Caliper Pin Repair Kit

Type : SN7 - SK7

Replaces : K004100 - K010766

Suitable for Mercedes : Replaces 000 420 56 82 000 420 50 82 Suitable for Actros 2/3 / Steermaster / Airmaster

Saf : Replaces 3 434 3815 00 Suitable for SK RB 9022 / B9-22K01 / BA9-22K01 B19-22K01 / S19-22K01 / S111-22K01 Z19-22K01 / Z111-22K01 / BL9-22K01 B1L9-22K01 / SIL9-22K01 / SIL11-22K01



54524

Caliper Pin Repair Kit

Type : SN5
 Replaces : K001928
 Suitable for Mercedes 000 420 41 82
 Man 81.50822.6026
 Replaces 55311
 Suitable for Atego / Atego 2/3
 TGL



53882

Caliper Pin Repair Kit

Type : SB7 - SB7 RADIAL
 Replaces : II358510062
 Suitable for Mercedes 1415149
 Scania 1415154
 Replaces 55309
 Suitable for 4 Series Truck / 4 Series Bus
 FKN Series Bus



53885

Caliper Pin Repair Kit

Type : SB7 - SB7 RADIAL
 Replaces : II179320062
 Suitable for Mercedes 050 121 01 67
 Replaces 55309
 Suitable for O300 / O400 / O500



53884

Caliper Pin Repair Kit

Type : SB6 - SB7 - SB7 RADIAL
 Replaces : II197140062



53890

Caliper Pin Repair Kit

Type : SB5 - SB6 - SB7 - SB7 RADIAL
 Replaces : II339680062 - II328090062 - II369100062 - II328090061
 Suitable for Mercedes 000 420 12 82
 Man 81.50822.6009
 Scania 1390427
 Daf 1448915
 Iveco 93162048
 Neoplan 1101 5565
 Replaces 55306
 Suitable for Atego / Atego2
 M 2000 / LION'S COACH
 4 Series Bus
 XF105/95 / CF65/75/85 / LF55
 Euro rider



54522

Caliper Pin Repair Kit

Type : SB6 - SB7 - SB7 RADIAL
Replaces : II39769F0062

Suitable for Replaces Suitable for
Iveco 42537451 EuroCargo / EuroStar
EuroTech / Irisbus



53886

Caliper Pin Repair Kit

Type : SB6 - SB7
Replaces : II197330062 - II304130062

Suitable for Replaces Suitable for
Scania 1390426 4 Series Bus



54686

Caliper Pin Repair Kit

Type : SB6 - SB7 - SB7 RADIAL
Replaces : K000132 - II350470062

Suitable for Replaces Suitable for
Mercedes 000 420 21 82 Atego / Atego2
Scania 1798063 4 Series Truck / 4 Series Bus



54070

Caliper Pin Repair Kit

Type : SN6
Replaces : K001925

Suitable for Replaces Suitable for
Mercedes 000 420 43 82 Atego / Atego 2 / Atego 3



70834

Caliper Pin Repair Kit

Type : SN6
Replaces : K028451



71448

Caliper Pin Repair Kit

Type : SB6 - SB7 - SB7 RADIAL
Replaces : K048396K50




78333

Caliper Pin Repair Kit

Type : SB6 - SB7 - SB7 RADIAL
Replaces : K048371K50

Suitable for	Replaces	Suitable for
Man	81.50822.6036	TGA



71447

Caliper Pin Repair Kit

Type : SN6 - SN7 - SL7 - SM7
Replaces : K099604K50 - K048389K50 - K001915

Suitable for	Replaces	Suitable for
Man	81.50822.6037	TGA / TGS / TGM / TGX / F 2000 / LIONS
Daf	1847716	



70359

Caliper Pin Repair Kit

Type : SB6 - SB7
Replaces : K000698 - K048434K55

Suitable for	Replaces	Suitable for
Scania	2021750 1906776 1477678	4 Series Truck PGRT Series Truck 4 Series Bus FKN Series Bus



53877

Caliper Pin Repair Kit

Type : SB7
Replaces : K000687

Suitable for	Replaces	Suitable for
Daf	1603326	XF105/95 CF65/75/85 LF45/55



56056 Caliper Pin Repair Kit

Type : SN6
Replaces : K002716

72708 $\varnothing 36 \times 102$
60373 $\varnothing 32 \times 80$
55331
55306 M16x1,5/86,5
55307 M16x1,5/80
60353
73001 $\varnothing 36 \times \varnothing 40 \times 75$
55376 $\varnothing 32 \times \varnothing 40 \times 64$
72805 $\varnothing 39$
60481
72669
72869 $\varnothing 40 \times 10,5$



53887 Caliper Pin Repair Kit

Type : SB5
Replaces : K001274

72708 $\varnothing 36 \times 102$
60373 $\varnothing 32 \times 80$
55331
55306 M16x1,5/86,5
55307 M16x1,5/80
60353
72999 $\varnothing 36 \times \varnothing 40 \times 70,5$
55376 $\varnothing 32 \times \varnothing 40 \times 64$
72805 $\varnothing 39$
60481
72669
72869 $\varnothing 40 \times 10,5$



54069 Caliper Pin Repair Kit

Type : SN6 - SN7 - SK7 - ST7
Replaces : K000472

Suitable for Man Daf Bpw Saf Iveco
Replaces 81.50822.6019 1639100 1622786 09.801.06.33.0 3 434 3812 00 42541412
Suitable for TGA / TGS / TGM TGX / F 2000 / LION'S XF105/95 / CF65 75/85 / LF45/55 SKH Series (SB 3745) SH Series (SB 4345) SKH..LL Series (SB 3745) SH..LL Series (SB 4309 / SB 4345) SBK 1937-11 S / SBK 2243-11 S Stralis EuroRider EuroStar EuroTech EuroTrakker Irisbus

60372 $\varnothing 36 \times 114$
60373 $\varnothing 32 \times 80$
55331
55306 M16x1,5/86,5
55307 M16x1,5/80
60353
60533 $\varnothing 36 \times \varnothing 40 \times 82$
55376 $\varnothing 32 \times \varnothing 40 \times 64$
72805 $\varnothing 39$
60481
72669
60485 $\varnothing 40 \times 14,5$



54071 Caliper Pin Repair Kit

Type : SB5 - SB6 - SB7 - SB7 RADIAL
Replaces : K001532

Suitable for Bpw Scania
Replaces 09.801.06.31.0 1472919
Suitable for SKH Series (SB 3745) SH Series (SB 4345) SKH..LL Series (SB 3745) SH..LL Series (SB 4309 / SB 4345) 4 Series Truck / PGRT Series Truck 4 Series Bus / FKN Series Bus

60372 $\varnothing 36 \times 114$
60373 $\varnothing 32 \times 80$
55331
55306 M16x1,5/86,5
55307 M16x1,5/80
60353
60533 $\varnothing 36 \times \varnothing 40 \times 82$
55376 $\varnothing 32 \times \varnothing 40 \times 64$
72806 $\varnothing 35$
60480 $\varnothing 52 \times 28$
72669
60481
60565
60565

53888

Caliper Pin Repair Kit



Type : SB6 - SB7 - SN6 - SN7

Replaces : K000375

Suitable for	Replaces	Suitable for
Man	81.50822.6023	TGA
Bpw	09.801.06.24.0	SKH Series (SB 3745) SKH..LL Series (SB 3745)

76298

Caliper Pin Repair Kit



Type : SB6 - SB7 - SB7 RADIAL - SN6 - SN7

Replaces : K067417K50 - K048434K62

Suitable for	Replaces	Suitable for
Scania	2365038 2087143	4 Series Truck / PGRT Series Truck 4 Series Bus / FKN Series Bus
Saf	3 434 3820 00	SKRB 9019 K (SN 6) SKRB 9022 K (SN 7) SKRS 9019 K (SN 6) SKRS 9022 K (SN 7) SKRZ 9019 K (SN 6) SKRZ 11019 K (SN 6) SKRZ 9022 K (SN 7) SKRZ 11222 K (SN 7) B9-19K / B19-19K / S19-19K / Z111-19K

77262

Caliper Pin Repair Kit



Type : SB5 - SB6 - SB7

Replaces : K001470

Suitable for	Replaces	Suitable for
Mercedes	000 421 61 74 000 420 46 82 000 420 34 82	Atego 2 Touro Multego Tourismo



54178
ø74,3

57162

57163

79387



56156



57182
29 Links



56133

79765 Caliper Kit

Type : SB7 RADIAL

Replaces : -



54178
ø74,3

57162

57163

77433
12° - 123 mm



56156



57182
29 Links



56133

78535 Caliper Kit

Type : SB6 - SB7

Replaces : -

Suitable for Replaces Suitable for



79766 Caliper Kit

Type : SB6 - SB7


Replaces : -



79767 Caliper Kit

Type : SB6 - SB7


Replaces : -



78534 Caliper Kit

Type : SN6 - SN7 - SK7

Replaces : -



79770 Caliper Kit

Type : SN6 - SN7 - SK7

Replaces : -



79768 Caliper Kit

Type : SN6 - SN7 - SK7


Replaces : -



79769 Caliper Kit

Type : SN6 - SN7 - SK7

Replaces : -



53881
ø69,3



57162



57163



79276
12^ø - 123 mm



56152



57182
29 Links




56134

78533 Caliper Kit

Type : SN7 - SK7

Replaces : -



53881
ø69,3



57162



57163



76975
0^ø - 113 mm



56152



57182
29 Links




56134

79771 Caliper Kit

Type : SN7 - SK7

Replaces : -



53881
ø69,3



57162



57163



79277
0° - 125 mm



56152



57182
29 Links



56134

79772 Caliper Kit

Type : SN7 - SK7

Replaces : -



77447
ø69,3



76973



57163



79386



79279



57182
29 Links




79388

79773 Caliper Kit

Type : SL7 - SM7

Replaces : -



81494 Comple Caliper Kit

Type : SB6 - SB7 - SB7 RADIAL

Replaces : -

Suitable for
Man

Replaces
-

Suitable for
TGA (New Model)



81493 Comple Caliper Kit

Type : SB6 - SB7 - SB7 RADIAL

Replaces : -

Suitable for
Mercedes

Replaces
-

Suitable for
Axor (Old Model)



54178
ø74,3



57162



57163



71447



56154



57182
29 Links



56134

81495 Comple Caliper Kit

Type : SN6 - SN7 - SK7

Replaces : -

Suitable for
Mercedes

Replaces
-

Suitable for
Axor (New Model)



77447
ø69,3



79279



71447



76978



76973



57163



57182
29 Links



79388

81497 Comple Caliper Kit, New Type

Type : SL7 - SM7

Replaces : -

Suitable for
Mercedes

Replaces
-


Suitable for
Axor (New Model)



54167
ø69,3



56152



76298



56130



76973



57163



57182
29 Links




56133


81498 Comple Caliper Kit

Type : ST7

Replaces : -



53881
ø69,3



56152



56021



56130



57162



57163



57182
29 Links



56133

81496 Comple Caliper Kit


Type : SN6 - SN7 - SK7 - ST7

Replaces : -

Suitable for
Scania

Replaces
-

Suitable for



80235 Comple Caliper Kit, New Type


Type : SN6 - SN7 - SK7

Replaces : -

Suitable for
Mercedes
Bpw

Replaces
-

Suitable for
Actros
SKH Series (SB 3745)
SH Series (SB 4345)
SKH..LL Series (SB 3745)
SH..LL Series (SB 4309 / SB 4345)



80236 Comple Caliper Kit, Old Type


Type : SN6 - SN7 - SK7

Replaces : -

Suitable for
Mercedes
Bpw

Replaces
-

Suitable for
Actros
SKH Series (SB 3745)
SH Series (SB 4345)
SKH..LL Series (SB 3745)
SH..LL Series (SB 4309 / SB 4345)



81499 Comple Caliper Kit

Type : SN5

Replaces : -

Suitable for
Man

Replaces
-

Suitable for
12.180 TGL



81500 Comple Caliper Kit

Type : SB5

Replaces : -

Suitable for
Man

Replaces
-

Suitable for
12.160 TGL

54525 Adjusting Mechanism Cap Set

Type : SN6 - SN7 - SK7 - ST7
Replaces : K003902

Suitable for	Replaces	Suitable for
Schmitz	1008543	-

54068 Adjusting Mechanism Cap Set

Type : SN5 - SB6 - SB7 - SB7 RADIAL - SN6 - SN7 - SK7 - ST7 - SL7 - SM7
Replaces : K000029

Suitable for	Replaces	Suitable for
Man	81.50822.6021	TGA / TGS / TGX / TGL / TGM / LION'S
Daf	1459407	XF105/95 / CF65/75/85 / LF45/55

53880 Adjusting Mechanism Cap Set

Type : SB5 - SN5 - SB6 - SB7 - SB7 RADIAL - SN6 - SN7 - SK7 - ST7 - SL7 - SM7
Replaces : K000945

Suitable for	Replaces	Suitable for
Man	81.50822.6024	TGA / TGS TGX / TGL TGM / LION'S
Scania	1390430	4 Series Bus
Daf	1439493	XF105/95 / CF65 75/85 / LF55

53880 Adjusting Mechanism Cap Set

Type : SB5 - SN5 - SB6 - SB7 - SB7 RADIAL - SN6 - SN7 - SK7 - ST7 - SL7 - SM7
Replaces : K000945

Suitable for	Replaces	Suitable for
Man	81.50822.6024	TGA / TGS TGX / TGL TGM / LION'S
Scania	1390430	4 Series Bus
Daf	1439493	XF105/95 / CF65 75/85 / LF55

56112 Brake Pad Retainer Kit

Type : SB5 - SN5 - SB6 - SB7 - SB7 RADIAL - SN6 - SN7 - SK7 - ST7 - SL7 - SM7
Replaces : -

56135 Caliper Screw Set

Type : SB5 - SB6 - SB7 - SB7 RADIAL
Replaces : -

56146 Brake Pad Retainer Kit

Type : SB7 - SB7 RADIAL - SN7
Replaces : K000129

70829 Brake Pad Retainer Kit

Type : SN5 - SB6 - SN6 - SK7 - SL7 - SM7
Replaces : K000133
Suitable for Mercedes 000 420 25 82
Saf 3 434 3807 00

Replaces :
Suitable for Atego / Atego 2 Axor 2 / Accelo / Actros 2/3
SKRB 9019 K (SN 6) / SKRS 9019 K (SN 6) SKRS 11019 K (SN 6) / SKRZ 11019 K (SN 6) B9-19K / B19-19K / S19-19K / S111-19K / Z111-19K

81487 Brake Pad Retainer Kit

Type : SB7 - SB7 RADIAL - SN7
Replaces : K000884

81488 Brake Pad Retainer Kit

Type : SN5 - SB6 - SN6 - SK7 - SL7 - SM7
Replaces : -

81491 Brake Pad Retainer Kit

Type : SB7 - SB7 RADIAL - SN7
Replaces : -

81492 Brake Pad Retainer Kit

Type : SN5 - SB6 - SN6 - SK7 - SL7 - SM7
Replaces : -



81489

Cable Protection Kit


Type : SN5 - SB6 - SB7 - SB7 RADIAL - SN6 - SN7 - SK7 - SL7 - SM7
Replaces : -



81490

Cable & Protection Kit

Type : SN5 - SB6 - SB7 - SB7 RADIAL - SN6 - SN7 - SK7 - SL7 - SM7
Replaces : -




56144

Brake Pad Retainer Kit

Type : Bendix ADB 3700 / 4300
Replaces : 381.419

Suitable for	Replaces	Suitable for
Iveco	93161560	EuroCargo / EuroTech / EuroStar / Irisbus



56145

Brake Pad Retainer Kit

Type : Bendix ADB 3700 / 4300
Replaces : 381.422

Suitable for	Replaces	Suitable for
Iveco	93161559	EuroCargo / EuroFire



56085

Pad Retention Pins and Clips Kit

Type : Bendix ADB 3700 / 4300
Replaces : 1133692

Suitable for	Replaces	Suitable for
Iveco	93161843	Trakker EuroCargo EuroFire EuroStar EuroTech Irisbus




56058

Caliper Pin Repair Kit

Type : Bendix ADB 3700 / 4300

Replaces : 381.391

Suitable for Replaces Suitable for
Iveco 93161189 EuroCargo / EuroFire / EuroStar / EuroTech
Irisbus



53883

Caliper Pin Boot Set

Type : Bendix ADB 3700 / 4300

Replaces : 381.413

Suitable for Replaces Suitable for
Iveco 93161192 EuroCargo / EuroFire / EuroStar / EuroTech
Irisbus



56069

Wedge Assembly

Type : Bendix ADB 3700 / 4300

Replaces : 381.427

Suitable for Replaces Suitable for
Iveco 93192575 EuroCargo / EuroStar / EuroTech / Irisbus




56106

Wedge Assembly

Type : Bendix ADB 3700 / 4300

Replaces : 381.426

Suitable for Replaces Suitable for
Iveco 93192555 EuroCargo / EuroFire




81559

Carrier - 22,5" - Front - Left/Right

Type : SB7 - SN7

Replaces : Z007541 - K000026

Suitable for Replaces Suitable for
Mercedes 000 421 11 06 Atego - Actros - Axor



81560

Carrier - 22,5" - Front - Left/Right

Type : SB7 - SN7

Replaces : -

Suitable for Replaces Suitable for
Mercedes - 4140

81561 Carrier - 22,5" - Left/Right

Type : SB7 - SB7 RADIAL - SN7
Replaces : K001278

Suitable for Man	Replaces -	Suitable for TGA 18.430
------------------	------------	-------------------------

81562 Carrier - 22,5" - Left/Right

Type : -
Replaces : Z006590

Suitable for Scania	Replaces -	Suitable for -
---------------------	------------	----------------

81563 Carrier - 22,5" - Left/Right

Type : SB7 - SB7 RADIAL - SN7
Replaces : K010765

Suitable for Scania	Replaces 1756388	Suitable for 4 Series Truck / PGRT Series Truck / 4 Series Bus / FKN Series Bus
---------------------	------------------	---

81564 Carrier - 22,5" - Left/Right

Type : SB7 - SN7
Replaces : Z006582 - K000027

Suitable for Mercedes	Replaces 000 423 06 06	Suitable for Axor
-----------------------	------------------------	-------------------

81565 Carrier - 22,5" - Left/Right


Type : -
Replaces : -

Suitable for Mercedes	Replaces -	Suitable for Conecto
-----------------------	------------	----------------------

81566 Carrier - 22,5" - Left/Right

Type : SB7 - SN7
Replaces : K011479 - K001528

Suitable for Daf	Replaces 1689314	Suitable for CF_E6 - XF_E6 - CF Series - XF Series
------------------	------------------	--




81567

Carrier - 22,5" - Rear Left

Type : SB7 - SB7 RADIAL - SN7
Replaces : K001530

Suitable for Mercedes	Replaces 000 421 38 06	Suitable for OH Series - O500
-----------------------	------------------------	-------------------------------




81568

Carrier - 22,5" - Rear Right

Type : SB7 - SB7 RADIAL - SN7
Replaces : K001529

Suitable for Mercedes	Replaces 000 421 37 06	Suitable for OH Series - O500
-----------------------	------------------------	-------------------------------




81569

Carrier - 22,5" - Rear Left/Right

Type : SL7
Replaces : Z025197 - K052379K50

Suitable for Mercedes	Replaces 000 423 10 06	Suitable for Axor - Antos - Arocs - Actros
-----------------------	------------------------	--




81570

Carrier - 22,5" - Front Left/Right

Type : -
Replaces : Z046338

Suitable for Mercedes	Replaces -	Suitable for 4140
-----------------------	------------	-------------------




81571

Carrier - 22,5" - Left/Right

Type : SN7
Replaces : -

Suitable for Mercedes	Replaces -	Suitable for -
-----------------------	------------	----------------



81572

Carrier - 22,5" - Left/Right

Type : SK7
Replaces : Z019050 - K015308

Suitable for Saf	Replaces -	Suitable for -
------------------	------------	----------------

81573 Carrier - 22,5" - Left/Right

Type : SK7
Replaces : K004680

Suitable for	Replaces	Suitable for
Scania	2379696	-
Bpw	01.303.88.57.0	-

81574 Carrier - 22,5" - Left/Right

Type : SK7
Replaces : K004099

Suitable for	Replaces	Suitable for
Scania	2121600	-
Saf	-	-

81575 Carrier - 19,5" - Left/Right

Type : SN6
Replaces : K001926

Suitable for	Replaces	Suitable for
Mercedes	000 421 31 06	Atego

81576 Carrier - 19,5" - Left/Right

Type : -
Replaces : -

Suitable for	Replaces	Suitable for
Bpw	-	-

81577 Carrier - 22,5" - Left/Right


Type : SK7
Replaces : Z006715 - K012619

Suitable for	Replaces	Suitable for
Bpw	01.303.88.56.0	-

81578 Carrier - 19,5" - Left/Right

Type : SN6
Replaces : Z019053

Suitable for	Replaces	Suitable for
Saf	-	Jumbo




81579

Carrier - 19,5" - Left/Right

Type : SN6
Replaces : Z017557

Suitable for Mercedes	Replaces -	Suitable for Axor
-----------------------	------------	-------------------




81580

Carrier - 19,5" - Left/Right

Type : SN6
Replaces : K004679

Suitable for Bpw	Replaces -	Suitable for -
------------------	------------	----------------



81581

Carrier - 17,5" - Left/Right

Type : SN5
Replaces : K001927

Suitable for Mercedes	Replaces 000 421 30 06	Suitable for Atego
Scania	2121599	-

Suitable for

ROR-MERITOR

56031 Caliper Bridge Assembly, Left

Type : DX195
Replaces : MCK1292

56032 Caliper Bridge Assembly, Right

Type : DX195
Replaces : MCK1293

81626 Caliper Piston Kit, Left

Type : DX195
Replaces : -

81627 Caliper Piston Kit, Right

Type : DX195
Replaces : -

56111 Caliper Piston Kit, Left

Type : DX195
Replaces : -

56110 Caliper Piston Kit, Right

Type : DX195
Replaces : -

56109 Caliper Plate Kit, Left

Type : DX195
Replaces : -

56108 Caliper Plate Kit, Right

Type : DX195
Replaces : -

77383 Adjusting Mechanism Repair Kit, Left

Type : DX195
Replaces : DSB5L - MCK1290S

77384 Adjusting Mechanism Repair Kit, Right

Type : DX195
Replaces : DSB5R - MCK1291S

81639 Adjusting Mechanism Repair Kit, Left

Type : DX225
Replaces : -

81640 Adjusting Mechanism Repair Kit, Right

Type : DX225
Replaces : -



56059

Adjusting Mechanism Repair Kit, Left

Type : D LISA
Replaces : MCK1075

Suitable for	Replaces	Suitable for
Renault Truck	5001 854 954	Premium / Magnum / Midliner



56060

Adjusting Mechanism Repair Kit, Right

Type : D LISA
Replaces : MCK1076

Suitable for	Replaces	Suitable for
Renault Truck	5001 854 955	Premium / Magnum / Midliner



56014

Adjusting Mechanism Repair Kit, Left

Type : C LISA - D LISA
Replaces : -

Suitable for	Replaces	Suitable for
Renault Truck	5001 856 319	Premium / Magnum / Midliner



56015

Adjusting Mechanism Repair Kit, Right

Type : C LISA - D LISA
Replaces : -

Suitable for	Replaces	Suitable for
Renault Truck	5001 856 320	Premium / Magnum / Midliner



56040

Adjusting Mechanism Repair Kit, Left

Type : C LISA - D LISA
Replaces : SJ4113 - MCK4113

Suitable for	Replaces	Suitable for
Volvo	3092763	B10
Renault Truck	-	Premium / Magnum / Midliner



56018

Adjusting Mechanism Repair Kit, Right

Type : C LISA - D LISA
Replaces : SJ4114

Suitable for	Replaces	Suitable for
Volvo	3092764	B10
Renault Truck	-	Premium / Magnum / Midliner

57597 Adjusting Mechanism Repair Kit, Left
(Old Type - Ø48 mm)

Type : ELSA 1
Replaces : -

Suitable for Man	Replaces -	Suitable for F2000 / Lion's City
------------------	------------	----------------------------------

57598 Adjusting Mechanism Repair Kit, Right
(Old Type - Ø48 mm)

Type : ELSA 1
Replaces : -

Suitable for Man	Replaces -	Suitable for F2000 / Lion's City
------------------	------------	----------------------------------

81632 Adjusting Mechanism Repair Kit, Left
(New Type - Ø44 mm)

Type : ELSA 1
Replaces : -

Suitable for Man	Replaces -	Suitable for F2000 / Lion's City
------------------	------------	----------------------------------

81633 Adjusting Mechanism Repair Kit, Right
(New Type - Ø44 mm)

Type : ELSA 1
Replaces : -

Suitable for Man	Replaces -	Suitable for F2000 / Lion's City
------------------	------------	----------------------------------

81634 Adjusting Mechanism, Left
(Old Type - Ø48 mm)

Type : ELSA 1
Replaces : -

81635 Adjusting Mechanism, Right
(Old Type - Ø48 mm)


Type : ELSA 1
Replaces : -



81636

Adjusting Mechanism, Left
(New Type - Ø44 mm)

Type : ELSA 1
Replaces : -



81637

Adjusting Mechanism, Right
(New Type - Ø44 mm)

Type : ELSA 1
Replaces : -



70701

Eccentric Shaft

Type : DX195
Replaces : -



56041

Eccentric Shaft Repair Kit

Type : DX195
Replaces : MCK1294 - MCK1168 - MCK1169




70689

Caliper Adjusting Gear Set, Left

Type : ELSA2 SERIES
Replaces : -

Suitable for	Replaces	Suitable for
Man	-	Lion's City / Centroliner NL / NG / NL / NUE / ND / NM
Volvo	-	B7/9/12
Renault Truck	-	Premium / Sisu / Midlum / Magnum



70688

Caliper Adjusting Gear Set, Right

Type : ELSA2 SERIES
Replaces : -

Suitable for	Replaces	Suitable for
Man	-	Lion's City / Centroliner NL / NG / NL / NUE / ND / NM
Volvo	-	B7/9/12
Renault Truck	-	Premium / Sisu / Midlum / Magnum



76246

Caliper Adjusting Gear Set

Type : ELSA195 - ELSA225 - EX225
Replaces : -




55719

Adjusting Mechanism Shaft Kit,
Front Left-Right

Type : C DUCO - Le DUCO - D DUCO SERIES
Replaces : MCK1113

Suitable for	Replaces	Suitable for
Volvo	85102093	FH12/16 - FM7/9/10/12



55720

Adjusting Mechanism Shaft Kit, Rear Left

Type : C DUCO - Le DUCO - D DUCO SERIES
Replaces : MCK1111

Suitable for	Replaces	Suitable for
Volvo	85102095	FH12/16 - FM7/9/10/12




56047

Adjusting Mechanism Shaft Kit,
Rear Left, 53720's Old Type

Type : C DUCO - Le DUCO - D DUCO SERIES
Replaces : SJ4102

Suitable for	Replaces	Suitable for
Volvo	3092265	FH12/16 - FM7/9/10/12



55721

Adjusting Mechanism Shaft Kit,
Rear Right

Type : C DUCO - Le DUCO - D DUCO SERIES
Replaces : MCK1112

Suitable for	Replaces	Suitable for
Volvo	85102096	FH12/16 - FM7/9/10/12



56048

Adjusting Mechanism Shaft Kit,
Rear Right, 55721's Old Type

Type : C DUCO - Le DUCO - D DUCO SERIES
Replaces : SJ4103

Suitable for	Replaces	Suitable for
Volvo	3092266	FH12/16 - FM7/9/10/12

73088
48 Teeth-Short

73093

73025
ø50xø55x20

72785
M10x1,5/50

55346
ø42x121/170x13

72677
ø54

81645 Caliper Overhaul Repair Kit, Front Left

Type : D3
Replaces : -

73089
48 Teeth-Short

73094

73025
ø50xø55x20

72785
M10x1,5/50

55346
ø42x121/170x13

72677
ø54

81646 Caliper Overhaul Repair Kit, Front Right

Type : D3
Replaces : -

73090
26 Teeth-Short

73093

73025
ø50xø55x20

72785
M10x1,5/50

55346
ø42x121/170x13

72677
ø54

81643 Caliper Overhaul Repair Kit, Front Left

Type : D3
Replaces : -

73091
26 Teeth-Short

73094

73025
ø50xø55x20

72785
M10x1,5/50

55346
ø42x121/170x13

72677
ø54

81644 Caliper Overhaul Repair Kit, Front Right

Type : D3
Replaces : -

26 Teeth-Long

73093

73025
ø50xø55x20

72785
M10x1,5/50

55346
ø42x121/170x13

72677
ø54

81641 Caliper Overhaul Repair Kit, Rear Left

Type : D3
Replaces : -

26 Teeth-Long

73094

73025
ø50xø55x20

72785
M10x1,5/50

55346
ø42x121/170x13

72677
ø54

81642 Caliper Overhaul Repair Kit, Rear Right

Type : D3
Replaces : -



73088

Spline Shaft, Front Left (48 Teeth-Short)

Type : D3
Replaces : -



73089

Spline Shaft, Front Right (48 Teeth-Short)

Type : D3
Replaces : -



73090

Spline Shaft, Front Left (26 Teeth-Short)

Type : D3
Replaces : -



73091

Spline Shaft, Front Right (26 Teeth-Short)

Type : D3
Replaces : -



73093

Shaft Base, Left


Type : D3
Replaces : -



73094

Shaft Base, Right

Type : D3
Replaces : -



73416

Caliper Adjusting Gear Set, Left

Type : D3
Replaces : -



57591

Caliper Adjusting Gear Set, Right

Type : D3
Replaces : -



56033

Caliper Adjusting Gear Set, Left

Type : C LISA - D LISA
Replaces : SJ4073
Suitable for Volvo 3098110
Renault Truck 5001 845 386

Suitable for B10
Premium / Magnum / Midliner



56034

Caliper Adjusting Gear Set, Right

Type : C LISA - D LISA
Replaces : SJ4074
Suitable for Volvo 3098111
Renault Truck 5001 845 387

Suitable for B10
Premium / Magnum / Midliner



56029

Operating Shaft Kit, Left

Type : C LISA - D LISA
Replaces : MCK1151 - MCK1021
Suitable for Volvo 85104827 - 3098579
Renault Truck -

Suitable for B10
Premium / Magnum / Midliner



56030

Operating Shaft Kit, Right

Type : C LISA - D LISA
Replaces : MCK1152 - MCK1022
Suitable for Volvo 85104828 - 3098580
Renault Truck -

Suitable for B10
Premium / Magnum / Midliner



73126

Operating Shaft, Left

Type : C LISA - D LISA
Replaces : -
Suitable for Volvo -
Renault Truck -

Suitable for B10
Premium / Magnum / Midliner



73127

Operating Shaft, Right

Type : C LISA - D LISA
Replaces : -
Suitable for Volvo -
Renault Truck -

Suitable for B10
Premium / Magnum / Midliner



73067

Shaft Base, Left

Type : C LISA - D LISA
Replaces : -
Suitable for Volvo -
Renault Truck -

Suitable for B10
Premium / Magnum / Midliner



73068

Shaft Base, Right

Type : C LISA - D LISA
Replaces : -
Suitable for Volvo -
Renault Truck -

Suitable for B10
Premium / Magnum / Midliner



57590 Caliper Adjusting Gear Set, Left

Type : ELSA 1
Replaces : -



57589 Caliper Adjusting Gear Set, Right

Type : ELSA 1
Replaces : -



79282 Caliper Adjusting Gear Set, Left

Type : ELSA 1
Replaces : -



79281 Caliper Adjusting Gear Set, Right

Type : ELSA 1
Replaces : -



81628 Caliper Adjusting Gear, Left

Type : ELSA 1
Replaces : -



81629 Caliper Adjusting Gear, Right

Type : ELSA 1
Replaces : -



81630 Caliper Adjusting Gear, Left

Type : ELSA 1
Replaces : -



81631 Caliper Adjusting Gear, Right

Type : ELSA 1
Replaces : -

56136

Caliper Adjusting Gear Set

Type : ELSA2 AXIAL - ELSA195 - ELSA225 - EX225

Replaces : -

Suitable for	Replaces	Suitable for
Man	-	Lion's City Centroliner NL / NG / NL NUE / ND / NM
Volvo	-	B7/9/12
Renault Truck	-	Premium Sisu Midlum Magnum



70694

Caliper Adjusting Gear Set

Type : ELSA2 AXIAL - ELSA195 - ELSA225 - EX225

Replaces : -

Suitable for	Replaces	Suitable for
Man	-	Lion's City Centroliner NL / NG / NL NUE / ND / NM
Volvo	-	B7/9/12
Renault Truck	-	Premium Sisu Midlum Magnum



81638

Caliper Adjusting Gear Set

Type : ELSA2 RADIAL

Replaces : -



73103

Caliper Adjusting Gear Slot

Type : ELSA 1

Replaces : -




70699

Caliper Adjusting Mechanism
(Bearing)

Type : ELSA2 AXIAL - ELSA195 - ELSA225 - EX225

Replaces : -



Suitable for Man	Replaces	Suitable for
	-	Lion's City Centroliner NL / NG / NL NUE / ND / NM
Volvo	-	B7/9/12
Renault Truck	-	Premium Sisu Midlum Magnum



56126

Clutch System Kit, Left


Type : D3
Replaces : -



56127

Clutch System Kit, Right

Type : D3
Replaces : -



56141


Adjusting Mechanism Repair Kit

Type : ELSA2 SERIES - ELSA195 - ELSA225 - EX225

Replaces : -

Suitable for Man	Replaces	Suitable for
	-	Lion's City Centroliner NL / NG / NL NUE / ND / NM
Volvo	-	B7/9/12
Renault Truck	-	Premium Sisu Midlum Magnum

73022
ø14xø16x15



56139

Clutch System Kit, Left

Type : ELSA 1
Replaces : -

Suitable for Man Replaces Suitable for F2000 / Lion's City



56140

Clutch System Kit, Right

Type : ELSA 1
Replaces : -

Suitable for Man Replaces Suitable for F2000 / Lion's City



79746

Small Gear Mechanism, Right

Type : C DUCO - Le DUCO - D DUCO SERIES - ELSA 1
Replaces : 68322563PK4

Suitable for Volvo Replaces 3092281 Suitable for FH12/16 - FM12 / B7-9




73417

Small Gear Mechanism, Left

Type : C DUCO - Le DUCO - D DUCO SERIES - ELSA 1
Replaces : 68322562PK4

Suitable for Volvo Replaces 3092280 Suitable for FH12/16 - FM12 / B7-9



53866

Caliper Pin Repair Kit

Type : DX195
Replaces : MCK1171/N



53872

Caliper Pin Repair Kit

Type : DX195
Replaces : MCK1171



72697
ø32x97

55318
M16x1,5/55

73014
ø32xø36x20

55375
ø21xø48,5x20,5

72860
ø41,75x27,5

73013
ø32xø36x30

56020 Caliper Pin Repair Kit

Type : DX195
Replaces : DSB1



72742
ø34,7x98

72741
ø35x98

55374
ø19xø64,5x21,75

57641
ø25xø55,5x17,5

57573
M18x2,5/90

57572
M18x2,5/55

73016
ø35xø39x50

72860
ø41,75x27,5

56035 Caliper Pin Repair Kit

Type : DX225
Replaces : MCK1172



57570
M14x1,5/90

57641
ø25xø55,5x17,5

57575
M14x1,5/70

57642
ø18,5xø44x19

72898
ø37,3x24

56036 Caliper Pin Repair Kit

Type : DX175
Replaces : MCK1191



57641
ø25xø55,5x17,5

55374
ø19xø64,5x21,75

57573
M18x2,5/90

57572
M18x2,5/55

72860
ø41,75x27,5

56044 Caliper Boot & Cap Set

Type : DX225
Replaces : MCK1193



72698
ø31,7/ø32x97

72697
ø32x97

72993
ø32xø36x55

55307
M16x1,5/80

55318
M16x1,5/55

55374
ø19xø64,5x21,75

55375
ø21xø48,5x20,5

72860
ø41,75x27,5

70687 Caliper Pin Repair Kit

Type : DX225
Replaces : MCK1173



55307
M16x1,5/80

55318
M16x1,5/55

55374
ø19xø64,5x21,75

55375
ø21xø48,5x20,5

72860
ø41,75x27,5

53873 Caliper Boot & Cap Set

Type : DX195
Replaces : MCK1192



54175

Caliper Pin Repair Kit

Type : D3
Replaces : SJ4001

Suitable for Renault Truck Replaces 5001 822 994 Suitable for Premium / Magnum



54546

Caliper Pin Repair Kit

Type : D3
Replaces : SJ1213

Suitable for Mercedes Replaces 000 420 01 76 Suitable for Tourismo



54549

Caliper Pin Repair Kit

Type : D3
Replaces : SJ4011 - MCK1213 - SJ1228 - SJ4012

Suitable for Mercedes Man Replaces 000 420 02 76 81.50802.6009 81.50802.6008 Suitable for Tourismo F90 F2000 M2000 E Series



54532

Caliper Pin Repair Kit

Type : C LISA
Replaces : SJ4052

Suitable for Renault Truck Replaces 5001 845 385 Daf 1522192 Suitable for Midliner



53874

Caliper Pin Repair Kit

Type : D LISA
Replaces : SJ4076 - MCK1104

Suitable for Volvo Replaces 3098108 Renault Truck 5001 837 006 Daf 1522184 Suitable for B7/10 Premium / Magnum

56088 Seal Kit

Type : D LISA
Replaces : -

Suitable for	Replaces	Suitable for
Renault Truck	5001 854 951	Premium / Magnum

54552 Screw & Cap Kit

Type : D LISA
Replaces : SJ4021

Suitable for	Replaces	Suitable for
Volvo	8550881	B10
Renault Truck	-	Premium / Magnum

54172 Caliper Boot & Cap Set

Type : D DUCO AXIAL - ELSA195 - ELSA225 - EX225
Replaces : MCK1310

Suitable for	Replaces	Suitable for
Volvo	85109892	FH13/12/16 FM9/11/12/13
Renault Truck	5001 866 400	Premium Magnum Midlum

54173 Caliper Boot & Cap Set

Type : ELSA2 SERIES - ELSA195 - ELSA225
Replaces : MCK1244

Suitable for	Replaces	Suitable for
Renault Truck	5001 858 718 5001 860 792	Premium / Magnum

53868 Caliper Boot & Cap Set

Type : ELSA195 - ELSA225 - EX225
Replaces : MCK1253



53869 Caliper Pin Repair Kit

Type : ELSA195
Replaces : MCK1254

72702 ø35x117
72701 ø31x78
55369
55304 M18x1,5/120
55303 M18x1,5/81,5
72862 ø44x17,5
72863 ø39x10
55302 M14x1,5/40
72996 30/31xø42x30
72995 ø35xø39x30



54170 Caliper Pin Repair Kit

Type : ELSA2 SERIES
Replaces : MCK1086

Suitable for Man -
Renault Truck 5001 858 717

Replaces
55301 M20x1,5/150
55300 M20x1,5/90
55384 M16x1,5/40

Suitable for
F2000
Premium / Magnum

72712 ø35x128
72711 33/ø35x66
72995 ø35xø39x30
72870 ø44x27
55369



54169 Caliper Pin Repair Kit

Type : ELSA195 - ELSA225 - EX225
Replaces : MCK1298

Suitable for Volvo
Renault Truck 5001 866 989

Replaces
85109890

Suitable for
FH13/12/16
FM9/11/12/13
Premium
Magnum
Midlum

72710 ø35x117
72709 ø31x78
72995 ø35xø39x30
72996 30/31xø42x30
55304 M18x1,5/120
55303 M18x1,5/81,5
55369
55294 M16x1,5/40
72863 ø39x10
55302 M14x1,5/40
72862 ø44x17,5



54171 Caliper Pin Repair Kit

Type : ELSA2 SERIES
Replaces : MCK1243 - MCK1140

Suitable for Man
Volvo
Renault Truck 5001 860 791

Replaces
81.50802.6025
85107912

Suitable for
TGA / TGL
Lion's City
FH12/16
FM7/9/10/12
Premium
Magnum
Midlum

72714 ø35x144
72713 ø31x84
72996 30/31xø42x30
55369
55296 M18x1,5/150
55295 M18x1,5/90
55384 M16x1,5/40
72870 ø44x27
72808 ø37xø42x14
72995 ø35xø39x30

72700 $\varnothing 35 \times 135$
72722 M20x1,5/ $\varnothing 28 \times 110$
55369
72811 $\varnothing 30,2 \times \varnothing 40 \times 19$
72810 $\varnothing 37 \times \varnothing 39 \times 15$
55301 M20x1,5/150
55300 M20x1,5/90
72861 $\varnothing 44 \times 27,5$
72995 $\varnothing 35 \times \varnothing 39 \times 30$
55343 $\varnothing 26 \times \varnothing 42,5 \times 27,5$

54529 Caliper Pin Repair Kit

Type : ELSA 1
Replaces : MCK1103

Suitable for Man Replaces 81.50802.6022 Suitable for TGA / TGS / TGX / Lion's Series

72700 $\varnothing 35 \times 135$
72699 $\varnothing 35 \times 72$
72861 $\varnothing 44 \times 27,5$
55301 M20x1,5/150
55300 M20x1,5/90
72801 $\varnothing 37 \times \varnothing 40 \times 15$
72995 $\varnothing 35 \times \varnothing 39 \times 30$
72994 35/37x $\varnothing 40 \times 32,5$
72802 $\varnothing 37 \times \varnothing 48 \times 13,5$

53867 Caliper Pin Repair Kit

Type : ELSA 1
Replaces : MCK1102/N

Suitable for - Replaces - Suitable for TGA / Lion's Series

72724 $\varnothing 35 \times 102$
72723 $\varnothing 35 \times 60$
55369
55316 M20x2/123,5
55315 M20x2/83
72875 $\varnothing 39,5 \times 17,5$
72672 $\varnothing 35 \times \varnothing 39 \times 38$
73006 35/36x $\varnothing 39 \times 30$
72813 $\varnothing 37 \times \varnothing 39 / \varnothing 40$

54530 Caliper Pin Repair Kit

Type : B DUCO - C DUCO - Le DUCO - D DUCO AXIAL
Replaces : MCK1134 - SJ4094

Suitable for Volvo Replaces 85103892 Suitable for FH12/16 - FM7/10

72700 $\varnothing 35 \times 135$
72699 $\varnothing 35 \times 72$
55369
72861 $\varnothing 44 \times 27,5$
55301 M20x1,5/150
55300 M20x1,5/90
72801 $\varnothing 37 \times \varnothing 40 \times 15$
72802 $\varnothing 37 \times \varnothing 48 \times 13,5$
72994 35/37x $\varnothing 40 \times 32,5$
72995 $\varnothing 35 \times \varnothing 39 \times 30$

56009 Caliper Pin Repair Kit

Type : ELSA 1
Replaces : MCK1102 - ST1157 - ST1192

Suitable for Man Replaces 81.50802.6021
81.50802.6020
81.50802.6017 Suitable for TGA / TGS / TGX / Lion's Series



54551

Caliper Pin Repair Kit

Type : B DUCO - C DUCO - Le DUCO - D DUCO AXIAL
Replaces : MCK1116

Suitable for	Replaces	Suitable for
Volvo	85102094	FH12/16 - FM7/9/10/12



54553

Caliper Pin Repair Kit

Type : D DUCO RADIAL
Replaces : MCK1135

Suitable for	Replaces	Suitable for
Volvo	85103891	FH12/16 - FM10/12



54556

Caliper Pin Repair Kit

Type : D DUCO RADIAL
Replaces : MCK1118

Suitable for	Replaces	Suitable for
Volvo	85102092	FH12/16 - FM7/9/10/12



54554

Caliper Pin Repair Kit

Type : B DUCO - C DUCO - Le DUCO - D DUCO SERIES - ELSA 1
Replaces : MCK1299 - MCK1066

Suitable for	Replaces	Suitable for
Volvo	85107718 3095628 3096769	FH12/16 - FM7/9/10/12



56010

Caliper Pin Repair Kit

Type : ELSA 225 RADIAL - EX225
Replaces : MCK1317

Suitable for	Replaces	Suitable for
Volvo	85109889	FH12/16 - FM7/9/10/12



54557

Caliper Pin Repair Kit

Type : D2
Replaces : SP8999

Suitable for	Replaces	Suitable for
Renault Truck	5000 821 966	Magnum / Major



57594

Eccentric Shaft Repair Kit

Type : 58 FRONT - 68 FRONT - 58 REAR - 68 REAR
Replaces : SP8570
Suitable for Replaces Suitable for
Volvo - FL4/6
Iveco - EuroCargo



57595

Eccentric Shaft Repair Kit

Type : 60 FRONT - 68 FRONT - 60 REAR - 68 REAR
Replaces : SJ1032
Suitable for Replaces Suitable for
Iveco - EuroCargo



54538

Caliper Pin Repair Kit

Type : 60 REAR
Replaces : SJ1034
Suitable for Replaces Suitable for
Iveco 93161037 93161473 EuroCargo / EuroFire



54540

Caliper Pin Repair Kit

Type : 58 FRONT - 68 FRONT - 58 REAR - 68 REAR
Replaces : SP8565
Suitable for Replaces Suitable for
Volvo 3090851 FL4/6
Iveco 8124737 EuroCargo
Renault Truck - Midliner



54543

Caliper Pin Repair Kit

Type : 60 FRONT
Replaces : SJ1035 - ST1153
Suitable for Replaces Suitable for
Mercedes 000 420 04 76 Sprinter / Vario
Iveco 93161029 93161472 EuroCargo



54544

Caliper Pin Repair Kit

Type : 60 FRONT
Replaces : SP8902
Suitable for Replaces Suitable for
Mercedes 000 421 14 63 Vario
Daf 1522173 -
Renault Truck - Midliner




54541

Caliper Pin Repair Kit

Type : 68 REAR
Replaces : SJ1022

Suitable for Replaces Suitable for
Iveco 93161475 EuroCargo



77382

Caliper Bearing Kit

Type : DX195 - DX225
Replaces : MCK1344



56006

Roller Bearing

Type : DX195 - DX225

Replaces : -



71855

Ball Bearing Set

Type : D3

Replaces : -



56004

Roller Bearing

Type : D3

Replaces : -




56116

Ball Bearing Set

Type : C LISA - D LISA
Replaces : -

Suitable for Replaces Suitable for
Volvo - B10
Renault Truck - Premium / Magnum / Midliner



56028

Caliper Bearing Kit

Type : C LISA - D LISA
Replaces : SJ4031

Suitable for Replaces Suitable for
Volvo 8550893 B10
Renault Truck - Premium / Magnum / Midliner

72852
ø49.7xø59x36

55819 Roller Bearing Kit

Type : B DUCO - C DUCO - Le DUCO - D DUCO AXIAL - ELSA 1 - ELSA2 AXIAL - ELSA195 - ELSA225 - EX225

Replaces : SJ4112

Suitable for	Replaces	Suitable for
Volvo	3092329	FH12/16 - FM7/9/10/12

72852
ø49.7xø59x36

57581 Roller Bearing Kit

Type : D DUCO RADIAL - ELSA2 RADIAL

Replaces : SJ4098

Suitable for	Replaces	Suitable for
Volvo	3092261	FH12/16 - FM7/9/10/12

81004 Caliper Bearing Cap

Type : ELSA2 SERIES - ELSA195 - ELSA225 - EX225

Replaces : -

Suitable for	Replaces	Suitable for
Man	-	Lion's City / Centroliner / NL / NG / NL / NUE / ND / NM
Volvo	-	B6/7/9/12 - FL6 / FS7
Renault Truck	-	Premium / Sisu / Midlum / Magnum

72852
ø49.7xø59x36

73159

57345 Caliper Lever Set

Type : B DUCO

Replaces : MCK1048

Suitable for	Replaces	Suitable for
Volvo	-	FL6

72852
ø49.7xø59x36

73159

57343 Caliper Lever Set, Left

Type : C DUCO - Le DUCO

Replaces : MCK1127

Suitable for	Replaces	Suitable for
Volvo	85109978 - 85102097	FM9

73158

72852
ø49.7xø59x36

57344 Caliper Lever Set, Right

Type : C DUCO - Le DUCO

Replaces : MCK1128

Suitable for	Replaces	Suitable for
Volvo	85109979 - 85102098	FM9



56071

Caliper Lever Set, Left

Type : D DUCO AXIAL
 Replaces : SJ4096 - MCK1398
 Suitable for Replaces Suitable for
 Volvo 21109753 FH12/16 - FM7/9/10/12
 85109975
 3092258



56072

Caliper Lever Set, Right

Type : D DUCO AXIAL
 Replaces : SJ4097 - MCK1399
 Suitable for Replaces Suitable for
 Volvo 21109754 FH12/16 - FM7/9/10/12
 85109976
 3092259



56053

Caliper Lever Set

Type : D DUCO RADIAL
 Replaces : SJ4108
 Suitable for Replaces Suitable for
 Volvo 21109755 FH12/16 - FM7/9/12
 85109977
 3092260



81005

Caliper Lever Set

Type : ELSA2 AXIAL
 Replaces : -
 Suitable for Replaces Suitable for
 Renault Truck - Premium / Sisu / Midlum / Magnum



81006

Caliper Lever Set

Type : ELSA2 RADIAL
 Replaces : -
 Suitable for Replaces Suitable for
 Man - Lion's City / Centroliner
 Volvo - NL / NG / NL / NUE / ND / NM
 B7/9/12



53871

Tappet Kit

Type : B DUCO - C DUCO - Le DUCO - D DUCO SERIES
 Replaces : MCK1238
 Suitable for Replaces Suitable for
 Volvo 3092264 FH12/16 - FM7/9/10/12
 Renault Truck 5021202828 -
 Daf 0868378 -



54174

Tappet Kit

Type : ELSA2 SERIES - ELSA195 - ELSA225 - EX225
 Replaces : MCK1309 - MCK1309
 Suitable for Replaces Suitable for
 Volvo 85109891 -
 Renault Truck 5001 866 398 Premium / Magnum / Midlum



55857

Dust Cover Kit


Type : ELSA 1
 Replaces : ST1156
 Suitable for Replaces Suitable for
 Man 81.50802.6016 TGA / TGS / TGX / Lion's Series



53870

Dust Cover Kit

Type : B DUCO - C DUCO - Le DUCO - D DUCO SERIES - ELSA2 SERIES - ELSA195 - ELSA225 - EX225
 Replaces : MCK1139
 Suitable for Replaces Suitable for
 Man 81.50802.6024 TGA / TGL / Lion's City
 Volvo 85107913 FH12/16 - FM7/9/10/12



54531

Dust Cover Kit

Type : D LISA
 Replaces : SJ4077
 Suitable for Replaces Suitable for
 Volvo - B10
 Renault Truck - Premium / Magnum



54555

Dust Cover Kit

Type : C LISA
 Replaces : SJ4053
 Suitable for Replaces Suitable for
 Renault Truck - Midliner



56016

Caliper Boot & Cap Set

Type : ELSA2 SERIES - ELSA195 - ELSA225
 Replaces : MCK1088
 Suitable for Replaces Suitable for
 Man - F2000



54547

Dust Cover & Gasket Kit

Type : D LISA

Replaces : SJ4078

Suitable for Volvo 3098113

Renault Truck -

Suitable for

B7/10/12
Premium / Magnum



56017

Dust Cover & Gasket Kit

Type : C LISA - D LISA

Replaces : SJ4032

Suitable for Renault Truck -

Replaces

Suitable for Premium



56045

Dust Cover & Gasket Kit

Type : C LISA

Replaces : SJ4061

Suitable for Renault Truck -

Replaces

Suitable for Midliner



54534

Caliper Repair Kit

Type : 68 REAR

Replaces : SP9670

Suitable for Volvo 3090940

Daf Iveco -

Replaces

Suitable for FL6

EuroCargo



54536

Caliper Repair Kit

Type : 58 REAR

Replaces : SP9669

Suitable for Volvo 3090939
3090356
271163

Suitable for FL6



54539

Caliper Repair Kit

Type : 60 REAR

Replaces : SJ1030

Suitable for Iveco 93161036

Replaces

Suitable for EuroCargo / EuroFire

55179 Caliper Repair Kit

Type : 68 REAR
 Replaces : SJ1033

Suitable for Iveco	Replaces 93161034 93161471	Suitable for EuroCargo
--------------------	-------------------------------	------------------------

54535 Caliper Repair Kit

Type : 58 FRONT
 Replaces : SP8567

Suitable for Volvo	Replaces 3090938 270531	Suitable for FL4/6
--------------------	----------------------------	--------------------

54545 Caliper Repair Kit

Type : 60 FRONT
 Replaces : SJ1037

Suitable for Iveco	Replaces 93161028	Suitable for EuroCargo / EuroFire
--------------------	-------------------	-----------------------------------

54533 Caliper Repair Kit

Type : 60 FRONT
 Replaces : SP8597

Suitable for Mercedes	Replaces -	Suitable for Vario
Renault Truck	5001 014 679 5001 829 892	Midliner

54537 Caliper Repair Kit

Type : 68 FRONT
 Replaces : SP8564

Suitable for Volvo	Replaces 3090937 270527	Suitable for FL6
Daf	1522160	-
Iveco	93161552	EuroCargo
Renault Truck	5001 829 895 5001 014 701	Midliner

54542

Caliper Repair Kit

Type : 58 FRONT - 60 FRONT - 68 FRONT - 58 REAR - 60 REAR - 68 REAR

Replaces : SP8566

Suitable for	Replaces	Suitable for
Mercedes	-	Vario
Volvo	-	FL4/6
Daf	1522175	-
Iveco	-	EuroCargo
Renault Truck	5001 829 894	Midliner



55813

Caliper Repair Kit

Type : 58 FRONT - 60 FRONT - 68 FRONT - 58 REAR - 60 REAR - 68 REAR
Replaces : ST1154

Suitable for	Replaces	Suitable for
Mercedes	000 421 83 86	Sprinter / Vario

55820

Intermediate Gear & Spring Set

Type : D DUCO SERIES
Replaces : MCK1067

Suitable for	Replaces	Suitable for
Volvo	3095626	FH12/16 - FM7/9/10/12 - B7/12



56005

Lock Plate

Type : ELSA 1
Replaces : 68321678PK10 - 68321678

Suitable for	Replaces	Suitable for
Man	81.50822.0006	TGA / TGS / TGX / Lion's Series



57161

Lock Plate

Type : D DUCO SERIES
Replaces : 68322900PK10



70698

Lock Plate

Type : C DUCO - Le DUCO
Replaces : 68322485PK10



55346
ø42x121/170x13

55329
M8x1,25/40

55330
M8x1,25/16

55176 Spline Shaft Cover Set

Type : D3
Replaces : -

Suitable for	Replaces	Suitable for
Renault Truck	5001 831 176	Premium / Magnum



55346
ø42x121/170x13

72677
ø54

55329
M8x1,25/40

55330
M8x1,25/16

56019 Spline Shaft Cover Set

Type : D3
Replaces : SJ1212

Suitable for	Replaces	Suitable for
Mercedes	-	O350 / O403 / O404
Man	81.50802.6007	F90 / F2000 / M2000 / E Series
Kassbohrer	8.285.388.441	-



55180 Dust Cover & Gasket Kit

Type : D2
Replaces : SJ1018

Suitable for	Replaces	Suitable for
Renault Truck	-	Magnum / Major



70697 Dust Cover

Type : D3
Replaces : 68320507PK10




72974

60566
ø28

55823 Dust Cover & Gasket Kit

Type : D DUCO AXIAL
Replaces : SJ4105

Suitable for	Replaces	Suitable for
Volvo	3092269	FH12/16 - FM7/9/10/12



72973

60566
ø28

55822 Dust Cover & Gasket Kit

Type : D DUCO RADIAL
Replaces : SJ4109

Suitable for	Replaces	Suitable for
Volvo	3092270	FH12/16 - FM7/9/10/12



55821

Dust Cover & Gasket Kit

Type : C DUCO - Le DUCO
Replaces : MCK1041

Suitable for Volvo	Replaces 3095669	Suitable for FH12- FM9/12
--------------------	------------------	---------------------------



56049

Caliper Visual Indicator

Type : B DUCO - C DUCO - Le DUCO - D DUCO SERIES
Replaces : SJ4111

Suitable for Volvo	Replaces 3092283	Suitable for B6/7/9/12 - FL6
--------------------	------------------	------------------------------



56011

Caliper Visual Indicator

Type : ELSA225
Replaces : MCK1311

Suitable for Volvo	Replaces 85109893	Suitable for FH12/16 - FM7/9/10/12
Renault Truck	7485 109 893	Premium / Midlum



56050

Caliper Visual Indicator

Type : ELSA2 SERIES
Replaces : MCK1240



56086

Brake Pad Retainer Kit

Type : C LISA
Replaces : SJ4051

Suitable for Renault Truck	Replaces 5001 845 022	Suitable for Midliner
----------------------------	-----------------------	-----------------------



56087

Brake Pad Retainer Kit

Type : D LISA
Replaces : SJ4022

Suitable for Volvo	Replaces -	Suitable for B10
Renault Truck	5001 836 607	Premium / Magnum

56042 Brake Pad Retainer Kit

Type : DX195
Replaces : MCK1154

72771
M8x1.25/60

56082 Brake Pad Retainer Kit

Type : B DUCO
Replaces : MCK1263

Suitable for Volvo Replaces Suitable for FL6

56083 Brake Pad Retainer Kit

Type : C DUCO - Le DUCO - D DUCO SERIES
Replaces : MCK1264

Suitable for Volvo Replaces Suitable for FH12/16 - FM7/9/10/12 - FL6

56081 Brake Pad Retainer Kit

Type : ELSA 1
Replaces : MCK1262

Suitable for Man Replaces Suitable for TGA / Lion's Series

56107 Brake Pad Retainer Kit

Type : ELSA2 SERIES - ELSA195 - ELSA225 - EX225
Replaces : MCK1174

Suitable for	Replaces	Suitable for
Man	81.50822.0014	TGA / F2000
Volvo	85107958	B7/9/12
Renault Truck	5001 866 486	Premium Sisu Midlum Magnum
Daf	0868303	-



81473

Caliper Cover, Left

Type : DX175
Replaces : -



81474

Caliper Cover, Right

Type : DX175
Replaces : -



81475

Caliper Cover, Left

Type : DX195
Replaces : -



81476

Caliper Cover, Right

Type : DX195
Replaces : -



81477

Caliper Cover, Left


Type : DX225
Replaces : -



81478

Caliper Cover, Right

Type : DX225
Replaces : -



81479

Caliper Push Plate

Type : D3
Replaces : -



81480

Caliper Push Plate


Type : D LISA
Replaces : -



81481

Caliper Push Plate


Type : C LISA
Replaces : -



81582

Carrier - 22.5" - Left/Right

Type : ELSA2 SERIES
Replaces : 68323673 - 68323675 - 68323676
Suitable for Replaces Suitable for
Man 35.50307.5526 -
Renault Truck - RENAULT 420




81583

Carrier - 22.5" - Left/Right

Type : ELSA225
Replaces : MCK1297


Suitable for Replaces Suitable for
Volvo 85109886 FM Series



81584

Carrier - 22.5" - Rear Left/Right

Type : D3
Replaces : 68320717-7



81585

Carrier - 22,5" - Left/Right

Type : D DUCO


Replaces : 68322778

Suitable for	Replaces	Suitable for
Volvo	3092253	FH12/16 - FM9/12
Daf	1489072	-

mauger
GERMANY

Suitable for

WABCO



77415

Adjusting Mechanism, Long, With Pin,
115 mm


Type : 19.5" Single Piston - 22.5" Single Piston
Replaces : -



75961

Caliper Calibration Bolt, Long, With Pin,
80.4 mm

Type : 19.5" Single Piston - 22.5" Single Piston
Replaces : -



79285

Adjusting Mechanism, Short, With Pin,
110 mm

Type : 17.5"
Replaces : -



77413

Caliper Calibration Bolt, Short, With Pin,
76 mm

Type : 17.5"
Replaces : -



79284

Adjusting Mechanism, Short,
With Groove, 110 mm


Type : 17.5"
Replaces : -



75960

Caliper Calibration Bolt, Short,
With Groove, 76 mm

Type : 17.5"
Replaces : -



81462

Caliper Calibration Bolt

Type : MAXX 22

Replaces : -

Suitable for Replaces : Suitable for
Man : TGS-TGX-TGA-LION'S



81660

Caliper Calibration Bolt, Left

Type : 19.5" Double Piston - 22.5" Double Piston
Replaces : -



81661

Caliper Calibration Bolt, Right

Type : 19.5" Double Piston - 22.5" Double Piston
Replaces : -



81653

Caliper Calibration Bolt Repair Kit, Left


Type : 19.5" Double Piston - 22.5" Double Piston
Replaces : -



81654

Caliper Calibration Bolt Repair Kit, Right

Type : 19.5" Double Piston - 22.5" Double Piston
Replaces : -



81652

Caliper Bridge


Type : 19.5" Double Piston - 22.5" Double Piston
Replaces : -



81651

Caliper Bridge Assembly

Type : 19.5" Double Piston - 22.5" Double Piston
Replaces : -



77414

Caliper Bridge

Type : 19.5" Single Piston - 22.5" Single Piston
Replaces : -



79286

Caliper Bridge


Type : 17.5"
Replaces : -



77311

Calliper Lever

Type : 17.5" - 19.5" Single Piston - 22.5" Single Piston
Replaces : -



81663

Calliper Lever, Complete

Type : 19.5" Double Piston - 22.5" Double Piston
Replaces : -



81662

Caliper Mechanism Housing

Type : 19.5" Double Piston - 22.5" Double Piston
Replaces : -



81377

Roller Bearing Kit

Type : MAXX 22
Replaces : -

Suitable for Man Replaces -

Suitable for TGS-TGX-TGA-LION'S



81655

Caliper Outer Roller Bearing


Type : 19.5" Double Piston - 22.5" Double Piston
Replaces : -



81656

Caliper Inner Roller Bearing

Type : 19.5" Double Piston - 22.5" Double Piston
Replaces : -



57600

Roller Bearing

Type : 17.5" - 19.5" Single Piston - 22.5" Single Piston
Replaces : -

72720 $\varnothing 25 \times 81$

72720 $\varnothing 24,5 \times 81$

55332

55353 $\varnothing 47 \times \varnothing 82 \times 17$

55313 M12x1,5/90

73005 $\varnothing 25 \times \varnothing 28 \times 15$

72877 $\varnothing 28 \times 16$

73187 $\varnothing 25$

54528

Caliper Pin & Durt Rubber Repair Kit

Type : 1000VG

Replaces : 12 999 729VT

Suitable for	Replaces	Suitable for
Man	81.50800.6023	L2000
Daf	1517354	-
Neoplan	0821.392.00 1101 5566	-

72729 $\varnothing 38 \times 118$

72728 $\varnothing 37,7 \times 76$

55337

55323 M16x1,5/120

55307 M16x1,5/80

72886 $\varnothing 42 \times 29$

73010 $\varnothing 38 \times \varnothing 42 \times 30$

55354 $\varnothing 31 \times \varnothing 72,5 \times 11$

72884 $\varnothing 42 \times 17$

73188 $\varnothing 26$

70838

Caliper Pin Repair Kit

Type : 19.5" Single Piston - 22.5" Single Piston

Replaces : 12 999 776

Suitable for	Replaces	Suitable for
Daf	1628065	LF45 / LF55
Renault Truck	5001 866 626	Midlum
Saf	3 434 3828 00	-

72729 $\varnothing 38 \times 118$

72728 $\varnothing 37,7 \times 76$

55337

55334

55323 M16x1,5/120

55307 M16x1,5/80

72886 $\varnothing 42 \times 29$

72884 $\varnothing 42 \times 17$

73010 $\varnothing 38 \times \varnothing 42 \times 30$

55354 $\varnothing 31 \times \varnothing 72,5 \times 11$

73188 $\varnothing 26$

54559

Caliper Pin Repair Kit

Type : 19.5" Single Piston

Replaces : 12 999 738VT

Suitable for	Replaces	Suitable for
Daf	1505890	-
Saf	3 434 3827 01	9019/11019 W Brake SBW 1937 - PAN 19-1 9022/11222 W Brake SBW 2243 - PAN 22-1



81375 Caliper Pin Repair Kit

Type : MAXX 22
Replaces : 640 322 926 2


Suitable for Man	Replaces	Suitable for
	81.50822.6038	TGS-TGX-TGA-LION'S



54561 Caliper Pin Repair Kit

Type : 17.5"
Replaces : 12 999 704VT

Suitable for Daf	Replaces	Suitable for Renault Truck
	1519363	5001 852 880
	-	Midlum



54565 Caliper Pin Repair Kit

Type : 17.5"
Replaces : 12 999 580VT


Suitable for Man	Replaces	Suitable for Daf
	81.50822.6003	1517407
		L2000 / M2000
		-



54566 Caliper Pin Repair Kit

Type : 17.5"
Replaces : 12 999 699VT - 12 999 702


Suitable for Daf	Replaces	Suitable for Iveco
	1436853	42536957
		LF45 / LF55
		EuroCargo / EuroPolis



54569 Caliper Pin Repair Kit

Type : 22.5" Double Piston
Replaces : 12 999 678VT

Suitable for Daf	Replaces	Suitable for Renault Truck
	0865966	5021 170 488
		-
		-



54562 Caliper Pin Repair Kit

Type : 19.5" Double Piston
Replaces : 12 999 746VT

Suitable for Daf	Replaces	Suitable for Renault Truck
	1440505	5001 858 722
		Midlum
		-



54558

Caliper Pin Repair Kit

Type : 22.5" Double Piston
Replaces : 12 999 677VT
Suitable for Replaces Suitable for
Daf 0865965 -
Renault Truck 5021 170 487 -



56119

Caliper Pin Repair Kit

Type : 17.5"
Replaces : -



56121

Caliper Pin Repair Kit

Type : 19.5" Single Piston
Replaces : -



81650

Tappet Kit

Type : 19.5" Double Piston - 22.5" Double Piston
Replaces : -
Suitable for Replaces Suitable for
Daf - LF55
Renault Truck - Midlum



54568

Caliper Pin Repair Kit

Type : AIR DISC BRAKE 1600 V-G
Replaces : 12 999 551VT
Suitable for Replaces Suitable for
Mercedes 000 420 09 82 O 405
Daf AMPA137 -
Neoplan 1101 5717 -



54560

Dust Cover Kit

Type : AIR DISC BRAKE 1600 V-G
Replaces : 12 999 552VT
Suitable for Replaces Suitable for
Mercedes 000 421 08 80 O 405
Daf AMPA141 -



56024 Caliper Pin Repair Kit

Type : AIR DISC BRAKE 1300 V-G
Replaces : 12 999 734VT

Suitable for Mercedes	Replaces	Suitable for
405 420 00 76		Unimog



56025 Dust Cover Kit

Type : AIR DISC BRAKE 1300 V-G
Replaces : 12 999 733VT

Suitable for Mercedes	Replaces	Suitable for
405 420 00 83		Unimog



56026 Dust Cover Kit

Type : 17.5" - 19.5" Single Piston - 22.5" Single Piston
Replaces : 640 175 920 2

Suitable for	Replaces	Suitable for
Saf	3 434 3829 00	SK RB 9019 W SK RB 9022 W BI9-19W BI9-22W




56118 Dust Cover & Bush Kit

Type : 17.5"
Replaces : -



56120 Dust Cover & Bush Kit

Type : 19.5" Single Piston
Replaces : -



54567

Dust Cover Kit

Type : CALIPER DISC BRAKE 244 V-Ö

Replaces : 12 999 543VT

Suitable for	Replaces	Suitable for
Mercedes	000 420 04 82	Sprinter / Vario
Daf	1517794	-



55814

Dust Cover Kit

Type : CALIPER DISC BRAKE 244 V-Ö

Replaces : -

Suitable for	Replaces	Suitable for
Mercedes	001 420 23 83	Sprinter / Vito



54563

Dust Cover Kit

Type : CALIPER DISC BRAKE 485 F-Ö

Replaces : 12 999 076VT

Suitable for	Replaces	Suitable for
Daf	1518458	-
Iveco	8124438	TurboCity



54527

Dust Cover Kit

Type : CALIPER DISC BRAKE 450 F-Ö

Replaces : 12 999 199VT

Suitable for	Replaces	Suitable for
Iveco	93161181	Daily II




54570

Dust Cover Kit

Type : CALIPER DISC BRAKE 456 F-Ö

Replaces : 12 999 141VT

Suitable for	Replaces	Suitable for
Daf	FBU1298	F600-800-1000 ROADRUNNER



56027

Dust Cover Kit

Type : CALIPER DISC BRAKE 456 F-Ö

Replaces : 12 999 116VT

Suitable for	Replaces	Suitable for
Daf	FBU1076	F45 F600-800-1000 ROADRUNNER



54564

Dust Cover Kit

Type : CALIPER DISC BRAKE 444 F-Ö
 Replaces : 12 999 197VT
 Suitable for Mercedes 000 420 68 83 L Series
 Daf 1505880 -
 Iveco 8124729 Daily I/II



81657

Caliper Mechanism Repair Kit


Type : 19.5" Double Piston - 22.5" Double Piston
 Replaces : -



81659

Adjuster Mechanism Gear Set


Type : 19.5" Double Piston - 22.5" Double Piston
 Replaces : -



79236

Caliper Gasket Kit


Type : 17.5"
 Replaces : -



79232

Caliper Gasket Kit

Type : 17.5"
 Replaces : -



81658

Caliper Gasket Kit

Type : 19.5" Double Piston - 22.5" Double Piston
 Replaces : -



81376

Caliper Cover Kit

Type : MAXX 22
Replaces : 640 322 650 4


Suitable for Man Replaces Suitable for TGS-TGX-TGA-LION'S



81482

Caliper Push Plate

Type : AIR DISC BRAKE 1600 V-G
Replaces : -




81586

Carrier - 17,5" - Left

Type : 17.5"
Replaces : 40 175 049

Suitable for Man	Replaces	Suitable for
	81.50804.6087	L2000 / M2000
	81.50804.6071	
	81.50804.6089	
	81.50804.6355	
	81.50804.9071	
	81.50804.9087	
Daf	1505372	-



81587


Carrier - 17,5" - Right

Type : 17.5"
Replaces : 40 175 050

Suitable for Man	Replaces	Suitable for
	81.50804.6070	L2000 / M2000
	81.50804.6354	
	81.50804.9070	
	81.50804.9088	
Daf	1505373	-

81588

Carrier - 19.5" - Left




Type : 19.5" Single Piston

Replaces : 40 195 017

Suitable for	Replaces	Suitable for
Saf	3 080 0019 01	SK RB 9019 W
	3 080 0033 00	SK RS 9019 W
	3 080 0033 20	SK RZ 9019 W
Daf	0866216	-

81589


Carrier - 19.5" - Right



Type : 19.5" Single Piston

Replaces : 40 195 018

Suitable for	Replaces	Suitable for
Saf	3 080 0018 01	SK RB 9019 W
Saf	3 080 0032 00	SK RS 9019 W
Saf	3 080 0032 20	SK RZ 9019 W
Daf	0866217	-




81590

Carrier - 22.5" - Left

Type : 22.5" Single Piston

Replaces : -



81591

Carrier - 22.5" - Right

Type : 22.5" Single Piston

Replaces : -

81592 Carrier - 22,5" - Left

Type : 22.5" Single Piston
Replaces : -

81593 Carrier - 22,5" - Right

Type : 22.5" Single Piston
Replaces : -

81594 Carrier - 22,5" - Left

Type : MAXX 22T TYPE (SCHMITZ SCB430W1)
Replaces : 640 222 740 6 D3-6K25

Suitable for Schmitz Replaces Suitable for
- SCB430W1

81595 Carrier - 22,5" - Right

Type : MAXX 22T TYPE (SCHMITZ SCB430W1)
Replaces : 640 222 740 6 D1-6J20


Suitable for Schmitz Replaces Suitable for
- SCB430W1

mauger
GERMANY

Suitable for
HALDEX



79759



79758



79754



79764



79784

81501 Caliper Repair Kit

Type : MODUL T

Replaces : -

Suitable for Saf

Replaces -

Suitable for BI9-22S (SBS 2220 Series)



79759 Adjusting Mechanism

Type : MODUL T

Replaces : -


Suitable for Replaces Saf - Suitable for BI9-22S (SBS 2220 Series)



81669 Caliper Adjusting Mechanism Set

Type : MARK III

Replaces : -



81668 Caliper Adjusting Mechanism Set

Type : MARK IV

Replaces : -



81670 Caliper Adjusting Mechanism Set

Type : MODUL X - GEN 2

Replaces : -



81671 Caliper Adjusting Mechanism Set

Type : MODUL X - GEN 1

Replaces : -



81681 Caliper Calibration Bolt

Type : MARK II - MARK III

Replaces : -



81694 Caliper Calibration Bolt

Type : MODUL X - GEN 2

Replaces : -



79763 Caliper Calibration Bolt

Type : MODUL T

Replaces : -

Suitable for Replaces Suitable for
Saf - BI9-22S (SBS 2220 Series)



81683 Caliper Calibration Gear, Left

Type : MARK II - MARK III


Replaces : -



81682 Caliper Calibration Gear, Right

Type : MARK II - MARK III

Replaces : -



81684 Adjusting Mechanism

Type : MARK II - MARK III

Replaces : -



79756 Adjusting Mechanism Repair Kit


Type : MODUL T

Replaces : -

Suitable for Replaces Suitable for
Saf - BI9-22S (SBS 2220 Series)



81700 Adjusting Mechanism (Driven)
Type : MARK IV
Replaces : -



81697 Adjusting Mechanism (Driven)
Type : MODUL X - GEN 1
Replaces : -



81701 Adjusting Mechanism (Driving)
Type : MARK IV - MODUL X - GEN 1
Replaces : -



81696 Adjusting Mechanism
Type : MODUL X - GEN 2
Replaces : -



81698 Adjusting Mechanism
Type : MODUL X - GEN 2
Replaces : -



81699 Adjusting Mechanism
Type : MARK IV - MODUL X - GEN 1
Replaces : -



81695 Caliper Adjustment Sleeve
Type : MODUL X - GEN 2
Replaces : -



81702 Adjusting Mechanism Gear
Type : MARK IV - MODUL X - GEN 1 - MODUL X - GEN 2
Replaces : -



79764 Caliper Mechanism Gear
Type : MODUL T
Replaces : -
Suitable for Replaces : Suitable for
Saf - B19-22S (SBS 2220 Series)



79760

Caliper Bridge

Type : MODUL T
Replaces : -

Suitable for Saf Replaces Suitable for B19-22S (SBS 2220 Series)



81689

Caliper Bridge Assembly Kit

Type : MODUL X - GEN 2
Replaces : -



81690

Caliper Bridge Assembly Kit

Type : MARK IV - MODUL X - GEN 1
Replaces : -



81680

Caliper Bridge Assembly Kit

Type : MARK II - MARK III
Replaces : -



81676

Caliper Cover Kit

Type : MARK III
Replaces : -



81688

Caliper Cover Kit

Type : MARK IV
Replaces : -



81677

Caliper Cover Kit

Type : MODUL X - GEN 1 - MODUL X - GEN 2
Replaces : -



81687

Caliper Cover Kit

Type : MARK IV
Replaces : -



81520

Caliper Cover Kit

Type : MARK II - MARK III
Replaces : -



81703

Lock Plate

Type : MODUL X - GEN 2
Replaces : -



81707

Caliper Mechanism Clamp


Type : MODUL X - GEN 2
Replaces : -



81708

Caliper Mechanism Clamp


Type : MODUL X - GEN 1
Replaces : -



81686

Caliper Mechanism Ring


Type : MARK III
Replaces : -



81685

Caliper Mechanism Ring

Type : MARK IV
Replaces : -



81674

Calliper Lever

Type : MARK IV
Replaces : -



81673

Calliper Lever

Type : MODUL X - GEN 1
Replaces : -



81672

Calliper Lever

Type : MODUL X - GEN 2
Replaces : -



81675

Calliper Lever

Type : MARK II - MARK II
Replaces : -



79761

Calliper Lever

Type : MODUL T
Replaces : -

Suitable for	Replaces	Suitable for
Saf	-	BI9-22S (SBS 2220 Series)



79762


Calliper Lever Housing

Type : MODUL T
Replaces : -

Suitable for	Replaces	Suitable for
Saf	-	BI9-22S (SBS 2220 Series)



81691 Roller Bearing Kit
Type : MODUL X - GEN 2
Replaces : -



81693 Roller Bearing
Type : MARK IV - MODUL X - GEN 1
Replaces : -



81692 Roller Bearing Kit
Type : MODUL X - GEN 2
Replaces : -



81678 Roller Bearing Kit
Type : MARK II - MARK III
Replaces : -



81679 Roller Bearing Kit
Type : MARK II - MARK III
Replaces : -




79751 Roller Bearing Kit
Type : MODUL T
Replaces : -
Suitable for Replaces Saf - Suitable for BI9-22S (SBS 2220 Series)



79753 Roller Bearing Kit
Type : MODUL T
Replaces : -
Suitable for Replaces Saf - Suitable for BI9-22S (SBS 2220 Series)



79752 Roller Bearing Kit
Type : MODUL T
Replaces : -
Suitable for Replaces Saf - Suitable for BI9-22S (SBS 2220 Series)



57599 Roller Bearing
Type : MARK IV - MODUL X - GEN 1
Replaces : -



81704 Calliper Lever Pin

Type : MARK IV

Replaces : -



81705 Calliper Lever Pin

Type : MODUL X - GEN 1

Replaces : -



81706 Calliper Lever Pin

Type : MODUL X - GEN 2


Replaces : -



79754 Calliper Reset Shaft Kit

Type : MODUL T
Replaces : 95398 - 95055

Suitable for	Replaces	Suitable for
Saf	3 434 3862 00	BI9-22S (SBS 2220 Series)
Krone	550017812	-



79755 Calliper Repair Kit

Type : MODUL T
Replaces : -

Suitable for	Replaces	Suitable for
Saf	-	BI9-22S (SBS 2220 Series)



56092 Calliper Plug Set

Type : MARK IV - MODUL X - GEN 1 - MODUL X - GEN 2
Replaces : 90693 - 89926

Suitable for	Replaces	Suitable for
Renault Truck	5021 174 163	-
Saf	3 434 385 502	SKRS 9022H Brake SBH 2243 SKRB 9022H Brake SBH 2243-11S SKRLB 9022H Brake SBH 2243-11S SKRZ 11222H Brake SBH 2243 SKRS 11222H Brake SBH 2243



56093

Caliper Plug Set

Type : MARK III - MODUL X - GEN 1 - MODUL X - GEN 2
Replaces : 89925



56099

Brake Tappet Plate

Type : MARK IV - MODUL X - GEN 1
Replaces : 91236



56098

Spring & Brake Tappet Plate

Type : MARK IV - MODUL X - GEN 1
Replaces : 92731



56094

Spring & Boot Set

Type : MARK IV - MODUL X - GEN 1 - MODUL X - GEN 2
Replaces : 89794



70839

Caliper Tappet Plate & Boot Set

Type : MARK IV - MODUL X - GEN 1
Replaces : 94664 - 93285



79785

Dust Cover Kit

Type : MODUL T
Replaces : -

Suitable for Saf - Replaces - Suitable for BI9-22S (SBS 2220 Series)



79780

Dust Cover Kit


Type : MODUL T
 Replaces : 95056 - 95399
 Suitable for Replaces Suitable for
 Saf 3 434 3863 00 BI9-22S (SBS 2220 Series)
 Krone 550017813 -



79758

Caliper Pin Repair Kit

Type : MODUL T
 Replaces : 95397 - 95054
 Suitable for Replaces Suitable for
 Saf 3 434 3861 00 BI9-22S (SBS 2220 Series)
 Krone 550017811 -



56091

Caliper Boot & Plug Set

Type : MARK IV - MODUL X - GEN 1 - MODUL X - GEN 2
 Replaces : 94662

Suitable for Replaces Suitable for
 Saf 3 434 3852 02 SK RB 9022 H (MK IV)
 SK RB 9022 H (MODUL X)
 9022/11222H(MODUL X) Brake SBH
 2243-11 S (MODUL X)



56090


Caliper Boot & Plug Set

Type : MARK II - MARK III
 Replaces : 94663 - 87405

Suitable for Replaces Suitable for
 Saf 3 434 3852 00 SK RB 9022 H (MK II/III)
 3 434 3855 00 9022/11222 H (MK II) Brake SBH
 2243-11 S (MK II)
 9022/11222 H (MK III Brake SBH)
 2243-11 S (MK III)

56095

Caliper Pin Bolt Repair Kit




Type : MARK II - MARK III - MARK IV
Replaces : 94661

Suitable for Saf	Replaces 3 434 3858 00 3 434 3854 01	Suitable for SK RB 9022 H (MK II/III) SK RB 9022 H (MK IV) 9022/11222 H (MK II) Brake SBH 2243-11 S (MK II) 9022/11222 H (MK III) Brake SBH 2243-11 S (MK III) 9022/11222 H (MK IV) Brake SBH 2243-11 S (MK IV)
------------------	--	--

56096

Caliper Pin Bolt Repair Kit



Type : MODUL X - GEN 1 - MODUL X - GEN 2
Replaces : 94660


Suitable for Saf	Replaces 3 434 3854 02	Suitable for SK RB 9022 H (MODUL X) 9022/11222H(MODUL X) Brake SBH 2243-11 S (MODUL X)
------------------	---------------------------	---



56097

Caliper Pin Repair Kit

Type : MARK II - MARK III - MARK IV
Replaces : 89541



56100

Caliper Pin Repair Kit

Type : MARK II - MARK III - MARK IV
Replaces : 87406

56101 Caliper Pin Repair Kit

Type : MODUL X - GEN 1
Replaces : 91012

71446 Caliper Pin Repair Kit

Type : MODUL X - GEN 2
Replaces : 93299

56150 Brake Pad Retainer Kit

Type : MARK II - MARK III - MARK IV - MODUL X - GEN 1 - MODUL X - GEN 2
Replaces : 94659

79757 Brake Pad Retainer Kit

Type : MODUL T
Replaces : -

Suitable for Saf : -
Replaces : -
Suitable for B19-22S (SBS 2220 Series)

81596 Carrier - 22.5" - Left/Right

Type : MODUL X - GEN 1 - MODUL X - GEN 2
Replaces : 92502 - 90636

Suitable for Saf : -
Replaces : -
Suitable for : -

81597 Carrier - 19.5" - Left/Right

Type : MODUL T
Replaces : 94861

Suitable for Saf : -
Replaces : -
Suitable for B19-22S (SBS 2220 Series)

mauger

GERMANY

Suitable for

BPW



79332

Calliper Cover Kit, Complete

Suitable for
Bpw

Replaces
-

Suitable for
BPW ECO Disc TSB 3709
BPW ECO Disc TSB 4309
BPW ECO Disc TSB 4312



79333

Calliper Cover Kit

Suitable for
Bpw

Replaces
-

Suitable for
BPW ECO Disc TSB 3709
BPW ECO Disc TSB 4309
BPW ECO Disc TSB 4312



79335

Calliper Mechanism Bearing House

Suitable for
Bpw

Replaces
-

Suitable for
BPW ECO Disc TSB 3709
BPW ECO Disc TSB 4309
BPW ECO Disc TSB 4312




79336

Calliper Calibration Bolt

Suitable for
Bpw

Replaces
-

Suitable for
BPW ECO Disc TSB 3709
BPW ECO Disc TSB 4309
BPW ECO Disc TSB 4312



79337

Calliper Mechanism Housing

Suitable for
Bpw

Replaces
-

Suitable for
BPW ECO Disc TSB 3709
BPW ECO Disc TSB 4309
BPW ECO Disc TSB 4312



79338

Calliper lever

Suitable for
Bpw

Replaces
-

Suitable for
BPW ECO Disc TSB 3709
BPW ECO Disc TSB 4309
BPW ECO Disc TSB 4312




80160

Caliper Cap

Suitable for
Bpw

Replaces
-

Suitable for
BPW ECO Disc TSB 3709
BPW ECO Disc TSB 4309
BPW ECO Disc TSB 4312




79340

Roller Bearing Kit

Suitable for
Bpw

Replaces
-

Suitable for
BPW ECO Disc TSB 3709
BPW ECO Disc TSB 4309
BPW ECO Disc TSB 4312




79341

Roller Bearing Kit

Suitable for
Bpw

Replaces
-

Suitable for
BPW ECO Disc TSB 3709
BPW ECO Disc TSB 4309
BPW ECO Disc TSB 4312



79342

Roller Bearing Kit

Suitable for
Bpw

Replaces
-

Suitable for
BPW ECO Disc TSB 3709
BPW ECO Disc TSB 4309
BPW ECO Disc TSB 4312



70656

Calliper Pin Boot & Cap Set

Suitable for
Bpw

Replaces
09.801.07.62.0

Suitable for
BPW ECO Disc TSB 3709
BPW ECO Disc TSB 4309
BPW ECO Disc TSB 4312



77368

Brake Pad Retainer Kit

Suitable for
Bpw

Replaces
09.801.07.68.1
09.801.07.68.0

Suitable for
BPW ECO Disc TSB 3709
BPW ECO Disc TSB 4309
BPW ECO Disc TSB 4312

mauger
GERMANY

Suitable for

BREMBO



81778 Caliper Pin Repair Kit

Suitable for Mercedes Replaces 000 421 08 50 Suitable for Sprinter / Viano



81779 Caliper Pin Repair Kit

Suitable for Mercedes Replaces 000 421 08 50 S Suitable for Sprinter / Viano



81777 Caliper Pin Repair Kit

Suitable for Mercedes Replaces 000 423 06 63 Suitable for Sprinter



81776 Caliper Pin Repair Kit

Suitable for Mercedes Replaces 000 423 05 63 Suitable for Sprinter

Suitable for

OTHER TYPE



55810

Caliper Repair Kit

Suitable for Mercedes

Replaces 001 420 25 83

Suitable for Sprinter



55815

Caliper Repair Kit

Suitable for Mercedes

Replaces 001 420 24 83

Suitable for Sprinter



72137

Caliper Repair Kit

Suitable for Iveco

Replaces 42555883

Suitable for Daily IV/V



55809

Caliper Repair Kit

Suitable for Mercedes

Replaces 002 586 53 42

Suitable for L Series



56089

Caliper Repair Kit

Suitable for Mercedes

Replaces 000 420 14 44

Suitable for L Series

Suitable for
SENSOR



70704

Pad Wear Indicator,
Front Left and Right

Type : -

Replaces : 81.25937.6039 - 81.25937.6015

Suitable for	Replaces	Suitable for
Man		TGA
Man		TGA
Ror-Meritor		Elsa2 Series / Elsa195 - Elsa225



70705

Pad Wear Indicator, Rear Left

Type : -

Replaces : 81.25937.6041 - 81.25937.6017 - 81.25937.6010

Suitable for	Replaces	Suitable for
Man		TGA
Man		TGA
Man		TGA
Ror-Meritor		Elsa2 Series / Elsa195 - Elsa225



70706

Pad Wear Indicator, Rear Right

Type : -

Replaces : 81.25937.6044 - 81.25937.6022 - 81.25937.6018

Suitable for	Replaces	Suitable for
Man		TGA
Man		TGA
Man		TGA
Ror-Meritor		Elsa2 Series / Elsa195 - Elsa225



76946

Pad Wear Indicator

Type : -

Replaces : 81.25937.6038 - 81.25937.6013

Suitable for	Replaces	Suitable for
Man		Lion's City / Centraliner
Man		Lion's City / Centraliner

76947

Pad Wear Indicator



Type : -

Replaces : 81.25937.6046 - 81.25937.6028

Suitable for	Replaces	Suitable for
Man		Lion's City / Centroliner
Man		Lion's City / Centroliner

76948

Pad Wear Indicator



Type : -

Replaces : 81.25937.6040 - 81.25937.6019 - 81.25937.6009

Suitable for	Replaces	Suitable for
Man		TGA / Lion's City / Centroliner
Man		TGA / Lion's City / Centroliner
Man		TGA / Lion's City / Centroliner

70707

Pad Wear Indicator, Front




Type : -

Replaces : 20928533 - 20442608 - 20392985 - 3986607

Suitable for	Replaces	Suitable for
Volvo		FH12/16 - FM7/9/10/12
Volvo		FH12/16 - FM7/9/10/12
Volvo		FH12/16 - FM7/9/10/12
Volvo		FH12/16 - FM7/9/10/12
Ror-Meritor		Elsa2 Series / Elsa195 - Elsa225

70708

Pad Wear Indicator, Rear



Type : -

Replaces : 20928532 - 20442607

Suitable for	Replaces	Suitable for
Volvo		FH12/16 - FM9/12
Volvo		FH12/16 - FM9/12
Ror-Meritor		Elsa2 Series / Elsa195 - Elsa225



74450

Pad Wear Indicator

Type : -

Replaces : 20928541 - 20526767

Suitable for	Replaces	Suitable for
Volvo		FH12/16 - FM9/12
Volvo		FH12/16 - FM9/12
Ror-Meritor		-




74455

Pad Wear Indicator, Left

Type : -

Replaces : 21390373 - 20928537

Suitable for	Replaces	Suitable for
Volvo		FH12/16 - FM7/9/10/12
Volvo		FH12/16 - FM7/9/10/12
Ror-Meritor		-



74454

Pad Wear Indicator, Right

Type : -

Replaces : 21390372 - 20928536

Suitable for	Replaces	Suitable for
Volvo		FH12/16 - FM7/9/10/12
Volvo		FH12/16 - FM7/9/10/12
Ror-Meritor		-



74453

Pad Wear Indicator, Left

Type : -

Replaces : 21390376 - 20928545 - 20534389

Suitable for	Replaces	Suitable for
Volvo		FH12/16 - FM7/9/10/12
Volvo		FH12/16 - FM7/9/10/12
Volvo		FH12/16 - FM7/9/10/12
Ror-Meritor		-

74451

Pad Wear Indicator, Right



Type : -

Replaces : 21390374 - 20928539

Suitable for	Replaces	Suitable for
Volvo		FH12/16 - FM7/9/10/12
Volvo		FH12/16 - FM7/9/10/12
Ror-Meritor		-

74452

Pad Wear Indicator, Right



Type : -

Replaces : 21390375 - 20928544

Suitable for	Replaces	Suitable for
Volvo		FH12/16 - FM7/9/10/12
Volvo		FH12/16 - FM7/9/10/12
Ror-Meritor		-

74457

Pad Wear Indicator, Left



Type : -

Replaces : 20928548 - 20554517

Suitable for	Replaces	Suitable for
Volvo		FH12/16 - FM7/9/10/12
Volvo		FH12/16 - FM7/9/10/12
Ror-Meritor		-

74456

Pad Wear Indicator, Right



Type : -

Replaces : 20928547 - 20554506

Suitable for	Replaces	Suitable for
Volvo		FH12/16 - FM7/9/10/12
Volvo		FH12/16 - FM7/9/10/12
Ror-Meritor		-



74459

Pad Wear Indicator, Left

Type : -

Replaces : 20928564

Suitable for Volvo

Replaces

Suitable for FH12/16 - FM7/9/10/12



74458

Pad Wear Indicator, Right

Type : -

Replaces : 20928563

Suitable for Volvo

Replaces

Suitable for FH12/16 - FM7/9/10/12



70711

Pad Wear Indicator, Front Left

Type : -

Replaces : 5001 856 031

Suitable for Renault Truck Ror-Meritor

Replaces

Suitable for Premium Elsa2 Series / Elsa195 - Elsa225



70709

Pad Wear Indicator, Front Right

Type : -

Replaces : 5001 856 032

Suitable for Renault Truck Ror-Meritor

Replaces

Suitable for Premium Elsa2 Series / Elsa195 - Elsa225



70712

Pad Wear Indicator, Rear Left

Type : -

Replaces : 5001 856 033

Suitable for
Renault Truck
Ror-Meritor

Replaces

Suitable for
Premium / Magnum
Elsa2 Series / Elsa195 - Elsa225



70710

Pad Wear Indicator, Rear Right

Type : -

Replaces : 5001 856 034

Suitable for
Renault Truck
Ror-Meritor

Replaces

Suitable for
Premium / Magnum
Elsa2 Series / Elsa195 - Elsa225



70715

Pad Wear Indicator, Front Left

Type : -

Replaces : 7420 928 559

Suitable for
Renault Truck
Ror-Meritor

Replaces

Suitable for
Premium DXI / Premium
Elsa2 Series / Elsa195 - Elsa225



70713

Pad Wear Indicator, Front Right

Type : -

Replaces : 7420 928 560

Suitable for
Renault Truck
Ror-Meritor

Replaces

Suitable for
Premium DXI / Premium
Elsa2 Series / Elsa195 - Elsa225



70716

Pad Wear Indicator, Rear Left

Type : -

Replaces : 7420 928 552

Suitable for
Renault Truck
Ror-Meritor

Replaces

Suitable for
Premium DXI / Premium / Magnum
Elsa2 Series / Elsa195 - Elsa225



70714

Pad Wear Indicator, Rear Right

Type : -

Replaces : 7420 928 553

Suitable for
Renault Truck
Ror-Meritor

Replaces

Suitable for
Premium DXI / Premium / Magnum
Elsa2 Series / Elsa195 - Elsa225